



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005339
INV Date 30/07/2020
Reference CC6/CTI19020843/Gda3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SKU 7627E
Insured Veh. GBD 4659D
Claim No. SNM19D205589
Policy No. DMCVSN3079471902
Accident Date 21/11/2019
Inspection Date 22/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19020843/Gda3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 30-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 4659D	Veh. Inspected	SKU 7627E
Policy No.	DMCVSN3079471902	Coverage (\$)	0.00
Claim No.	SNM19D205589	Excess (\$)	0.00
Assign From		Assign Date	22/11/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0316474	Colour	SILVER
Odometer	70225	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/11/2019	Inspection Date	22/11/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 7627E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	BENT	1,352.20	1,004.00
1	REAR BOOT LOCK	BENT	465.20	185.00
1	REAR BOOT LOCK CATCH	NOT NECESSARY	70.20	-
2	REAR BOOT HINGES @\$168.00	NOT NECESSARY	336.00	-
1	REAR BOOT INSULATOR	NOT NECESSARY	365.50	-
1	REAR BOOT RUBBER	TWISTED	315.20	107.70
2	REAR BOOT REFLECTOR LAMP @\$543.00	BROKEN	1,086.00	932.00
1	REAR BOOT EMBLEM (MAZDA 3)	NECESSARY	65.00	54.00
1	REAR BOOT EMBLEM LOGO	NECESSARY	72.00	72.00
1	REAR BOOT EMBLEM (SKYACTIVE)	NECESSARY	65.00	65.00
2	TAILLAMP PANEL @\$388.00	TO REPAIR SEE LABOUR	776.00	-
2	REAR TAILLAMP @\$985.00	CRACKED	1,970.00	1,830.00
1	REAR END PANEL	BUCKLED	825.00	425.00
1	REAR END PANEL TOP GARNISH	DEFORMED	315.50	99.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,325.00	-
1	REAR SPARE TYRE PANEL TOP COVER BOARD	CRACKED	465.20	249.00
2	REAR BUMPER SIDE RETAINER @\$35.00	DEFORMED	70.00	70.00
1	REAR BUMPER REINFORCEMENT	BENT	652.20	537.30
2	REAR BUMPER REFLECTOR @\$50.00	N/S CUT / O/S NOT NECESSARY	100.00	50.00
2	REAR NUMBER PLATE LAMP @\$85.00	NOT NECESSARY	170.00	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	1,800.00	-
2	REAR EXHAUST CHROME PIPE @\$125.00	NOT NECESSARY	250.00	-
2	REAR FENDER @\$1250.00	TO REPAIR SEE LABOUR	2,500.00	-
2	REAR FENDER INNER GARNISH @\$598.40	NOT NECESSARY	1,196.80	-
2	REAR BUMPER TOW COVER @\$75.20	MISSING (1 PC ONLY)	150.40	16.20
4	REVERSING SENSOR HOLDER @\$22.00	NOT NECESSARY	88.00	-
1	REAR BUMPER	DEFORMED	1,210.00	1,042.00

Report Ref No. CC6/CTI19020843/Gda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,611.28	-1,347.64
			14,445.12	5,390.56
4	REVERSING SENSOR @\$274.00 (SN)	DAMAGED	1,096.00	200.00
	LESS 20% DISCOUNT		-219.20	-
			876.80	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BOOT BOARD CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL GARNISH CLIP (SN)	NECESSARY	40.00	20.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	45.00	40.00
			135.00	60.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		150.00	30.00
	APPLY ANTI RUST CHEMICAL.		200.00	60.00
	REMOVE AND REFIX PETROL TANK.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR CUSHION SEAT, TRIMMING ETC.		150.00	60.00
	REMOVE AND REFIX REVERSING SENSOR.		150.00	40.00
	REMOVE AND REFIX EXHAUST PIPE.	NOT NECESSARY	150.00	-
	LABOUR CHARGE FOR KNOCK DENTS, CUT & WELDING PARTS ON FRONT & REAR DAMAGE PORTION. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL, REAR SPARE TYRE PANEL, REAR EXHAUST SILENCER AND REAR FENDER.		1,800.00	850.00
	TO SPRAY PAINTING AND ETC.		1,600.00	1,000.00
			4,320.00	2,040.00
	GRAND TOTAL		19,776.92	7,690.56

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00
---	--	--	-----------------

Report Ref No. CC6/CTI19020843/Gda3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.