

ASS. REC. BY:

REF: CS/FCI 19020864/ Kyf3 12 | Special Instruction:

Supervisor: Kenneth ASSIGNMENT (Office)

From (Person): Rachel Wu Limoi of FCI Date/Time: 26.11.19 9.41a.m

Estimated Cost: Bill to:

OD/TP/AWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 944K Insured: SHA 2278C

at Workshop m/s Trans-cab Tel: 62876666

of NO 2 AMK Street 63

Policy No: Claim No: D1900 7408 MFS4

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 21.11.2019

CA / REV / REP. / REV 24 HRS "up" H.O.D. Endorsement:

Date/Time: 26.11.19 10.09a.m Person Contacted: zhe wei Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 944K - X
	SHA 2278C - (C3/AXA 13006885/ 4/2 f3c3 DCA - 11/04/2013
2/12@11:37am	Revised via email preli aduse

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 26. 11. 2019

Veh No: S110 944K Yr Regn: 12, 17

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or A) Make: Renault Latitude c.c. 1995

To Inspect Vehicle No: SHD 944K

Colour M. White / Red A/C: Insured / Std / NI / NA

at Workshop m/s Trans- Cab

Sp. Reading 288226 T/Radio: Insured / Std / NI / NA

of NO 2 AMK STRUA 63

Eng/No: _____ C/No: VIFIABL 15AUC 283228

Insured: _____

Gen. Cond: Good / Fair / Poor / Burnt

Policy No. _____

Steering: In order / Jammed / Leaked / Burnt or

Claims No. _____

Brake: In order / Jammed / Leaked / Burnt or

Sum Insured: _____ Excess: _____

Modi: Nil / S/Rim / STD A/Rim or

(Client's Record)

Tyre Size: F: Giti 215/60R16


Make of Veh: _____

R: Sailun

(Policy Condition)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Remark: The veh had commenced its repair at the time of inspection.



TOYO / YOKO or

Bal. or Market Value: _____

Front R/Bal. 8 mm Rear R/Bal. 9 mm

IDAC Accident Rpt: _____ Consistent?: Yes or No

L/Bal. 8 mm L/Bal. 9 mm

GIA / PR Seen: _____ Consistent?: Yes or No

D.O.A. 21/11/19 D.O.I. 26/11/19

Est. Repairs: 14 days Res.: Yes or No

Survey held at _____

Lum Sum: 1.B.1% 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

Rear O/S

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP \$13233-05 (Red \$45773-11, 77%)
	RECEIVED 20 MAR 2020

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 14

1) : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to? 2) 20/3/20 Typist

Add Fee: : Site Insp (\$)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Copies	
TOTAL	350

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format: _____

Lump Sum / T.P.R. \$ PIP \$13233-05



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007408MFSH

Date: 2/12/2019

Our Ref: CS/FCI19020864/Kyf3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 944K

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/11/2019 at the premises of M/s Trans-cab have the following to report: -

Workshop Estimate Amount	: S\$ <u>59,006.16</u>
Revised Estimate Amount	: S\$ <u>13,233.05</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the
Rear o/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-11-2019	Our Ref No. D19007408MFSH
Accident Date	21-11-2019	Claim Type. Third Party
Insured Vehicle	SHA2278C	Third Party Vehicle. SHD944K
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	RACHELWU LIMEI	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 2 December 2019 11:27 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Rachel Wu'
Subject: RE: SURVEY ASSESSMENT - D19007408MFSH/1
Attachments: PRELI ADVISED OF SHD 944K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 944K**
Number of days (estimated) : 14 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 26 November 2019 10:09 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Rachel Wu' <RachelWu@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007408MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 26 November, 2019 9:41 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Rachel Wu <RachelWu@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007408MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD944K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003133
Chassis No.:	VF1ABL15AUC283228
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,055.00
Total Rebate Amount:	\$41,053.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Nov 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 944K

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

26 NOV 2019

AAD1911-178

*Not Authored
 Resuming B4 paint*

SHD 944K

VF1ABL15AUC283228

RENAULT

LATITUDE

21.11.19

FCIL

29/12/2017

		PART
1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BUMPER BLOCK RH REAR
14	1	BUMPER BLOCK LH REAR
15	1	BUMPER HARNESS REAR
16	1	BOOT REAR
17	1	BOOT FINISHER
18	1	BOOT WHEATERSTRIP
19	1	BOOT REFLECTOR LAMP LH
20	1	BOOT REFLECTOR LAMP RH
21	1	BOOT BADGE 'RENAULT'
22	1	BOOT BADGE
23	1	BOOT STRUT LH
24	1	BOOT STRUT RH
25	1	BOOT HINGE LH
26	1	BOOT HINGE RH

		LIST
\$	<i>B1</i>	<i>B1</i> 561.70 ✓
\$	<i>B1</i>	<i>B1</i> 411.90 ✓
\$		<i>D11</i> 98.10 ✓
\$		<i>D11</i> 82.10 ✓
\$		<i>D11</i> 59.80 ✓
\$		<i>CM</i> 16.60 ✓
\$		<i>Sn</i> 80.80 X
\$		<i>Sn</i> 54.20 X
\$		<i>Sn</i> 16.60 X
\$		<i>B1</i> 547.80 ✓
\$		<i>Sn</i> 114.50 X
\$		<i>B1</i> 100.90 ✓
\$		<i>Sn</i> 76.50 X
\$		<i>Sn</i> 75.70 X
\$		<i>Sn</i> 301.10 X
\$		<i>Bur</i> 1,677.20 ✓
\$		<i>Sn</i> 344.70 X
\$		<i>D11ad</i> 178.20 ✓
\$		<i>Sn</i> 277.70 X
\$		<i>Ad</i> 277.70 ✓
\$		<i>Mc</i> 82.40 ✓
\$		<i>Mc</i> 95.80 ✓
\$		<i>Sn</i> 145.10 X
\$		<i>Sn</i> 145.10 X
\$		<i>R</i> 254.20 X
\$		<i>R</i> 253.80 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 944K

AAD1911-178

27	1	BOOT INNER TRIM BOARD	\$	Sm	611.00	
28	1	BOOT SWITCH	\$	Sm	113.00	
29	1	BOOT LOCK	\$	R	246.60	
30	1	BOOT LOCK CATCH	\$	R	41.70	
31	2	LICENCE PLATE LAMP	\$	Sm	26.30	
32	2	BOOT RUBBER PLUG	\$	Sm	139.30	} X
33	2	BOOT BUFFER	\$	Sm	26.80	
34	1	BOOT LOCK LINKAGE HOLDER	\$	Sm	99.50	
35	1	BOOT LOCK LINKAGE	\$	Sm	20.60	
36	1	CHASSIS PANEL REAR RH	\$	R	2,192.40	
37	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R	1,933.20	
38	1	FENDER INNER BOARD RH	\$	Sm	561.40	
39	1	FENDER PANEL INNER REAR RH	\$	R	952.50	
40	1	FENDER PANEL INNER TRIM REAR RH	\$	Neform	671.45	✓
41	1	FENDER PANEL REAR RH	\$	Bur	1,933.20	✓
42	1	WHEELARCH REAR RH	\$	Sm	275.40	X
43	1	SPARE TYRE BOARD	\$	Sm	680.90	X
44	1	TAILLAMP RH	\$	CM	313.10	—
45	1	TAILLAMP PANEL RH	\$	R	401.40	✓
46	1	TAILLAMP LH	\$	Sm	401.40	X
47	1	TAILLAMP PANEL LH	\$	R	401.40	X
48	1	AIR VENT RH	\$	Sm	59.40	X
49	1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
50	1	OUTER PANEL REAR (End Panel) TRIM	\$	Oit	404.56	✓
51	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	BT/Bur	1,229.40	✓
52	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
53	1	EXHAUST REAR	\$	R	5,263.60	X
54	1	EXHAUST CAP REAR	\$	De	125.40	✓
55	1	KNUCKLE ARM REAR RH	\$	Sm	472.10	} X
56	1	BRAKE DISC REAR	\$	Sm	266.50	
57	1	ABS SENSOR REAR RH	\$	Sm	190.50	
58	1	WHEEL HUB NUT	\$	Sm	41.80	
59	1	WHEEL HUB CAP	\$	Sm	30.50	
60	1	KNUCKLE HUB+ BEARING RH	\$	Sm	272.30	
61	1	REAR AXLE	\$	Sm	3,469.00	

Trans-cab Auto Services Pte Ltd

AAD1911-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 944K

62	1	AXLE ARM RH	\$	69.50
63	1	REAR AXLE SPACER	\$	49.00
64	1	REAR AXLE ARM ROD	\$	69.50
65	1	LOWER ARM REAR RH	\$	543.50
66	1	AXLE SPRING ARM RH	\$	220.60
67	1	AXLE SPRING ARM BUSH UPPER	\$	42.50
68	1	AXLE SPRING ARM BUSH LOWER	\$	30.80
69	1	ABSORBER REAR	\$	217.30
70	1	ABSORBER DUST COVER REAR	\$	47.10
71	1	ABSORBER MOUNTING REAR	\$	49.40
72	1	STABILIZER BAR REAR	\$	427.90
73	1	STABILIZER LINK REAR	\$	55.20
74	1	BRAKE CALIPER REAR RH	\$	659.10
75	1	BRAKE PAD REAR	\$	145.60
76	1	BRAKE CALIPER BRACKET REAR RH	\$	384.00
77	1	BRAKE HOSE REAR RH	\$	79.50
78	1	SUBFRAME ARM REAR	\$	198.33
79	1	RODE- LONG REAR	\$	120.16
80	1	DOOR PANEL REAR RH	\$	758.70
TOTAL				\$ 35,723.51
10%				\$ 3,572.35
				\$ 32,151.16

Sm
X

Special Nett

1	1SET	PARKING AID	\$	700.00	<i>Shay</i>	<i>400sm</i>
2	1SET	REAR BUMPER CLIP	\$	66.00	<i>na</i>	<i>—</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	<i>na</i>	<i>—</i>
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	<i>na</i>	<i>X</i>
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	<i>na</i>	<i>X</i>
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	<i>na</i>	<i>X</i>
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	<i>na</i>	<i>X</i>
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	<i>na</i>	<i>X</i>
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	<i>na</i>	<i>✓</i>
10	1	EXHAUST MOUNTING REAR	\$	16.00	<i>na</i>	<i>X</i>
11	1	EXHAUST BRACKET REAR	\$	24.80	<i>na</i>	<i>X</i>
12	1SET	BOOT FINISHER CLIP	\$	24.20	<i>na</i>	<i>X</i>
13	1	BOOT STICKER "Trans-cab"	\$	30.00	<i>na</i>	<i>—</i>
14	1	BOOT STICKER "6555-3333"	\$	30.00	<i>na</i>	<i>—</i>

Trans-cab Auto Services Pte Ltd

AAD1911-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 944K

15	1	BOOT INNER TRIM CLIP	\$	nn	45.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
17	1	SPARE TYRE	\$	sn	330.00	X
18	1	TAILLAMP CLIP RH	\$	nn	5.00	✓
19	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	40sn
20	1	WINDSCREEN MOULDING	\$	nn	100.00	X
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
22	1	TAILLAMP CLIP LH	\$	nn	5.00	} X
23	1	Rear Bumper Protector	\$	nn	100.00	
24	1SET	Rear licence plate with holder	\$	sn	80.00	
25	1	REAR RIGHT TYRE	\$	sn	300.00	
26	1	REAR RIGHT TYRE RIM	\$	sn	380.00	
27	1	REAR RH TYRE RIM COVER	\$	sn	50.00	
28	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	
29	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	
30	1	REAR DOOR STICKER "6555-3333"	\$	nn	80.00	
TOTAL			\$		3,175.00	

TOTAL PARTS \$ 35,326.16

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	1100l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	1800l
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80l
To Rust-Proofing Of The Affected Areas.	\$	170.00	120l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60l.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 944K

AAD1911-178

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 944K

AAD1911-178

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	↳ 380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	↳ 380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	↳ 170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	↳ 380.00	X
TOTAL	\$	23,680.00	
Over All Total	\$	59,006.16	

(PART BY PART) Repair Days

~~30 DAYS~~
14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020864/Kyf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-03-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2278C	Veh. Inspected	SHD 944K
Policy No.		Coverage (\$)	0.00
Claim No.	D19007408MFSH	Excess (\$)	0.00
Assign From	RACHEL WU LIMEI	Assign Date	26/11/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1ABL15AUC283228	Colour	METALLIC WHITE / RED
Odometer	288226	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	SAILUN	9 mm
L/H Rear Tyre	215/60 R16	SAILUN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/11/2019	Inspection Date	26/11/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 944K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	BENT	561.70	561.70
1	BUMPER LOWER REAR	BENT	411.90	411.90
1	BUMPER BRACKET CTR REAR	DISTORTED	98.10	98.10
1	BUMPER BRACKET SIDE RH REAR	DISTORTED	82.10	82.10
1	BUMPER RETAINER RH REAR	DISTORTED	59.80	59.80
1	BUMPER REFLECTOR RH	CRACKED	16.60	16.60
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	SERVICEABLE	114.50	-
1	BUMPER BEAM BRACKET RH REAR	BENT	100.90	100.90
1	BUMPER BLOCK RH REAR	SERVICEABLE	76.50	-
1	BUMPER BLOCK LH REAR	SERVICEABLE	75.70	-
1	BUMPER HARNESS REAR	SERVICEABLE	301.10	-
1	BOOT REAR	BUCKLED	1,677.20	1,677.20
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	DISTORTED / DENTED	178.20	178.20
1	BOOT REFLETOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLETOR LAMP RH	DENTED	277.70	277.70
1	BOOT BADGE "RENAULT"	NECESSARY	82.40	82.40
1	BOOT BADGE	NECESSARY	95.80	95.80
1	BOOT STRUT LH	SERVICEABLE	145.10	-
1	BOOT STRUT RH	SERVICEABLE	145.10	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	41.70	-
2	LICENCE PLATE LAMP	SERVICEABLE	26.30	-
2	BOOT RUBBER PLUG	SERVICEABLE	139.30	-
2	BOOT RUBBER	SERVICEABLE	26.80	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	99.50	-
1	BOOT LOCK LINKAGE	SERVICEABLE	20.60	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	2,192.40	-
1	FENDER WHEEL HOUSE PANEL REAR RH	TO REPAIR SEE LABOUR	1,933.20	-
1	FENDER INNER BOARD RH	SERVICEABLE	561.40	-
1	FENDER PANEL INNER REAR RH	TO REPAIR SEE LABOUR	952.50	-
1	FENDER PANEL INNER TRIM REAR RH	DEFORMED	671.45	671.45
1	FENDER PANEL REAR RH	BUCKLED	1,933.20	1,933.20
1	WHEELARCH REAR RH	SERVICEABLE	275.40	-
1	SPARE TYRE BOARD	SERVICEABLE	680.90	-
1	TAILLAMP RH	CRACKED	313.10	313.10
1	TAILLAMP PANEL RH	BENT	401.40	401.40
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	AIR VENT RH	SERVICEABLE	59.40	-
1	OUTER PANEL REAR (END PANEL)	BENT	745.80	745.80
1	OUTER PANEL REAR (END PANEL) TRIM	DISTORTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	BENT / BUCKLED	1,229.40	1,229.40
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	5,263.60	-
1	EXHAUST CAP REAR	DENTED	125.40	125.40
1	KNUCKLE ARM REAR RH	SERVICEABLE	472.10	-
1	BRAKE DISC REAR	SERVICEABLE	266.50	-

Report Ref No. CS/FC119020864/Kyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABS SENSOR REAR RH	SERVICEABLE	190.50	-
1	WHEEL HUB NUT	SERVICEABLE	41.80	-
1	WHEEL HUB CAP	SERVICEABLE	30.50	-
1	KNUCKLE HUB + BEARING RH	SERVICEABLE	272.30	-
1	REAR AXLE	SERVICEABLE	3,469.00	-
1	AXLE ARM RH	SERVICEABLE	69.50	-
1	REAR AXLE SPACER	SERVICEABLE	49.00	-
1	REAR AXLE ARM ROD	SERVICEABLE	69.50	-
1	LOWER ARM REAR RH	SERVICEABLE	543.50	-
1	AXLE SPRING ARM RH	SERVICEABLE	220.60	-
1	AXLE SPRING ARM BUSH UPPER	SERVICEABLE	42.50	-
1	AXLE SPRING ARM BUSH LOWER	SERVICEABLE	30.80	-
1	ABSORBER REAR	SERVICEABLE	217.30	-
1	ABSORBER DUST COVER REAR	SERVICEABLE	47.10	-
1	ABSORBER MOUNTING REAR	SERVICEABLE	49.40	-
1	STABILIZER BAR REAR	SERVICEABLE	427.90	-
1	STABILIZER LINK REAR	SERVICEABLE	55.20	-
1	BRAKE CALIPER REAR RH	SERVICEABLE	659.10	-
1	BRAKE PAD REAR	SERVICEABLE	145.60	-
1	BRAKE CALIPER BRACKET REAR RH	SERVICEABLE	384.00	-
1	BRAKE HOSE REAR RH	SERVICEABLE	79.50	-
1	SUBFRAME ARM REAR	SERVICEABLE	198.33	-
1	RODE-LONG REAR	SERVICEABLE	120.16	-
1	DOOR PANEL REAR RH	SERVICEABLE	758.70	-
	LESS 10% DISCOUNT		-3,572.35	-1,001.46
			32,151.16	9,013.05
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-

Report Ref No. CS/FCI19020864/Kyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	16.00	-
1	EXHAUST BRACKET REAR (SN)	NOT NECESSARY	24.80	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	REAR RIGHT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	REAR RH TYRE RIM COVER (SN)	SERVICEABLE	50.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
			3,175.00	700.00
LABOUR				
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.			9,000.00	1,100.00

Report Ref No. CS/FCI19020864/Kyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,CHASSIS PANEL REAR RH,FENDER WHEEL HOUSE PANEL REAR RH,FENDER PANEL INNER REAR RH,TAILLAMP PANEL LH AND EXHAUST REAR.		9,000.00	1,800.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.		170.00	60.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	100.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19020864/Kyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAK POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR AXLE ASSY,REMOVE AND RENEWAL OF PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK ABS AND BRAKE EFFICIENCY,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			23,680.00	3,520.00
	GRAND TOTAL		59,006.16	13,233.05
RECOMMENDED COST OF REPAIRS				13,233.05

Report Ref No. CS/FC119020864/Kyf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.