

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCR 784R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	915.00	915.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	580.00	-
1	REAR BUMPER ABSORBER	* CHECK	165.00	-
1	REAR BUMPER RETAINER, UPPER LH	* CHECK	70.00	-
1	REAR BUMPER SIDE, NO.1, LH	* CHECK	75.00	-
1	REAR BUMPER SIDE RETAINER, NO. 2, LH	* CHECK	115.00	-
1	REAR BUMPER SIDE RETAINER LH	* CHECK	25.00	-
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	30.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	850.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	865.00	-
1	REAR SPLASH SHIELD LH	NOT NECESSARY	415.00	-
1	REAR TOW COVER LH	NOT NECESSARY	30.00	-
			4,160.00	945.00
	SPECIAL NETT ITEMS			
1	REAR SENSOR (SN)	NOT NECESSARY	250.00	-
			250.00	-
	<u>LABOUR</u>			
	REPLACE NEW PARTS, REMOVE / REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,500.00	250.00
	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.		1,000.00	400.00
	REMOVE AND REFIT REAR TAIL LAMP TO FACILITATE REPAIR.	NOT NECESSARY	200.00	-
	CHECK WIRING AND PROPER FUNCTIONING.		80.00	30.00
			2,780.00	680.00
	GRAND TOTAL		7,190.00	1,625.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$450.00 NETT)			1,625.00

Report Ref No. CS/INC19020879/Evd3e2





Report Ref No. CS/INC19020879/Evd3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser