



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020879/Evd3e2

73 BRAS BASAH ROAD

Date: 27-11-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : ENG HUEY HUEY

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FZ 4485A	Veh. Inspected	SCR 784R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1072027-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	26/11/2019

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA GS300	c.c	2994
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JTHBG96S405013837	Colour	BLUE
Odometer	189971 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	DUNLOP	5 mm
L/H Front Tyre	225/50 R17	DUNLOP	5 mm
R/H Rear Tyre	225/50 R17	DUNLOP	5 mm
L/H Rear Tyre	225/50 R17	DUNLOP	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	18/11/2019	Inspect Date / Time	26/11/2019 ( 11:46 AM )
Survey held at	HIN LUNG WORKSHOP BLK 1008 BUKIT MERAH LANE 3 #01-20 SINGAPORE 159722		

#### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------