

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19020908/UPA3Q2
Date: 27/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SKD2417S	Insured Vehicle No :	GBH4356G
Date of Loss:	10/11/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001409

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD2417S	Engine No:	CDA247289
Make & Model:	VOLKSWAGEN PASSAT CC, 1.8 TSI (A)	Chassis No:	WVWZZZ3CZCE538005
Reg. Date:	11/11/2011 (Man. Year: 2011)	Odometer:	115812 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45Z R17	Rear Tyre Size:	235/45Z R17
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,188.90	3,600.77	9,588.13	72.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	660.00	2,200.00	76.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,048.90	4,260.77	11,788.13	73.45
Approved Total (Overridden) (S\$)		3,400.00		

Nett Amount (S\$)	16,048.90	3,400.00	12,648.90	78.81
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/11/2019

Date Inspected: 31/01/2020

Estimated Period of Repair: 3.0 days

Inspected At: 15 KAKI BUKIT ROAD # 01-53
Repairer: Asia Motorsports Solution Pte Ltd (HQ)

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
Parts:	143	VOLKSWAGEN PASSAT CC 1.8 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD2417S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	1,680.00 FL	*1,579.77 FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	154.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	598.00 FL	*- FL
4	1		*FRONT BUMPER FOAM	Torn	185.00 FL	*116.42 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	310.00 FL	*- FL
6	2		*FRONT BUMPER DAYLIGHT LAMPS	Not Necessary	545.00 FL	*- FL
7	2		*FRONT FOG LAMP	Not Necessary	984.00 FL	*- FL
8	2		*FRONT FOG LAMP COVER	Not Necessary	284.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL COMPLETE	Not Necessary	780.00 FL	*- FL
10	1		*FRONT SUPPORT PANEL TOP COVER	Cracked	298.00 FL	*298.00 FL
11	1		*FRONT RADIATOR GRILLE	Cracked	372.00 FL	*372.00 FL
12	1		*FRONT RADIATOR GRILLE CHROME	Cracked	480.00 FL	*480.00 FL
13	1		*RHS FRONT FENDER	Not Necessary	982.00 FL	*- FL
14	1		*RHS FRONT FENDER INNER SHIELD	Not Necessary	232.00 FL	*- FL
15	1		*RHS FRONT DOR (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*RHS & LHS HEADLAMP	O/S Cracked	2,900.00 FL	*988.00 FL
17	2		*RHS & LHS HEADLAMP LOWER PANEL	Not Necessary	420.00 FL	*- FL
18	2		*RHS & LHS HEADLAMP TOP PANEL	Not Necessary	344.00 FL	*- FL
19	1		*BONNET	Not Necessary	1,798.00 FL	*- FL
20	1		*BONNET DAMPER (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*BONNET LOCK	Not Necessary	245.00 FL	*- FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
23	1		*SET FRONT PDC SENSOR	Not Necessary	480.00 FS	*- FS
24	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS	Not Necessary	60.00 FS	*- FS
25	1		*SET RHS FRONT FENDER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
26	1		*FRONT NUMBER PLATE W/HOLDER	Bent	75.00 FS	*40.00 FS
27	1		*FRONT NUMBER PLATE GARNISH	Torn	90.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT GRILLE VW BADGE	Not Necessary	132.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					14,548.00	3,984.19
- List Item Discount on L Items 10.00/10.00% (\$)					1,359.10	383.42
Total Parts (\$)					13,188.90	3,600.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS & COMPONENTS	New	1,200.00	300.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED AND REPAIRED (FRONT DOOR)	New	1,000.00	300.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS AND FOCUS HEADLAMP BEAM	New	120.00	20.00
4	TO REMOVE AND REPLACE FRONT PDC SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	40.00
5	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION	New	300.00	0.00
6	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			2,860.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >