

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020918/UBA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994164

Claimant
Vehicle No : SLQ4120D **Insured Vehicle No :** GBH7276J

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: 1942882265SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4120D		
Make & Model:	TOYOTA SIENTA, 1.5 WELCAB 1.5G A (A)	Engine No:	2NR8630457
Reg. Date:	07/07/2017 (Man. Year: 2016)	Chassis No:	NSP1727001207
Colour:	Blue	Odometer:	203682 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,199.53	2,231.62	4,967.91	69.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,370.00	2,120.00	60.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,689.53	3,601.62	7,087.91	66.31
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	10,689.53	2,800.00	7,889.53	73.81
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,076.45		
Global Sum Settlement (S\$)		3,050.00		

INSPECTION

Date of Assignment: 26/11/2019

Date Inspected: 28/11/2019 Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
BLK 15 KAKI BUKIT ROAD 4 #01-53
BARTLEY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.70 FL	*120.70 FL
2	1		*REAR TAILGATE	Badly Dented	1,602.41 FL	*1,245.10 FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	481.94 FL	*- FL
4	1		*REAR TAILGATE LAMPS	O/S Scratched	770.40 FL	*385.20 FL
5	1		*REAR TAILGATE LOCK	Serviceable	489.67 FL	*- FL
6	1		*REAR TAILGATE LOGO	Necessary	58.50 FL	*58.50 FL
7	1		*REAR TAILGATE RUBBER	Not Necessary	291.61 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Cracked	257.30 FL	*257.30 FL
9	1		*REAR WIPER MOTOR	Not Necessary	436.80 FL	*- FL
10	2		*REAR TAILLAMPS	Not Necessary	874.40 FL	*- FL
11	1		*REAR END PANEL	Repair	820.65 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Not Necessary	221.50 FL	*- FL
13	1		*REAR SMART KEYLESS SENSOR	Not Necessary	189.50 FL	*- FL
14	1		*REAR BUMPER	Deformed	788.70 FL	*788.70 FL
15	1		*REAR BUMPER BRACKET	Not Necessary	98.50 FL	*- FL
16	1		*REAR BUMPER CENTRE PAD	No such part	225.00 FL	*- FL
17	1		*REAR BUMPER REFLECTOR	Not Necessary	95.00 FL	*- FL
18	1		*REAR BUMPER REFLECTOR OUTER GARNISH	Not Necessary	180.50 FL	*- FL
19	1		*REAR BUMPER SIDE OUTER GARNISH	Not Necessary	127.50 FL	*- FL
20	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	128.80 FL	*- FL
21	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*REAR PRIVATE HIRE STICKER	Not Necessary	45.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
24	1		*SET REAR REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
25	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,264.38	2,945.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,064.85	713.88
Total Parts (\$\$)	7,199.53	2,231.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	180.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	150.00	30.00
7	PANEL BEATING	New	1,400.00	450.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	580.00
Gross Labour Cost (\$\$)			3,490.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >