

YP8062M FUSO FEB50

DATE 25/11/2019

No	Qty	PARTICULAR	AMOUNT S\$	
1	1	WIPER PANEL ✓ CRA	951.00	398.40 ✓
2	1	WIPER LINKAGE X SVC	752.30	
3	1	WIPER ARM 4H ✓ CRA	185.00	✓
4	1	FRONT PANEL ✓ BT	1,122.40	730.80 ✓
5	1	FRONT PANEL (FUSO) EMBLEM ✓ nec	250.00	160.20 ✓
6	1	FRONT GRILL ✓ CRA	1,105.70	688.50 ✓
7	1	FRONT GRILL LOGO ✓ nec	112.00	75.20 ✓
8	1	FRONT GRILL CANTER EMBLEM ✓ nec	125.00	78.90 ✓
9	1	CORNER PANEL LH X R	475.20	
10	1	MIRROR ARM LH X SVC	452.30	
11	1	FRONT BUMPER ✓ cut	920.00	820.80 ✓
12	2	FRONT SIDE BUMPER R+L ✓ CRA	684.40	600.60 ✓
13	1	FRONT BUMPER REINFORCEMENT X NS	452.00	
14	2	FRONT BUMPER BRACKET R+L ✓ BT	392.60	285 ✓
15	1	FRONT BUMPER LAMP LH X (SVC)	352.00	
16	1	HEADLAMP ASSY LH ✓ CRA	501.50	410.50 ✓
17	1	SIGNAL LAMP LH ✓ CRA	266.40	107.50 ✓
18	1	SIDE REFLECTOR LH X SVC	175.00	
			\$ 9,274.80	
		LESS 20%	\$ 1,854.96	
			\$ 7,419.84	

No	Qty	PARTICULAR	SPECIAL NETT	sup	AMOUNT S\$
1	1	WINDSCREEN SEALANT	X NS	Weatherstrip - 265	90.00
2	1	WINDSCREEN GLASS INNER SEAL	X NS	✓ nec	65.00
3	1	AIR CON COOLING BOX ASSY X SVC			1,850.00
4	1	FAN BLOWER ASSY X SVC			1,455.00
5	1	FRONT/REAR NUMBER PLATE ✓ CRA			75.00 ✓
6	1	REAR NUMBER PLATE BRACKET ✓ BT			195.20 95.20 ✓
7	8	REAR NUMBER PLATE LAMP X SVC			50.00
8	8	FOOT STEP BRACKET X R			85.00
9	6	WIPER PANEL CLIP ✓ nec			48.00 20 ✓
10	1	CORNER PANEL CLIP ✓ nec	8ps		64.00 25 ✓
11	2	FRONT GRILL CLIP ✓ nec	8ps		36.00 20 ✓
12	1	REAR CARGO BOX LOWER PANEL X R			1,450.00
13	1	TAIL LAMP LH RH ✓ CRA			328.20 270.20 ✓
14	1	CARGO DOOR LOCK HANDLE ASSY X R			1,570.00
15	1	REVERSE SENSOR ✓ mis			200.00 ✓
					\$ 7,561.40

No	LABOUR & MISCELLANEOUS:	AMOUNT \$S
1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,000.00 600 ✓
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,000.00 700 ✓
3	To remove,refix front dashboard with all necessary components/attachments	200.00 150 ✓
4	To remove,refix front windscreen glass and water test	200.00 150 ✓
5	To conduct headlamp alignment	30.00 15 ✓
6	To remove,replace air con cooling box,blower assy with all necessary attachments and recharge gas	350.00 200 ✓
7	To straighten rear cargo box lower rear member repair dented panel replace damage parts	1,500.00 500 ✓
8	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	600.00 250 ✓
9	To install reverse sensor and check function	80.00 40 ✓
		\$ 4,760.00

20,306.24#

L/s refer
without prejudice
Hock Ann
85311883
27/11/19

5:35pm

Resurvey taken
16/3/20 2:25pm
H ANN (LKK)

8 Leg
Hock Ann @ LKK Auto.com
Resurvey after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts	4541140
Parts less	20%
	3633112
Spent	970140
Labour	2605
	7208.52
L/s less	20%
Total	5766.81
L/s An	\$5750#