

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020944/HGA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJX3260B	Insured Vehicle No :	SH7852U
Date of Loss: 23/11/2019	Nature of Claim: TP	Claim No: MCT19110543

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX3260B		
Make & Model:	HONDA CIVIC, 1.3 IMA CVT (A)	Engine No:	LDA24018228
Reg. Date:	02/06/2010 (Man. Year: 2008)	Chassis No:	JHMF36209S205247
Colour:	Black	Odometer:	314468 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,981.80	3,581.36	14,400.44	80.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,150.00	2,905.00	12,245.00	80.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	33,131.80	6,486.36	26,645.44	80.42
Approved Total (Overridden) (\$)		5,000.00		
(\$)	33,131.80	5,000.00	28,131.80	84.91
+ GST 7.00/7.00% (\$)	2,319.23	350.00	1,969.23	84.91
Nett Amount (\$)	35,451.03	5,350.00	30,101.03	84.91
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	26/11/2019	
Date Inspected:	26/11/2019 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ)
		8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
		Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: LEE HOCK ANN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	143	HONDA CIVIC 1.3 IMA CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX3260B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROCKER PANEL (L+R)	N/S Cut / O/S Serviceable	1,780.00 F	*685.85 FL
2	2		*ROCKER PANEL GARNISH (L/R)	Serviceable	967.20 F	*- FL
3	1		*REAR WINDSCREEN SEALANT	Necessary	148.60 F	*140.00 FL
4	1		*TAIL LAMP (LH) (NPA)	Serviceable	0.00 F	*- FL
5	1		*TAIL LAMP PANEL (LH) (NPA)	Serviceable	0.00 F	*- FL
6	1		*REAR BUMPER	Crumpled	857.70 F	*604.20 FL
7	1		*REAR BUMPER RETAINER (L+R)	N/S Necessary /O/S Serviceable	122.80 F	*48.60 FL
8	1		*REAR BUMPER REINFORCEMENT BAR (NPA)	Serviceable	0.00 F	*- FL
9	2		*REAR BUMPER BRACKET (L+R) (NPA)	Serviceable	0.00 F	*- FL
10	1		*REAR BUMPER BEAM (NPA)	Serviceable	0.00 F	*- FL
11	1		*REAR BUMPER SPONGE (NPA)	Serviceable	0.00 F	*- FL
12	1		*REAR BUMPER UNDERCOVER (NPA)	Serviceable	0.00 F	*- FL
13	1		*REAR FENDER (LH)	Cut	1,167.40 F	*683.80 FL
14	1		*REAR FENDER INNER PANEL (LH) (NPA)	Repair	0.00 F	*- FL
15	1		*REAR FENDER INNER TRIM (LH) (NPA)	Serviceable	0.00 F	*- FL
16	1		*REAR FENDER PETROL COVER (LH) (NPA)	Serviceable	0.00 F	*- FL
17	1		*REAR FENDER COWLING (LH)	Serviceable	103.90 F	*- FL
18	1		*REAR FENDER MUDFLAP (LH)	Crumpled	96.00 F	*77.60 FL
19	1		*C PILLAR LOWER (LH) (NPA)	Not Necessary	0.00 F	*- FL
20	1		*REAR DOOR (LH)	Bent	819.50 F	*786.50 FL
21	1		*REAR DOOR WINDOW MOULDING (LH) (NPA)	Not Necessary	0.00 F	*- FL
22	1		*REAR DOOR SIDE PROTECTOR (LH) (NPA)	Not Necessary	0.00 F	*- FL
23	1		*REAR DOOR SIDE PROTECTOR CHROME STRIP (LH) (NPA)	Not Necessary	0.00 F	*- FL
24	1		*REAR DOOR LOCK (LH)	Jammed	268.90 F	*220.70 FL
25	1		*REAR DOOR LOCK CATCH (LH) (NPA)	Serviceable	0.00 F	*- FL
26	1		*REAR DOOR INNER BOARD (LH) (NPA)	Serviceable	0.00 F	*- FL
27	1		*REAR DOOR INNER BOARD SWITCH (LH) (NPA)	Serviceable	0.00 F	*- FL
28	1		*REAR DOOR POWER WINDOW MOTOR (LH)	Serviceable	274.60 F	*- FL
29	1		*REAR DOOR REGULATOR (LH)	Serviceable	322.80 F	*- FL
30	1		*REAR DOOR HINGE (UPPER & LOWER) (LH) (NPA)	Serviceable	0.00 F	*- FL
31	1		*REAR DOOR CHECKER (LH) (NPA)	Serviceable	0.00 F	*- FL
32	1		*REAR DOOR WEATHERSTRIP (LH)	Necessary	178.60 F	*94.80 FL
33	1		*REAR DOOR INNER WEATHERSTRIP (LH)	Necessary	183.90 F	*87.60 FL
34	1		*REAR ABSORBER (LH)	Serviceable	266.40 F	*- FL
35	1		*REAR LOWER ARM (LH)	Crumpled	384.80 F	*327.80 FL
36	1		*REAR KNUCKLE (LH)	Bent	297.30 F	*230.80 FL
37	1		*REAR KNUCKLE BEARING (LH)	Jammed	168.40 F	*159.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR BEARING HUB (LH)	Jammed	163.30 F	*110.30 FL
39	1		*REAR AXLE	Serviceable	1,910.00 F	*- FL
40	10		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
41	10		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
42	1		*FRONT FENDER INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
43	1		*FRONT FENDER QUARTER WINDOW SEALANT	Not Necessary	120.00 FS	*- FS
44	10		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
45	5		*FRONT FENDER MUDFLAP CLIPS	Not Necessary	50.00 FS	*- FS
46	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
47	10		*FRONT DOOR INNER BOARD CLIPS	Not Necessary	100.00 FS	*- FS
48	2		*SET FRONT DOOR VISOR	Not Necessary	400.00 FS	*- FS
49	1		*FRONT DOOR HANDLE CHROME (RH)	Not Necessary	800.00 FS	*- FS
50	1		*FRONT DOOR HANDLE END CAP CHROME (RH)	Not Necessary	300.00 FS	*- FS
51	1		*ROCKER PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
52	1		*REAR WINDSCREEN MOULDING SEALANT	Necessary	120.00 FS	*30.00 FS
53	1		*BOOTLID SPOILER	Not Necessary	2,000.00 FS	*- FS
54	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
55	1		*TAIL LAMP CLIPS (L+R)	N/S Necessary	80.00 FS	*10.00 FS
56	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*25.00 FS
57	2		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
58	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*30.00 FS
59	10		*REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FS	*20.00 FS
60	1		*REAR FENDER COWLING CLIPS (10 PCS)	Necessary (3 PCS ONLY)	100.00 FS	*10.00 FS
61	10		*REAR FENDER MUDFLAP CLIPS	Serviceable	100.00 FS	*- FS
62	1		*C PILLAR SEALANT	Not Necessary	120.00 FS	*- FS
63	1		*REAR DOOR HANDLE (LH)	Not Necessary	800.00 FS	*- FS
64	1		*REAR DOOR HANDLE END CAP (LH)	Not Necessary	300.00 FS	*- FS
65	10		*REAR DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
66	1		*REAR CONTROL KNOCKLE ARM (LH)	Serviceable	350.80 F	*- FL
67	1		*REAR STRAIGHT ARM (LH)	Serviceable	298.90 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,981.80	4,432.95
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	851.59
Total Parts (\$\$)	17,981.80	3,581.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT/WELD ,KNOCK & REALIGN	New	6,000.00	1,400.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	4,200.00	1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	400.00	0.00
4	TO RNR REAR WINDSCREEN	New	400.00	100.00
5	TO RNR REAR BOOT MECHANISM	New	400.00	0.00
6	TO RNR REAR LUGGAGE COMPARTMENT	New	400.00	0.00
7	TO RNR UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS	New	400.00	0.00
8	TO RNR DOOR MECHANISM	New	800.00	0.00
9	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	120.00	20.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
11	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	150.00
12	TO CHECK WHEEL ALIGNMENT	New	250.00	60.00
13	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	150.00	0.00
14	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	25.00
15	TO RNR TYRE AND WHEEL BALANCING	New	250.00	0.00
16	TO DO DIAGNOSIS AND RESET REPROGRAM OR CODING FAULT CODE	New	400.00	120.00
17	TO DO WATER LEAK TEST	New	80.00	30.00
18	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	250.00	0.00
Gross Labour Cost (\$\$)			15,150.00	2,905.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >