Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020945/KDA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SCK7087K Insured Vehicle No: GBJ2165T

Vehicle No:

Date of Loss: Nature of Claim: ΤP 20/11/2019 Claim No: 4343424557SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SCK7087K Reg No:

Make & Model: MERCEDES-BENZ E250, 1.8 (A) Engine No: 27186030619521 WDD2074472F209917 Reg. Date: 22/03/2013 (Man. Year: 2012) Chassis No: Odometer: 96824 km

Colour: Metallic Pearl White

Engine Capacity: 1796 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R19 Rear Tyre Size: 245/35Z R19 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,748.40	4,128.30	620.10	13.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,870.00	580.00	1,290.00	68.98
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	6,618.40	4,708.30	1,910.10	28.86
			000.00		

+ Loss of Use (2.0 x S\$100.00/day) (S\$) 200.00 + Doc/Search Fee (S\$) 7.45 Nett Liability (S\$) 4,915.75

INSPECTION

Date of Assignment: 26/11/2019

Date Inspected: 26/11/2019 Inspected At: **G.M.MOTOR PTE LTD**

BLK 5035 ANG MO KIO IND. PARK 2

#01-359

SINGAPORE 569538

Estimated Period of Repair: 2.0 days

KENNETH KONG Manager: CHAN JIA LE Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS
2	1		*FRONT NUMBER PLATE GARNISH	Serviceable	182.00 FL	*- FL
3	1		*BONNET	Bent	2,980.00 FL	*2,980.00 FL
4	1		*BONNET LOCK	Repair	105.00 FL	*- FL
5	1		*BONNET EMBLEM	Necessary	85.00 FL	*85.00 FL
6	1		*BONNET CHROME	Cracked	162.00 FL	*162.00 FL
7	1		*BONNET HINGE LH	Repair	176.00 FL	*- FL
8	1		*BONNET HINGE RH	Repair	176.00 FL	*- FL
9	1		*FRONT GRILLE	Cracked	969.00 FL	*969.00 FL
10	1		*FRONT GRILLE BASE	Cracked	127.00 FL	*127.00 FL
11	1		*FRONT GRILLE LOGO	Necessary	159.00 FL	*159.00 FL
12	1		*SUPPORT PANEL HOLDER	Cracked	105.00 FL	*105.00 FL
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,271.00	4,587.00
			- List Item Discount on L Items	s 10.00/10.00% (S\$) _	522.60	458.70
				Total Parts (S\$)	4,748.40	4,128.30
			Report was unsubmitted dui	ing this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,SUPPORT PANEL ,FRONT BUMPER)	New	800.00	200.00				
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER,SUPPORT PANEL,FRONT BUMPER)	New	800.00	300.00				
3	TO CHECK WIRING	New	50.00	20.00				
4	TO REMOVE & REFIT FRONT BUMPER SENSOR	New	120.00	60.00				
5	TO TUFF COAT	New	100.00	0.00				
	Gross Labour Cost (S\$)		1,870.00	580.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.