

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 3794Y

DATE 26/11/2019 9:55

MAKE :

MODEL : HYUNDAI IONIQ

*Like*

*ALG*

| Qty | Parts Description/ Labour                         | Type | Unit Price   | Amount                |
|-----|---|------|--------------|-----------------------|
|     | Rear Bumper <i>X (R)</i>                          |      |              | \$ 459.40             |
|     | Rear Bumper Centre Moulding Assy <i>cut</i>       |      |              | \$ 451.25             |
|     | Rear Bumper Lower Centre Moulding Assy <i>Xun</i> |      |              | \$ 155.00             |
|     | Rear Bumper Stay <i>Xun</i>                       |      |              | \$ 138.10             |
|     | Rear Bumper Side Bracket (LH/RH) <i>Xun</i>       |      | \$ 33.10     | \$ 66.20              |
|     | Rear Bumper Cover Clips <i>Xun</i>                |      |              | \$ 22.00              |
|     | <b>SUB TOTAL</b>                                  |      |              | <b>\$ 1,291.95</b>    |
|     | <b>LESS 20%</b>                                   |      |              | <b>\$ 258.39</b>      |
|     | <b>DISCOUNTED TOTAL</b>                           |      |              | <b>\$ 1,033.56</b>    |
|     | Rear No. Plate <i>cha</i>                         |      |              | \$ 25.00 <b>Nett</b>  |
|     | Rear No. Plate Trim Cover <i>Xun</i>              |      |              | \$ 30.00 <b>Nett</b>  |
|     | Rear Bumper Reverse Sensor <i>Xun</i>             |      |              | \$ 135.70 <b>Nett</b> |
|     | Rear Bumper Rubber Mat <i>Xun</i>                 |      |              | \$ 50.00 <b>Nett</b>  |
|     |   |      |              | <b>\$ 240.70</b>      |
|     | <b>Labour Charge</b>                              |      |              |                       |
|     | Panel Beating                                     |      | <i>\$240</i> | \$ 350.00             |
|     | Spray Painting Charge                             |      | <i>\$200</i> | \$ 250.00             |
|     | Wiring Charge                                     |      | <i>Xun</i>   | \$ 50.00              |
|     | Remove/Refix Reverse Sensor                       |      | <i>Xun</i>   | \$ 80.00              |
|     |   |      |              | <b>\$ 730.00</b>      |
|     | <b>TOTAL LABOUR</b>                               |      |              | <b>\$ 730.00</b>      |
|     | <b>ESTIMATE TOTAL</b>                             |      |              | <b>\$ 2,004.26</b>    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Ram (LKK)*  
*26/11/19 1230hrs*  
*Part by part*  
*aft repair photo*  
*2 repair days*  
*Park Surin@LKKauto.com*  
*8822778no*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.