

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19020954/R1HA3Q2**Date:** 11/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant**Vehicle No :** SBS3420C**Insured Vehicle No :** SJJ1777P

Date of Loss: 23/11/2019

Nature of Claim: TP

Claim No: 3705366653SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBS3420C**

Make & Model: VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)

Engine No: D9193064

Reg. Date: 01/10/2014 (Man. Year: 2014)

Chassis No: YV3S4P927EA168232

Colour: Green

Odometer: 394307 km

Engine Capacity: 9364 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8/8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	740.00	740.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,460.00	2,580.00	3,880.00	60.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,200.00	3,320.00	3,880.00	53.89
+ GST 7.00/7.00% (S\$)	504.00	232.40	271.60	53.89
Nett Amount (S\$)	7,704.00	3,552.40	4,151.60	53.89
+ Loss of Use (4.0 x S\$350.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,954.40		
Global Sum Settlement (S\$)		4,900.00		

INSPECTION

Date of Assignment: 25/11/2019

Date Inspected: 25/11/2019 Inspected At:

Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S/F CORNER BUMPER	Cracked	390.00 F	*390.00 F
2	1		*N/S/F DEFLECTOR	Cracked	160.00 F	*160.00 F
3	1		*N/S/F LIGHT BAZEL	Cracked	190.00 F	*190.00 F
					Total Parts (\$)	740.00
						740.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACED PARTS	New	1,950.00	650.00
2	SPRAY PAINTING	New	2,560.00	1,280.00
3	TO REPAIR FRONT FIBER GLASS BODY PANEL AND PUTTY	New	1,950.00	650.00
			Gross Labour Cost (\$)	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >