

### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2003571

INV Date 29/04/2020

Reference CC6/CTI19020959/Aea3n2

Code CT



#### PROFESSIONAL SERVICE FEE

Vehicle No. SJK 2993U

Insured Veh. GT 7821M

Claim No. SNM19D205535

Policy No. DMCVSN3037101902

Accident Date 19/11/2019

Inspection Date 25/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
CHIN	A TAIPING INSURANCE (S) PTE LTD Ref : CC6/CTI19020959/Aea3n2					
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 29-04-2020 Code: CTI				
1.		Policy Particulars :	- THIRD PARTY CLAIM			
	Insured Veh.	GT 7821M	Veh. Inspected	SJK 2993U		
	Policy No.	DMCVSN3037101902	Coverage (\$)	0.00		
	Claim No.	SNM19D205535	Excess (\$)	0.00		
	Assign From		Assign Date	25/11/2019		
2.		Vehicle Partic	culars & Condition			
	Make & Model	HYUNDAI AVANTE	c.c	1591		
	Engine No.	HIDDEN	Year of Reg.	2008		
	Chassis No.	KMHDU41BR9U589297	Colour	SILVER		
	Odometer	150585	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	195/65 R15	LING LONG	6 mm		
	L/H Front Tyre	195/65 R15	LING LONG	6 mm		
	R/H Rear Tyre	195/65 R15	LING LONG	6 mm		
	L/H Rear Tyre	195/65 R15	LING LONG	6 mm		
4.	1. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT O/S PORTION.			
	DAMAGES SEE DI	ETAILS.				
5.		General	Information			
	Accident Date	19/11/2019	Inspection Date	25/11/2019		
	Survey held at	HUA MENG SPRAY PAINTING \	WORKSHOP			
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883				
5a.			emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5 Working Days			
	•		1			



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 2993U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	470.90	470.90
2	FRONT BUMPER SIDE HOLDER @\$46.20	NECESSARY	92.40	92.40
1	FRONT BUMPER RH FOG LAMP	CRACKED	172.50	172.50
1	FRONT BUMPER REINFORCEMENT	BENT	274.60	274.60
1	FRONT BUMPER SPONGE	NOT NECESSARY	121.70	-
1	FRONT BUMPER CENTRE LOWER GRILLE	NOT NECESSARY	76.80	-
1	FRONT GRILLE	NOT NECESSARY	385.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	41.80	-
1	FRONT RH HEADLAMP	CRACKED	532.00	532.00
2	FRONT RH HEADLAMP BLUBS @\$28.40	NOT NECESSARY	56.80	-
1	FRONT RH HEADLAMP LOWER GARNISH	NOT NECESSARY	41.80	-
1	FRONT RH FENDER	BUCKLED	436.40	436.40
1	FRONT RH FENDER INNER SHIELD	NOT NECESSARY	70.20	-
1	SET FRONT RH FENDER INNER SHIELD CLIPS	NOT NECESSARY	66.00	-
1	FRONT SUPPORT PANEL	CRACKED	829.00	829.00
	LESS 20% DISCOUNT		-733.58	-561.56
			2,934.32	2,246.24
	<u>LABOUR</u>			
	REMOVE & REINSTALL AIRCON FILL IN GAS.		150.00	120.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,400.00	600.00
	RESPRAY PAINTING.		1,300.00	600.00
	TUFF KOTE.	NOT NECESSARY	100.00	-
	-		-	-
	-		_	-
	-		-	-
			2,950.00	1,320.00
	GRAND TOTAL		5,884.32	3,566.24

DECOMMENDED COST OF LUMP SUM DEDAIDS	2 000 00
RECOMMENDED COST OF LUMP SUM REPAIRS	2,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC6/CTI19020959/Aea3n2





Report Ref No. CC6/CTI19020959/Aea3n2



**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.