



Case Details

Case Reference Number :
TAX/11/19/2094
Type of Repair : Accident Repair
Vehicle Registration Number :
SHC4612Y

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-9429-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
Accident Date and Time : 21/11/2019 09:00 AM
Vehicle Age(In Months) : 63

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation														
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	✓ DD
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓ N/C
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	✓ R

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by: _____
Signature: _____
Date: _____
Surveyor Approval

Total Spare Part Cost	4,137.04	Surveyor Total	641.47
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	3,309.63	Final Sur Total	513.18

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ NEC
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			MIRROR ASSY,LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	✓ SVC
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	✓ SVC

Total Spare Part Cost	4,137.04	Surveyor Total	641.47
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	3,309.63	Final Sur Total	513.16

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	200	✓
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER LH	378.00	200	✓
2	Main	TO RESPRAY RIM	180.00	0	
3	Main	TO RESPRAY FRONT DOOR LH	378.00	200	✓
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			896.88	296.88	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
7	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
Total:			896.88	296.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,309.63	513.18
Total Labour Cost	507.00	200.00
Total Spray Painting	936.00	400.00
Other	896.88	296.88
Overall Total	5,649.51	1,410.06
Lump Sum Repair Option		*
Lump Sum Total	5,650.00	1,400.00
Surveyor Approved Amount		1,400.00
No of Repair Days*	5	3
Remarks	-	Lump Sum repair, Take after spray photo.
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	25/11/2019	

Save Clear