

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19020962/R1KA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800095332

**Claimant**  
**Vehicle No :** SKQ550J **Insured Vehicle No :** SKA7617P

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: 0913557272SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKQ550J</b>		
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Engine No:	A3520677N20B20B
Reg. Date:	30/10/2014 (Man. Year: 2013)	Chassis No:	WBA5A32080D335210
Colour:	Grey	Odometer:	57625 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,516.50	4,339.15	3,177.35	42.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,346.00	3,818.00	1,528.00	28.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,862.50</b>	<b>8,157.15</b>	<b>4,705.35</b>	<b>36.58</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	900.38	571.00	329.38	36.58
<b>Nett Amount (\$\$)</b>	<b>13,762.88</b>	<b>8,728.15</b>	<b>5,034.73</b>	<b>36.58</b>
<b>+ Loss of Use (5.0 x S\$110.00/day) (\$\$)</b>		550.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>9,280.15</b>		

### INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 09/12/2019 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Serviceable	83.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
3	1		*BOOTLID	Bent	1,650.65 FS	*1,650.65 FS
4	1		*SET MOUNT PDC SENSOR REAR	Serviceable	58.90 FS	*- FS
5	1		*RR BUMPER CARRIER	Bent	775.95 FS	*775.95 FS
6	2		*PROTECTION FOIL L=55MM	Not Necessary	10.70 FS	*- FS
7	2		*PROTECTION FOIL L=55MM	Not Necessary	10.70 FS	*- FS
8	1		*ADAPTOR	Cracked	109.35 FS	*109.35 FS
9	1		*REAR BUMPER CENTRE GUIDE	Serviceable	67.45 FS	*- FS
10	1		*RR LH MOUNT	Serviceable	193.15 FS	*- FS
11	1		*RR RH MOUNT	Serviceable	193.15 FS	*- FS
12	1		*REAR BUMPER PRIMED (PDC)	Deformed	1,571.95 FS	*1,571.95 FS
13	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS
14	1		*MODEL LETTERING 520I	Necessary	64.45 FS	*64.45 FS
15	1		*BMW EMBLEM	Necessary	71.60 FS	*71.60 FS
16	1		*SPINDLE DRIVE RH	Serviceable	556.75 FS	*- FS
17	2		*STOP BUFFER	Serviceable	62.20 FS	*- FS
18	1		*TRIGGER CONTACT	Serviceable	135.95 FS	*- FS
19	1		*LOADING SILL COVER	Serviceable	116.15 FS	*- FS
20	1		*BOOTLID SEALING	Serviceable	115.25 FS	*- FS
21	2		*(S/L) RUBBER BUFFER	Serviceable	3.60 FS	*- FS
22	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.40 FS	*- FS
23	4		*BUMPER PDC SENSOR (A52 SPACEGRAU)	Serviceable	1,480.00 FS	*- FS
24	4		*EXPANDING NUT	Necessary	4.00 FS	*4.00 FS
25	10		*PLUG BLACK D=5MM	Necessary	9.50 FS	*9.50 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **7,516.50**      **4,339.15**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REPLACE REAR BOOT LID ,REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC AND REPAIR ON ACCIDENT AND REPAIR ON ACCIDENT DAMAGE AREA	New	2,978.00	1,700.00
2	SPRAY PAINTING REAR BOOT LID AND REAR BUMPER	New	2,076.00	1,868.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	115.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>5,346.00</b>	<b>3,818.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**