

ASS. REC. BY:

REF:

03/SPF/19020979/Gsd3⁵⁷

Special Instruction:

Surveyor: Chao Qiang

ASSIGNMENT (Office)

From (Person): Perry He

of

SPFDate/Time: 27/11/19 @ 9.11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 793S

Insured:

at Workshop m/s

Indeco

Tel:

9987 7084

of

39 Defu Lane 12

Policy No:

Claim No:

MHA 3PF 03 00000113

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:35am @ 27/11/19

Person Contacted:

MikeVehicle: IN / OUT

Date/Time	Action/Instruction
	<u>Schmidt</u> ✓
	<u>QX 793S - X</u>
<u>02/12/19</u>	<u>@ 14:02 pm revised & sent via to Perry via email</u>

ASS. REC. BY:

6ul.

REF: SPF

ASSIGNMENT

From:

Date:

27/11/19

Estimated Cost:

☒ OD / ☐ IP / ☐ S / TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

QX793S

at Workshop m/s

Indeco

of

301 Debn June 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

Mike @ 7787 7084

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

QX793S

Yr Regn:

- /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Police car h6

Make:

Hyundai Avante c.c 1591

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

110 881

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU 4 / BM AU 035686

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 / 65 R 15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

w/s

27-11-19

2:30 pm

Survey held at

Des. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

 Recommend Total loss due to chassis affected.
bent. unsafe to repair. Both

 Jimminto
11/12/2019

RECEIVED 12 DEC 2019

Date/Time, File Pass to?

12/12/19
Type 24

Date/Time, File Return to?

2)

Report Format:

Total Loss

Lump Sum / L.B.I. @

 A say after
don't close first,
send email to spf
then inform Shirley
A * wait for Shirley
say can close
the file just pass
to auditor to close
(urgent)

Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Shirley Hiew (LKK Auto)

From: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Sent: Tuesday, 10 December 2019 5:52 pm
To: Shirley Hiew (LKK Auto)
Cc: Kim Pang CHAY (HTX); Kwee Huat TAN (HTX); assignments; SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Hi Shirley,

Ok, pls email all documents, thanks.

Perry He Junyun

Contract Management Engineer (Land Systems – Vehicle)
Capability Sustainment
Home Team Science & Technology (Forward Deployed to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



eXponentially
impacting
Singapore's
safety and security_



Home Team Science & Technology Agency W htx.gov.sg FB fb.com/HTXSG IG Instagram.com/htx_sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 10 December 2019 5:46 PM
To: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Cc: Kim Pang CHAY (HTX) <CHAY_Kim_Pang@htx.gov.sg>; Kwee Huat TAN (HTX) <TAN_Kwee_Huat@htx.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Dear Perry,

Please advise whether can we submit our report of QX 793S accordingly.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Sent: Tuesday, 10 December 2019 5:44 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Kim Pang CHAY (HTX) <CHAY_Kim_Pang@htx.gov.sg>; Kwee Huat TAN (HTX) <TAN_Kwee_Huat@htx.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Hi Shirley,

Noted, pls provide the official letter on this stance.

Thanks.

Perry He Junyun

Contract Management Engineer (Land Systems – Vehicle)
Capability Sustainment
Home Team Science & Technology (Forward Deployed to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



eXponentially
impacting
Singapore's
safety and security_



Home Team Science & Technology Agency W htx.gov.sg FB fb.com/HTXSg IG Instagram.com/htx_sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 10 December 2019 5:34 PM
To: Perry HE (HTX) <Perry_HE@htx.gov.sg>
Cc: Kim Pang CHAY (HTX) <CHAY_Kim_Pang@htx.gov.sg>; Kwee Huat TAN (HTX) <TAN_Kwee_Huat@htx.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Dear Perry,

According to our surveyor, vehicle recommended total loss due to both chassis bent and unsafe to repair.

Kindly contact our surveyor, Guo Qiang @ 82880282 if further clarification is required.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (HTX) <Perry_HE@spf.gov.sg>

Sent: Wednesday, 4 December 2019 9:11 am

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Kim Pang CHAY (HTX) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (HTX) <TAN_Kwee_Huat@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Hi Shirley,

OK, do update us again as this is crucial to safety.

Thanks.

Perry He Junyun

Contract Management Engineer

Capability Sustainment

Home Team Science & Technology (Forward Deployment to SPF)

DID: (65) 6478 4869 | HP: (65) 9191 5725



eXponentially
impacting
Singapore's
safety and security_



Home Team Science & Technology Agency W htx.gov.sg FB fb.com/HTXSG IG Instagram.com/htx_sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Tuesday, 3 December 2019 4:52 PM

To: Perry HE (SPF) <Perry_HE@spf.gov.sg>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Dear Perry,

According to our surveyor, it's safe to repair unless chassis member need to change.

Our surveyor will resurvey chassis to determine it after workshop dismantle the damaged parts.

Kindly contact our surveyor, Guo Qiang @ 82880282 if further clarification is required.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>

Sent: Monday, 2 December 2019 3:21 pm

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Hi Shirley,

Noted, pls update us again.

Do update us too whether this car is safe to repair.

Perry He Junyun

Contract Management Engineer

Capability Sustainment, MHA STG (Forward Deployment to SPF)

DID: (65) 6478 4869 | HP: (65) 9191 5725



eXponentially
impacting
Singapore's
safety and security_



Home Team Science & Technology Agency W htx.gov.sg FB fb.com/HTXSG IG Instagram.com/htx_sg

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Monday, 2 December 2019 2:08 PM

To: Perry HE (SPF) <Perry_HE@spf.gov.sg>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Dear Perry,

Please refer attached.

The unconfirm items we will update you after the resurvey conduct.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Wednesday, 27 November 2019 9:37 am

To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>

Subject: RE: Appraisal Services for SPF vehicle at INDECO - QX793S

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]

Sent: Wednesday, 27 November 2019 9:11 AM

To: 'assignments' <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>

Subject: Appraisal Services for SPF vehicle at INDECO - QX793S

Hi Catherine and Ashley,

Nivitha (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 27 November 2019 9:11 AM
To: 'assignments'
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); 'Denise Tay (LKKAuto)'
Subject: Appraisal Services for SPF vehicle at INDECO - QX7935

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contractual rate.

Ref: MHASPF0300000113

Pls also advise whether this vehicle is structurally safe to repair.

QX7935

Parts:

- 1.1 BONNET
- 1.2 BONNET HINGE RH
- 1.3 BONNET HINGE LH
- 1.4 BONNET LOCK
- 1.5 BONNET INSULATOR
- 1.6 BONNET INSLATOR CLIP
- 1.7 BONNET RUBBER STRIP
- 1.8 SUPPORT PANEL
- 1.9 HEADLAMP LH
- 1.10 HEADLAMP RH
- 1.11 LH CHASSIS ASSY
- 1.12 FRT BUMPER
- 1.13 FRT BUMPER RETAINER RH
- 1.14 FRT BUMPER RETAINER LH
- 1.15 FRT BUMPER BRACKET RH
- 1.16 FRT BUMPER BRACKET LH
- 1.17 FRT BUMPER CLIP
- 1.18 FRT BUMPER REINFORCEMENT
- 1.19 FRT BUMPER REINFORCEMENT BRACKET RH WITH 1.18
- 1.20 FRT BUMPER REINFORCEMENT BRACKET LH WITH 1.18
- 1.21 FRT BUMPER SPONGE
- 1.22 FRT BUMPER LOWER GRILLE
- 1.23 FOGLAMP COVER RH
- 1.24 FOGLAMP COVER LH
- 1.25 FRT BUMPER LOWER LIP
- 1.26 FRT GRILLE COMPLETE ASSY
- 1.27 LHF FENDER
- 1.28 RHF FENDER
- 1.29 LHF FENDER INNER SHILED
- 1.30 RHF FENDER INNER SHIELD
- 1.31 FENDER INNER SHILED CLIPS
- 1.32 ENGINE UNDER COVER ASSY
- 1.33 ENGINE UNDER COVER CLIPS
- 1.34 ENGINE CROSS MEMBER COMPLETE 62405-2H100
- 1.35 RHF S/ABSORBER

1.36	RHF S/ABSORBER TOP MOUNTING
1.37	RHF LOWER ARM
1.38	RHF LOWER ARM BALL JOINT
1.39	RHF KNUCKLE ARM
1.40	RHF WHEEL HUB
1.41	RHF WHEEL HUB BEARING
1.42	RHF ANTI ROLL BAR LINK
1.43	RHF TIE ROD
1.44	RHF TIE ROD END
1.45	LHF S/ABSORBER
1.46	LHF S/ABSORBER TOP MOUNTING
1.47	LHF LOWER ARM
1.48	LHF LOWER ARM BALL JOINT
1.49	LHF KNUCKLE ARM
1.50	LHF WHEEL HUB
1.51	LHF WHEEL HUB BEARING
1.52	LHF ANTI ROLL BAR LINK
1.53	LHF TIE ROD
1.54	LHF TIE ROD END
1.55	ENGINE CROSS MEMBER STAY LH 62476-2H000
1.56	ENGINE CROSS MEMBER STAY RH 62477-2H000
1.57	ANTI ROLL BAR
1.58	STEERING RACK 56500-2H290
1.59	AIR CLEANER DUCT ASSY 28210-2H000
1.60	AIR CLEANER ASSY 28111-2H000
1.61	AIR CLEANER HOSE ASSY 8130-2H000
1.62	ALTERNATOR 37300-2B101
1.63	BATTERY SOR 5A 12V 65AH
1.64	BATTERY TRAY
1.65	ENGINE 109N1-2BU00
1.66	INTAKE MANI FOLD
1.67	ENGINE VALVE COVER
1.68	RADIATOR
1.69	RADIATOR TOP MOUNTING
1.70	RADIATOR BOTTOMMOUNTING
1.71	RADIATOR FAN ASSY
1.72	RADIATOR TOP HOSE
1.73	RADIATOR BOTTOM HOSE
1.74	CONDENSOR
1.75	AC RECEIVE PIPE
1.76	AC DISCHARGE HOSE
1.77	COMPRESSOR
1.78	HEATER PIPE 25457-2B000
1.79	COOLANT INLET 25631-2B001
1.80	SUCTION & LIQUID HOSE 97775-2L000 (WITH 75)
1.81	ENGINE MOUNTING RH
1.82	ENGINE MOUNTING BRACKET RH
1.83	ENGINE MOUNTING FRONT
1.84	ENGINE MOUNTING REAR
1.85	GEARBOX MOUNTING
1.86	ENGINE MOUNTING BOLT 21920-2E100
1.87	ENGINE MOUNTING BOLT21920-2G846K
1.88	DRIVER AIR BAG
1.89	CLOCK SPRING
1.90	DASHBOARD
1.91	PASSENGER AIRBAG

- 1.92 AIRBAG ECU
- 1.93 SEATBELT RH
- 1.94 SEATBELT LH
- 1.95 FRT WINDSCREEN
- 1.96 FRT WINDSCREEN MOULDING
- 1.97 INNER SEAL TAPE
- 1.98 IU STICKER
- 1.99 SEALANT
- 1.100 FRT NUMBER PLATE

Labour (Hrs)

TO REPLACE AND RESPRAY BONNET
TO REPLACE SUPPORT PANEL
TO REPLACE AND RESPRAY FRT BUMPER
TO REPLACE AND RESPRAY LHF FENDER
TO REPLACE AND RESPRAY RHF FENDER
TO REMOVE AND REFIX CONDENSER, RADIATOR AND TOP UP AC GAS
TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK
TO ALIGN, REPLACE AND RESPRAY RH/LH CHASSIS
TO REPLACE FRT UNDER CARRIAGE PARTS
TO PERFORM 4 WHEEL ALIGNMENT
TO ALIGN, REPLACE AND RESPRAY REINFORCEMENT
TO REPLACE DASHBOARD
TO REPLACE FRONT WINDSCREEN

Thanks.

Perry He Junyun
Contract Management Engineer
Capability Sustainment, MHA STG (Forward Deployment to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error.

It's safe to repair unless chassis member need to change.
I will resurvey chassis to determine it after
workshop dismantle the damaged parts. Anson will
arrange resurvey ~~dismant~~ for me.



SCOPE OF WORK

I To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	MARINA BAY	Reference No. MHA/SPF/2019/11-0028 1100038838
VEH NO :	QX 793 S	FRC	REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL:	HYUNDAI AVANTE		Mileage:	110881	

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	BONNET / <i>mc</i>	130.00	1	20%	156.00	156.00
1.2	BONNET HINGE RH / <i>BT</i>	25.00	1	20%	30.00	30.00
1.3	BONNET HINGE LH / <i>BT</i>	25.00	1	20%	30.00	30.00
1.4	BONNET LOCK / <i>mc</i>	25.00	1	20%	30.00	30.00
1.5	BONNET INSULATOR / <i>mc</i>	85.00	1	20%	102.00	102.00
1.6	BONNET INSULATOR CLIP / <i>mc</i>	2.00	10	20%	2.40	24.00
1.7	BONNET RUBBER STRIP / <i>mc</i>	18.00	1	20%	21.60	21.60
1.8	SUPPORT PANEL / <i>mc</i>	110.00	1	20%	132.00	132.00
1.9	HEADLAMP LH / <i>mc</i>	180.00	1	20%	216.00	216.00
1.10	HEADLAMP RH / <i>mc</i>	180.00	1	20%	216.00	216.00
1.11	LH CHASSIS ASSY / <i>mc</i>	680.00	1	20%	816.00	816.00
1.12	FRT BUMPER / <i>mc</i>	95.00	1	20%	114.00	114.00
1.13	FRT BUMPER RETAINER RH / <i>mc</i>	18.00	1	20%	21.60	21.60
1.14	FRT BUMPER RETAINER LH / <i>mc</i>	18.00	1	20%	21.60	21.60
1.15	FRT BUMPER BRACKET RH / <i>mc</i>	26.00	1	20%	31.20	31.20
1.16	FRT BUMPER BRACKET LH / <i>mc</i>	26.00	1	20%	31.20	31.20
1.17	FRT BUMPER CLIP / <i>mc</i>	1.50	10	20%	1.80	18.00
1.18	FRT BUMPER REINFORCEMENT / <i>mc</i>	65.00	1	20%	78.00	78.00
1.19	FRT BUMPER REINFORCEMENT BRACKET RH WITH 1.18 ?	0.00	1	0%	0.00	0.00
1.20	FRT BUMPER REINFORCEMENT BRACKET LH WITH 1.18 ?	0.00	1	0%	0.00	0.00
1.21	FRT BUMPER SPONGE / <i>mc</i>	70.00	1	20%	84.00	84.00
1.22	FRT BUMPER LOWER GRILLE / <i>mc</i>	30.00	1	20%	36.00	36.00
1.23	FOGLAMP COVER RH / <i>mc</i>	25.00	1	20%	30.00	30.00
1.24	FOGLAMP COVER LH / <i>mc</i>	25.00	1	20%	30.00	30.00
1.25	FRT BUMPER LOWER LIP / <i>mc</i>	25.00	1	20%	30.00	30.00
1.26	FRT GRILLE COMPLETE ASSY / <i>mc</i>	290.00	1	20%	348.00	348.00
1.27	LHF FENDER / <i>mc</i>	60.00	1	20%	72.00	72.00
1.28	RHF FENDER / <i>mc</i>	60.00	1	20%	72.00	72.00
1.29	LHF FENDER INNER SHIELD / <i>mc</i>	35.00	1	20%	42.00	42.00
1.30	RHF FENDER INNER SHIELD / <i>mc</i>	35.00	1	20%	42.00	42.00
1.31	FENDER INNER SHIELD CLIPS / <i>mc</i>	1.50	12	20%	1.80	21.60
1.32	ENGINE UNDER COVER ASSY / <i>mc</i>	35.00	1	20%	42.00	42.00
1.33	ENGINE UNDER COVER CLIPS / <i>mc</i>	1.50	10	20%	1.80	18.00
1.34	ENGINE CROSS MEMBER COMPLETE 62405-2H100 ?	950.00	1	20%	1140.00	1140.00
1.35	RHF S/ABSORBER / <i>mc</i>	140.00	1	20%	168.00	168.00
1.36	RHF S/ABSORBER TOP MOUNTING / <i>mc</i>	40.00	1	20%	48.00	48.00
1.37	RHF LOWER ARM / <i>mc</i>	65.00	1	20%	78.00	78.00
1.38	RHF LOWER ARM BALL JOINT / <i>mc</i>	38.00	1	20%	45.60	45.60
1.39	RHF KNUCKLE ARM / <i>mc</i>	155.00	1	20%	186.00	186.00
1.40	RHF WHEEL HUB / <i>mc</i>	90.00	1	20%	108.00	108.00
1.41	RHF WHEEL HUB BEARING / <i>mc</i>	50.00	1	20%	60.00	60.00
1.42	RHF ANTI ROLL BAR LINK / <i>mc</i>	20.00	1	20%	24.00	24.00
1.43	RHF TIE ROD / <i>mc</i>	46.00	1	20%	55.20	55.20
1.44	RHF TIE ROD END / <i>mc</i>	45.00	1	20%	54.00	54.00
1.45	LHF S/ABSORBER / <i>mc</i>	140.00	1	20%	168.00	168.00
1.46	LHF S/ABSORBER TOP MOUNTING / <i>mc</i>	40.00	1	20%	48.00	48.00
1.47	LHF LOWER ARM / <i>mc</i>	65.00	1	20%	78.00	78.00
1.48	LHF LOWER ARM BALL JOINT / <i>mc</i>	38.00	1	20%	45.60	45.60
1.49	LHF KNUCKLE ARM / <i>mc</i>	155.00	1	20%	186.00	186.00
1.50	LHF WHEEL HUB / <i>mc</i>	90.00	1	20%	108.00	108.00
1.51	LHF WHEEL HUB BEARING / <i>mc</i>	50.00	1	20%	60.00	60.00
1.52	LHF ANTI ROLL BAR LINK / <i>mc</i>	20.00	1	20%	24.00	24.00
1.53	LHF TIE ROD / <i>mc</i>	46.00	1	20%	55.20	55.20
1.54	LHF TIE ROD END / <i>mc</i>	45.00	1	20%	54.00	54.00
1.55	ENGINE CROSS MEMBER STAY LH 62476-2H000 ?	55.00	1	20%	66.00	66.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO REPLACE AND RESPRAY BONNET	61.80	6	370.80
1.2	TO REPLACE SUPPORT PANEL	61.80	2	123.60
1.3	TO REPLACE AND RESPRAY FRT BUMPER	61.80	5	309.00
1.4	TO REPLACE AND RESPRAY LHF FENDER	61.80	4	247.20
1.5	TO REPLACE AND RESPRAY RH FENDER	61.80	4	247.20
1.6	TO REMOVE AND REFIX CONDENSER,RADIATOR AND TOP UP AC GAS	61.80	2	123.60
1.7	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK	61.80	10	618.00
1.8	TO ALIGN,REPLACE AND RESPRAY RH/LH CHASSIS	61.80	20	1236.00
1.9	TO REPLACE FRT UNDER CARRIAGE PARTS	61.80	4	247.20
1.10	TO PERFORM 4 WHEEL ALIGNMENT	61.80	1	61.80
1.11	TO ALIGN,REPLACE AND RESPRAY REINFORCEMENT	61.80	1	61.80
1.12	TO REPLACE DASHBOARD	61.80	4	247.20
1.13	TO REPLACE FRONT WINDSCREEN	61.80	4	247.20
			67	
2	Additional Services			
		Labour Total:	\$	4,140.60
		GRAND TOTAL :	\$	49,895.52

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	RAZALI B. NAWI Technical Officer	Name:		Name:	
Date:	27/11/2018	Date:		Date:	
Sign:		Sign:		Sign:	
					
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager /		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

Date:

Not Authorised.

before & After paint photos.

Guo Qiang - 82880282
(UK)

27/4/19.



25/11

ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

ILMS Notification No	1100038838		
Vehicle No	QX793S	Division/Unit	A/MB NPC
Vehicle Type (e.g. FRC, minibus)	FRC	Date	24/11/19
Vehicle Make & Model	Hyundai Avante	Mileage (km)	




Description	Pls tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)		
NP168 (Accident do not involve 3 rd Party)	✓	T/20191124/2078
NP299 Discovered Damage		
NP299 Vandalism		
Ad hoc, pls specify		

Description of affected area/required works (e.g. dented, cracked, grazed etc)

Front bumper and hood badly damaged/caved in.

Airbags deployed because of collision.

Pls mark affected area with



Rank/Name: SSS M.Habeebulla (AO MB NPC)

Signature

[Handwritten Signature]

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BONNET	1	BUCKLED	\$156.00	\$156.00	
1.2	BONNET HINGE RH	1	BENT	\$30.00	\$30.00	
1.3	BONNET HINGE LH	1	BENT	\$30.00	\$30.00	
1.4	BONNET LOCK	1	BENT	\$30.00	\$30.00	
1.5	BONNET INSULATOR	1	DEFORMED	\$102.00	\$102.00	
1.6	BONNET INSULATOR CLIP	10	NECESSARY	\$2.40	\$24.00	
1.7	BONNET RUBBER STRIP	1	TWISTED	\$21.60	\$21.60	
1.8	SUPPORT PANEL	1	DISTORTED	\$132.00	\$132.00	
1.9	HEADLAMP LH	1	BROKEN	\$216.00	\$216.00	
1.10	HEADLAMP RH	1	MISSING	\$216.00	\$216.00	
1.11	LH CHASSIS ASSY	1	REPAIR	\$816.00	\$0.00	
1.12	FRONT BUMPER	1	DISTORTED	\$114.00	\$114.00	
1.13	FRONT BUMPER RETAINER RH	1	DEFORMED	\$21.60	\$21.60	
1.14	FRONT BUMPER RETAINER LH	1	DEFORMED	\$21.60	\$21.60	
1.15	FRONT BUMPER BRACKET RH	1	BENT	\$31.20	\$31.20	
1.16	FRONT BUMPER BRACKET LH	1	NOT NECESSARY	\$31.20	\$0.00	
1.17	FRONT BUMPER CLIP	10	NECESSARY	\$1.80	\$18.00	
1.18	FRONT BUMPER REINFORCEMENT	1	BENT	\$78.00	\$78.00	
1.19	FRONT BUMPER REINFORCEMENT BRACKET RH WITH 1.18	0	UNCONFIRM	\$0.00	\$0.00	
1.20	FRONT BUMPER REINFORCEMENT BRACKET LH WITH 1.18	0	UNCONFIRM	\$0.00	\$0.00	
1.21	FRONT BUMPER SPONGE	1	CRACKED	\$84.00	\$84.00	
1.22	FRONT BUMPER LOWER GRILLE	1	DISTORTED	\$36.00	\$36.00	
1.23	FOGLAMP COVER RH	1	MISSING	\$30.00	\$30.00	
1.24	FOGLAMP COVER LH	1	SCRATCHED	\$30.00	\$30.00	
1.25	FRONT BUMPER LOWER LIP	1	DEFORMED	\$30.00	\$30.00	
1.26	FRONT GRILLE COMPLETE ASSY	1	DISTORTED	\$348.00	\$348.00	
1.27	LHF FENDER	1	REPAIR	\$72.00	\$0.00	
1.28	RHF FENDER	1	REPAIR	\$72.00	\$0.00	
1.29	LHF FENDER INNER SHIELD	1	DEFORMED	\$42.00	\$42.00	
1.3	RHF FENDER INNER SHIELD	1	DEFORMED	\$42.00	\$42.00	
1.31	FENDER INNER SHIELD CLIPS	12	NECESSARY	\$1.80	\$21.60	
1.32	ENGINE UNDER COVER ASSY	1	MISSING	\$42.00	\$42.00	
1.33	ENGINE UNDER COVER CLIPS	10	NECESSARY	\$1.80	\$18.00	
1.34	ENGINE CROSS MEMBER COMPLETE 62405-2H100	1	UNCONFIRM	\$1,140.00	\$1,140.00	
1.35	RHF S/ABSORBER	1	UNCONFIRM	\$168.00	\$168.00	
1.36	RHF S/ABSORBER TOP MOUNTING	1	UNCONFIRM	\$48.00	\$48.00	
1.37	RHF LOWER ARM	1	UNCONFIRM	\$78.00	\$78.00	
1.38	RHF LOWER ARM BALL JOINT	1	UNCONFIRM	\$45.60	\$45.60	
1.39	RHF KNUCKLE ARM	1	UNCONFIRM	\$186.00	\$186.00	
1.4	RHF WHEEL HUB	1	UNCONFIRM	\$108.00	\$108.00	
1.41	RHF WHEEL HUB BEARING	1	UNCONFIRM	\$60.00	\$60.00	
1.42	RHF ANTI ROLL BAR LINK	1	NOT NECESSARY	\$24.00	\$0.00	
1.43	RHF TIE ROD	1	NOT NECESSARY	\$55.20	\$0.00	
1.44	RHF TIR ROAD END	1	NOT NECESSARY	\$54.00	\$0.00	
1.45	LHF S/ABSORBER	1	UNCONFIRM	\$168.00	\$168.00	
1.46	LHF S/ABSORBER TOP MOUNTING	1	UNCONFIRM	\$48.00	\$48.00	
1.47	LHF LOWER ARM	1	UNCONFIRM	\$78.00	\$78.00	
1.48	LHF LOWER ARM BALL JOINT	1	UNCONFIRM	\$45.60	\$45.60	
1.49	LHF KNUCKLE ARM	1	UNCONFIRM	\$186.00	\$186.00	
1.5	LHF WHEEL HUB	1	UNCONFIRM	\$108.00	\$108.00	
1.51	LHF WHEEL HUB BEARING	1	UNCONFIRM	\$60.00	\$60.00	
1.52	LHF ANTI ROLL BAR LINK	1	NOT NECESSARY	\$24.00	\$0.00	
1.53	LHF TIE ROD	1	NOT NECESSARY	\$55.20	\$0.00	
1.54	LHF TIE ROD END	1	NOT NECESSARY	\$54.00	\$0.00	
1.55	ENGINE CROSS MEMBER STAY LH 62476-2H000	1	UNCONFIRM	\$66.00	\$66.00	
1.56	ENGINE CROSS MEMBER STAY RH 62477-2H000	1	UNCONFIRM	\$66.00	\$66.00	
1.57	ANTI ROLL BAR	1	NOT NECESSARY	\$186.00	\$0.00	
1.58	STEERING RACK 56500-2H290	1	NOT NECESSARY	\$54.00	\$0.00	
1.59	AIR CLEANER DUCT ASSY 28210-2H000	1	UNCONFIRM	\$72.00	\$72.00	
1.6	AIR CLEANER ASSY 28111-2H000	1	UNCONFIRM	\$90.00	\$90.00	
1.61	AIR CLEANER HOSE ASSY 8130-2H000	1	UNCONFIRM	\$138.00	\$138.00	
1.62	ALTERNATOR 37300-2B101	1	UNCONFIRM	\$354.00	\$354.00	
1.63	BATTERY SOR SA 12V 65AH	1	UNCONFIRM	\$112.92	\$112.92	
1.64	BATTERY TRAY	1	UNCONFIRM	\$26.40	\$26.40	
1.65	ENGINE 109N1-2B000	1	UNCONFIRM	\$27,600.00	\$27,600.00	
1.66	INTAKE MANI FOLD	1	UNCONFIRM	\$336.00	\$336.00	
1.67	ENGINE VALVE COVER	1	UNCONFIRM	\$336.00	\$336.00	
1.68	RADIATOR	1	BENT	\$312.00	\$312.00	
1.69	RADIATOR TOP MOUNTING	1	BENT	\$18.00	\$18.00	
1.7	RADIATOR BOTTOM MOUNTING	1	BENT	\$12.00	\$12.00	
1.71	RADIATOR FAN ASSY	1	UNCONFIRM	\$150.00	\$150.00	

1.72	RADIATOR TOP HOSE	1	UNCONFIRM	\$33.60	\$33.60	
1.73	RADIATOR BOTTOM HOSE	1	UNCONFIRM	\$33.60	\$33.60	
1.74	CONDENSOR	1	BENT	\$222.00	\$222.00	
1.75	AC RECEIVE PIPE	1	UNCONFIRM	\$234.00	\$234.00	
1.76	AC DISCHARGE HOSE	1	UNCONFIRM	\$138.00	\$138.00	
1.77	COMPRESSOR	1	UNCONFIRM	\$384.00	\$384.00	
1.78	HEATER PIPE 25457-2B000	1	UNCONFIRM	\$57.60	\$57.60	
1.79	COOLANT INLET 25631-2B001	1	UNCONFIRM	\$33.60	\$33.60	
1.8	SUCTION & LIQUARD HOSE 97775-2L000 (WITH 75)	1	UNCONFIRM	\$0.00	\$0.00	
1.81	ENGINE MOUNTING RH	1	UNCONFIRM	\$126.00	\$126.00	
1.82	ENGINE MOUNTING BRACKET RH	1	UNCONFIRM	\$162.00	\$162.00	
1.83	ENGINE MOUNTING FRONT	1	UNCONFIRM	\$90.00	\$90.00	
1.84	ENGINE MOUNTING REAR	1	UNCONFIRM	\$90.00	\$90.00	
1.85	GEARBOX MOUNTING	1	UNCONFIRM	\$120.00	\$120.00	
1.86	ENGINE MOUNTING BOLT 21920-2E100	2	UNCONFIRM	\$36.00	\$72.00	
1.87	ENGINE MOUNTING BOLT T21920-2G846K	2	UNCONFIRM	\$21.60	\$43.20	
1.88	DRIVER AIR BAG	1	ACTIVATED	\$1,500.00	\$1,500.00	
1.89	CLOCK SPRING	1	ACTIVATED	\$234.00	\$234.00	
1.9	DASHBOARD	1	ACTIVATED	\$1,332.00	\$1,332.00	
1.91	PASSENGER AIRBAG	1	ACTIVATED	\$1,800.00	\$1,800.00	
1.92	AIRBAG ECU	1	ACTIVATED	\$696.00	\$696.00	
1.93	SEATBELT RH	1	ACTIVATED	\$660.00	\$660.00	
1.94	SEATBELT LH	1	ACTIVATED	\$660.00	\$660.00	
1.95	FRONT WINDSCREEN	1	CRACKED	\$696.00	\$696.00	
1.96	FRONTWINDSCREEN MOULDING	1	NECESSARY	\$54.00	\$54.00	
1.97	INNER SEAL TAPE	1	NECESSARY	\$36.00	\$36.00	
1.98	IU STICKER	1	NECESSARY	\$3.60	\$3.60	
1.99	SEALANT	2	NECESSARY	\$24.00	\$48.00	
1.100	FRONT NUMBER PLATE	1	CRACKED	\$24.00	\$24.00	
2	SCOPE OF REPAIRS					
2.1	TO REPLACE AND RESPRAY BONNET					6
2.2	TO REPLACE SUPPORT PANEL					2
2.3	TO REPLACE AND RESPRAY FRT BUMPER					5
2.4	TO REPLACE AND RESPRAY LHF BUMPER					4
2.5	TO REPLACE AND RESPRAY RHF BUMPER					4
2.6	TO REMOVE AND REFIX CONDENSER, RADIATOR AND TOP UP AC GAS					2
2.7	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK					10
2.8	TO ALIGN, REPLACE AND RESPRAY RH/LH CHASSIS					20
2.9	TO REPLACE FRT UNDER CARRIAGE PARTS					4
3	TO PERFORM 4 WHEEL ALIGNMENT					1
3.1	TO ALIGN, REPLACE AND RESPRAY REINFORCEMENT					1
3.2	TO REPLACE DASHBOARD					4
	TO REPLACE FRONT WINDSCREEN					4
		TOTAL PARTS COST			\$43,765.32	
		TOTAL MAN-HOUR				67



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. QX 793S

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BONNET	1	BUCKLED	\$156.00	\$156.00	
1.2	BONNET HINGE RH	1	BENT	\$30.00	\$30.00	
1.3	BONNET HINGE LH	1	BENT	\$30.00	\$30.00	
1.4	BONNET LOCK	1	BENT	\$30.00	\$30.00	
1.5	BONNET INSULATOR	1	DEFORMED	\$102.00	\$102.00	
1.6	BONNET INSULATOR CLIP	10	NECESSARY	\$2.40	\$24.00	
1.7	BONNET RUBBER STRIP	1	TWISTED	\$21.60	\$21.60	
1.8	SUPPORT PANEL	1	DISTORTED	\$132.00	\$132.00	
1.9	HEADLAMP LH	1	BROKEN	\$216.00	\$216.00	
1.10	HEADLAMP RH	1	MISSING	\$216.00	\$216.00	
1.11	LH CHASSIS ASSY	1	REPAIR	\$816.00		
1.12	FRONT BUMPER	1	DISTORTED	\$114.00	\$114.00	
1.13	FRONT BUMPER RETAINER RH	1	DEFORMED	\$21.60	\$21.60	
1.14	FRONT BUMPER RETAINER LH	1	DEFORMED	\$21.60	\$21.60	
1.15	FRONT BUMPER BRACKET RH	1	BENT	\$31.20	\$31.20	
1.16	FRONT BUMPER BRACKET LH	1	NOT NECESSARY	\$31.20		
1.17	FRONT BUMPER CLIP	10	NECESSARY	\$1.80	\$18.00	
1.18	FRONT BUMPER REINFORCEMENT	1	BENT	\$78.00	\$78.00	
1.19	FRONT BUMPER REINFORCEMENT BRACKET RH WITH 1.18	0	UNCONFIRM	\$0.00	\$0.00	
1.20	FRONT BUMPER REINFORCEMENT BRACKET LH WITH 1.18	0	UNCONFIRM	\$0.00	\$0.00	
1.21	FRONT BUMPER SPONGE	1	CRACKED	\$84.00	\$84.00	
1.22	FRONT BUMPER LOWER GRILLE	1	DISTORED	\$36.00	\$36.00	
1.23	FOGLAMP COVER RH	1	MISSING	\$30.00	\$30.00	
1.24	FOGLAMP COVER LH	1	SCRATCHED	\$30.00	\$30.00	
1.25	FRONT BUMPER LOWER LIP	1	DEFORMED	\$30.00	\$30.00	
1.26	FRONT GRILLE COMPLETE ASSY	1	DISTORTED	\$348.00	\$348.00	
1.27	LHF FENDER	1	REPAIR	\$72.00		
1.28	RHF FENDER	1	REPAIR	\$72.00		

1.29	LHF FENDER INNER SHILED	1	DEFORMED	\$42.00	\$42.00	
1.3	RHF FENDER INNER SHIELD	1	DEFORMED	\$42.00	\$42.00	
1.31	FENDER INNER SHILED CLIPS	12	NECESSARY	\$1.80	\$21.60	
1.32	ENGINE UNDER COVER ASSY	1	MISSING	\$42.00	\$42.00	
1.33	ENGINE UNDER COVER CLIPS	10	NECESSARY	\$1.80	\$18.00	
1.34	ENGINE CROSS MEMBER COMPLETE 62405-2H100	1	UNCONFIRM	\$1,140.00	\$1,140.00	
1.35	RHF S/ABSORBER	1	UNCONFIRM	\$168.00	\$168.00	
1.36	RHF S/ABSORBER TOP MOUNTING	1	UNCONFIRM	\$48.00	\$48.00	
1.37	RHF LOWER ARM	1	UNCONFIRM	\$78.00	\$78.00	
1.38	RHF LOWER ARM BALL JOINT	1	UNCONFIRM	\$45.60	\$45.60	
1.39	RHF KNUCKLE ARM	1	UNCONFIRM	\$186.00	\$186.00	
1.4	RHF WHEEL HUB	1	UNCONFIRM	\$108.00	\$108.00	
1.41	RHF WHEEL HUB BEARING	1	UNCONFIRM	\$60.00	\$60.00	
1.42	RHF ANTI ROLL BAR LINK	1	NOT NECESSARY	\$24.00		
1.43	RHF TIE ROD	1	NOT NECESSARY	\$55.20		
1.44	RHF TIR ROAD END	1	NOT NECESSARY	\$54.00		
1.45	LHF S/ABSORBER	1	UNCONFIRM	\$168.00	\$168.00	
1.46	LHF S/ABSORBER TOP MOUNTING	1	UNCONFIRM	\$48.00	\$48.00	
1.47	LHF LOWER ARM	1	UNCONFIRM	\$78.00	\$78.00	
1.48	LHF LOWER ARM BALL JOINT	1	UNCONFIRM	\$45.60	\$45.60	
1.49	LHF KNUCKLE ARM	1	UNCONFIRM	\$186.00	\$186.00	
1.5	LHF WHEEL HUB	1	UNCONFIRM	\$108.00	\$108.00	
1.51	LHF WHEEL HUB BEARING	1	UNCONFIRM	\$60.00	\$60.00	
1.52	LHF ANTI ROLL BAR LINK	1	NOT NECESSARY	\$24.00		
1.53	LHF TIE ROD	1	NOT NECESSARY	\$55.20		
1.54	LHF TIE ROD END	1	NOT NECESSARY	\$54.00		
1.55	ENGINE CROSS MEMBER STAY LH 62476-2H000	1	UNCONFIRM	\$66.00	\$66.00	
1.56	ENGINE CORSS MEMBER STAY RH 62477-2H000	1	UNCONFIRM	\$66.00	\$66.00	
1.57	ANTI ROLL BAR	1	NOT NECESSARY	\$186.00		
1.58	STEERING RACK 56500-2H290	1	NOT NECESSARY	\$546.00		
1.59	AIR CLEANER DUCT ASSY 28210-2H000	1	UNCONFIRM	\$72.00	\$72.00	
1.6	AIR CLEANER ASSY 28111-2H000	1	UNCONFIRM	\$90.00	\$90.00	
1.61	AIR CLEANER HOSE ASSY 8130-2H000	1	UNCONFIRM	\$138.00	\$138.00	
1.62	ALTERNATOR 37300-2B101	1	UNCONFIRM	\$354.00	\$354.00	
1.63	BATTERY SOR 5A 12V 65AH	1	UNCONFIRM	\$112.92	\$112.92	
1.64	BATTERY TRAY	1	UNCONFIRM	\$26.40	\$26.40	
1.65	ENGINE 109N1-2BU00	1	UNCONFIRM	\$27,600.00	\$27,600.00	
1.66	INTAKE MANI FOLD	1	UNCONFIRM	\$336.00	\$336.00	
1.67	ENGINE VALVE COVER	1	UNCONFIRM	\$336.00	\$336.00	
1.68	RADIATOR	1	BENT	\$312.00	\$312.00	

1.69	RADIATOR TOP MOUNTING	1	BENT	\$18.00	\$18.00	
1.7	RADIATOR BOTTOM MOUNTING	1	BENT	\$12.00	\$12.00	
1.71	RADIATOR FAN ASSY	1	UNCONFIRM	\$150.00	\$150.00	
1.72	RADIATOR TOP HOSE	1	UNCONFIRM	\$33.60	\$33.60	
1.73	RADIATOR BOTTOM HOSE	1	UNCONFIRM	\$33.60	\$33.60	
1.74	CONDENSOR	1	BENT	\$222.00	\$222.00	
1.75	AC RECEIVE PIPE	1	UNCONFIRM	\$234.00	\$234.00	
1.76	AC DISCHARGE HOSE	1	UNCONFIRM	\$138.00	\$138.00	
1.77	COMPRESSOR	1	UNCONFIRM	\$384.00	\$384.00	
1.78	HEATER PIPE 25457-2B000	1	UNCONFIRM	\$57.60	\$57.60	
1.79	COOLANT INLET 25631-2B001	1	UNCONFIRM	\$33.60	\$33.60	
1.8	SUCTION & LIQUARD HOSE 97775-2L000 (WITH 75)	1	UNCONFIRM	\$0.00	\$0.00	
1.81	ENGINE MOUNTING RH	1	UNCONFIRM	\$126.00	\$126.00	
1.82	ENGINE MOUNTING BRACKET RH	1	UNCONFIRM	\$162.00	\$162.00	
1.83	ENGINE MOUNTING FRONT	1	UNCONFIRM	\$90.00	\$90.00	
1.84	ENGINE MOUNTING REAR	1	UNCONFIRM	\$90.00	\$90.00	
1.85	GEARBOX MOUNTING	1	UNCONFIRM	\$120.00	\$120.00	
1.86	ENGINE MOUTNING BOLT 21920-2E100	2	UNCONFIRM	\$36.00	\$72.00	
1.87	ENGINE MOUNTING BOLT T21920-2G846K	2	UNCONFIRM	\$21.60	\$43.20	
1.88	DRIVER AIR BAG	1	ACTIVATED	\$1,500.00	\$1,500.00	
1.89	CLOCK SPRING	1	ACTIVATED	\$234.00	\$234.00	
1.9	DASHBOARD	1	ACTIVATED	\$1,332.00	\$1,332.00	
1.91	PASSENGER AIRBAG	1	ACTIVATED	\$1,800.00	\$1,800.00	
1.92	AIRBAG ECU	1	ACTIVATED	\$696.00	\$696.00	
1.93	SEATBELT RH	1	ACTIVATED	\$660.00	\$660.00	
1.94	SEATBELT LH	1	ACTIVATED	\$660.00	\$660.00	
1.95	FRONT WINDSCREEN	1	CRACKED	\$696.00	\$696.00	
1.96	FRONTWINDSCREEN MOULDING	1	NECESSARY	\$54.00	\$54.00	
1.97	INNER SEAL TAPE	1	NECESSARY	\$36.00	\$36.00	
1.98	IU STICKER	1	NECESSARY	\$3.60	\$3.60	
1.99	SEALANT	2	NECESSARY	\$24.00	\$48.00	
1.100	FRONT NUMBER PLATE	1	CRACKED	\$24.00	\$24.00	
2	LABOUR DESCRIPTION					
2.1	TO REPLACE AND RESPRAY BONNET					6
2.2	TO REPLACE SUPPORT PANEL					2
2.3	TO REPLACE AND RESPRAY FRT BUMPER					5
2.4	TO REPLACE AND RESPRAY LHF FENDER					4
2.5	TO REPLACE AND RESPRAY RHF FENDER					4

2.6	TO REMOVE AND REFIX CONDENSER, RADIATOR AND TOP UP AC GAS					2
2.7	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK					10
2.8	TO ALIGN, REPLACE AND RESPRAY RH / LH CHASSIS					20
2.9	TO REPLACE FRT UNDER CARRIAGE PARTS					4
2.10	TO PERFORM 4 WHEEL ALIGNMENT					1
2.11	TO ALIGN, REPLACE AND RESPRAY REINFORCEMENT					1
2.12	TO REPLACE DASHBOARD					4
2.13	TO REPLACE FRONT WINDSCREEN					4
COSTING		TOTAL PARTS COST			\$43,765.32	
		TOTAL MAN-HOUR				67

Registration No. QX 793S

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.