

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO19020996/R1qd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 31-03-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 3319S	Veh. Inspected	YQ 1426M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905515/THE	Excess (\$)	0.00
Assign From	YONG KANG MELVIN	Assign Date	27/11/2019

2. Vehicle Particulars & Condition

Make & Model	ISUZU NPR75UH5A	c.c	5193
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JAANPR75HJ7100833	Colour	WHITE
Odometer	9372	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/75 R17.5	BRIDGESTONE	7 mm
L/H Front Tyre	215/75 R17.5	BRIDGESTONE	7 mm
R/H Rear Tyre	215/75 R17.5 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	215/75 R17.5 (D)	BRIDGESTONE	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/10/2019	Inspection Date	28/11/2019
Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1426M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT GRILLE	SERVICEABLE	397.00	-
2	SIDE LAMP R/L	CRACKED	150.00	150.00
1	SIDE MIRROR ARM	NOT NECESSARY	249.00	-
1	SIDE MIRROR	NOT NECESSARY	51.00	-
1	FRONT PANEL	BENT	786.00	786.00
1	MIRROR GARNISH	DEFORMED	41.00	41.00
	LESS 15% DISCOUNT		-	-146.55
			1,674.00	830.45
	<u>LABOUR</u>			
	TO KNOCK & WELD FRONT PANEL, CHANGE SIDE MIRROR ARM, MIRROR & GRILLE.		550.00	300.00
	TO SPRAY PAINT & PUTTY FRONT PANEL & DAMAGED PARTS.		580.00	350.00
			1,130.00	650.00
	GRAND TOTAL		2,804.00	1,480.45
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CS/SMO19020996/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.