

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021023/FKA3Q2

**Date:** 28/04/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700034233  
**Claimant**  
**Vehicle No :** SH7226C **Insured Vehicle No :** SML5755E  
Date of Loss: 27/11/2019 Nature of Claim: TP Claim No: 0608371697SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH7226C**  
Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU625141  
Reg. Date: 29/09/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU093546  
Colour: Blue Odometer: 558659 km  
Engine Capacity: 1685 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 7 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 885.06            | 0.00              | 885.06            | 100.00        |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 730.00            | 440.00            | 290.00            | 39.73         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                        | <b>1,615.06</b>   | <b>440.00</b>     | <b>1,175.06</b>   | <b>72.76</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 113.05            | 30.80             | 82.25             | 72.76         |
| <b>Nett Amount (S\$)</b>                        | <b>1,728.11</b>   | <b>470.80</b>     | <b>1,257.31</b>   | <b>72.76</b>  |
| <b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b> |                   | 150.00            |                   |               |
| <b>+ Car Rental (3.0 x S\$112.67/day) (S\$)</b> |                   | 338.01            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.49              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>966.30</b>     |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>900.00</b>     |                   |               |

#### INSPECTION

Date of Assignment: 27/11/2019  
Date Inspected: 28/11/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969  
Estimated Period of Repair: 2.0 days

---

**Adjuster:** PARASURAM SHANMUGAM**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                  | Condition     | Repairer's | Amount |
|-----|-----|----------|------------------------------|---------------|------------|--------|
| 1   | 1   |          | *REAR BUMPER                 | Repair        | 553.00 FL  | * - FL |
| 2   | 1   |          | *REAR BUMPER CLIP            | Not Necessary | 22.00 FL   | * - FL |
| 3   | 2   |          | *REAR BUMPER BRACKET (LH/RH) | Not Necessary | 71.20 FL   | * - FL |
| 4   | 1   |          | *REAR BUMPER UNDER COVER     | Not Necessary | 228.00 FL  | * - FL |
| 5   | 1   |          | *REAR BUMPER REVERSE SENSOR  | Not Necessary | 135.70 FS  | * - FS |
| 6   | 1   |          | *REAR BUMPER RUBBER MAT      | Not Necessary | 50.00 FS   | * - FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                 |             |
|---|-----------------|-------------|
| <b>Sub Total (S\$)</b>                                    | <b>1,059.90</b> | <b>0.00</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> | 174.84          | 0.00        |
| <b>Total Parts (S\$)</b>                                  | <b>885.06</b>   | <b>0.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                 | Lab.Type | Repairer's                      | Amount        |
|---------------------|-----------------------------|----------|---------------------------------|---------------|
| <b>Labour Items</b> |                             |          |                                 |               |
| 1                   | PANEL BEATING               | New      | 350.00                          | 240.00        |
| 2                   | SPRAY PAINTING CHARGE       | New      | 250.00                          | 200.00        |
| 3                   | WIRING CHARGE               | New      | 50.00                           | 0.00          |
| 4                   | REMOVE/REFIX REVERSE SENSOR | New      | 80.00                           | 0.00          |
|                     |                             |          | <b>Gross Labour Cost (\$\$)</b> | <b>440.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >