

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7226C

MAKE :

MODEL : HYUNDAI i40

Ag Asia-4S

DATE 27/11/2019

LKK - Ram.

IS
1600

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper x (R)			\$ 553.00
	Rear Bumper Clip 10 pcs xnn			\$ 22.00
	Rear Bumper Bracket (RH/LH) xnn		\$ 35.60	\$ 71.20
	Rear Bumper Under Cover xnn			\$ 228.00
	SUB TOTAL			\$ 874.20
	LESS 20%			\$ 174.84
	DISCOUNTED TOTAL			\$ 699.36
	Rear Bumper Reverse Sensor xnn			\$ 135.70 Nett
	Rear Bumper Rubber Mat xnn			\$ 50.00 Nett
				\$ 185.70
	Labour Charge			
	Panel Beating		<i>\$240</i>	\$ 350.00
	Spray Painting Charge		<i>\$200</i>	\$ 250.00
	Wiring Charge		<i>xnn</i>	\$ 50.00
	Remove/Refix Reverse Sensor		<i>xnn</i>	\$ 80.00
	TOTAL LABOUR			\$ 730.00
	ESTIMATE TOTAL			\$ 1,615.06

RAM (LKK)
28/11/19 1130hrs
RAMSURAM@wcauto.com
88622778
4S
not repair photo
2 repair days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.