

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021024/BBA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800146841

Claimant
Vehicle No : SMP272T **Insured Vehicle No :** SMG8228S

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: 3303073435SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP272T		
Make & Model:	TOYOTA SIENTA, 1.5 G (A)	Engine No:	2NR8499143
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	NSP1707001785
Colour:	Black	Odometer:	68180 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,337.07	5,012.60	11,324.47	69.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,870.00	2,060.00	2,810.00	57.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,207.07	7,072.60	14,134.47	66.65
Approved Total (Overridden) (\$\$)		5,650.00		
Nett Amount (\$\$)	21,207.07	5,650.00	15,557.07	73.36
+ Loss of Use (9.0 x S\$60.00/day) (\$\$)		540.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,197.45		
Global Sum Settlement (\$\$)		6,150.00		

INSPECTION

Date of Assignment: 27/11/2019

Date Inspected: 06/12/2019 Inspected At: Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,983.50 FL	*1,395.00 FL
2	1		*FRONT DOOR PANEL RH	Not Damaged	1,580.00 FL	*- FL
3	1		*FRONT DOOR TRIM BOARD RH	Not Damaged	730.00 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP RH	Torn	294.00 FL	*294.00 FL
5	1		*FRONT DOOR WEATHERSTRIP RETAINER RH	No such part	357.60 FL	*- FL
6	1		*FRONT BODY B PILLAR RH	Not Damaged	1,095.60 FL	*- FL
7	1		*FRONT DOOR OUTER HANDLE	Cut	654.00 FL	*395.00 FL
8	1		*FRONT DOOR LOCK RH	Broken	582.40 FL	*582.40 FL
9	1		*FRONT DOOR KEY LOCK	Dented	359.00 FL	*359.00 FL
10	1		*FRONT DOOR REGULATOR ASSY RH	Not Damaged	853.40 FL	*- FL
11	1		*FRONT DOOR UPPER HINGE ASSY RH	Not Damaged	85.60 FL	*- FL
12	1		*FRONT DOOR LOWER HINGE ASSY RH	Not Damaged	85.60 FL	*- FL
13	1		*SIDE MIRROR RH	Broken	986.30 FL	*986.30 FL
14	1		*REAR DOOR RH	Dented	2,314.00 FL	*1,435.00 FL
15	1		*REAR DOOR LOWER PANEL	Not Damaged	328.40 FL	*- FL
16	1		*REAR DOOR LOWER PANEL GARNISH	Not Damaged	121.60 FL	*- FL
17	1		*REAR DOOR INNER GARNISH	Not Damaged	288.60 FL	*- FL
18	1		*REAR DOOR REGULATOR ASSY	Not Damaged	782.90 FL	*- FL
19	1		*REAR DOOR SENSOR STRIP	Not Damaged	354.80 FL	*- FL
20	1		*REAR DOOR WEATHERSTRIP	Not Damaged	234.20 FL	*- FL
21	1		*AUTO DOOR MECHANISM	Not Damaged	1,680.00 FL	*- FL
22	1		*REAR DOOR ROLLER UPPER	Not Damaged	239.50 FL	*- FL
23	1		*REAR DOOR ROLLER CENTER	Dented	241.00 FL	*241.00 FL
24	1		*REAR DOOR ROLLER LOWER	Not Damaged	238.50 FL	*- FL
25	1		*REAR DOOR LOCK MECHANISM	Not Damaged	942.00 FL	*- FL
26	1		*REAR DOOR TRIM BOARD RH	Not Damaged	326.00 FL	*- FL
27	1		*REAR FENDER	Dented	689.10 FL	*689.10 FL
28	1		*REAR FENDER INNER SHIELD	Not Damaged	342.80 FL	*- FL
29	1		*REAR FENDER CENTER GARNISH	Not Damaged	473.50 FL	*- FL
30	1		*REAR TAILLAMP RH	Not Damaged	864.20 FL	*- FL
31	1		*REAR KNUCKLE BEARING	Not Damaged	368.00 FL	*- FL
32	1		*SUNDRIES	Not Applicable	80.00 FS	*- FS
33	1		*FRONT DOOR SEALANT	Necessary	80.00 FS	*50.00 FS
34	1		*FRONT DOOR TRIM BOARD CLIP	Necessary	60.00 FS	*30.00 FS
35	2		*DOOR VISOR SEALANT	Necessary	120.00 FS	*30.00 FS
36	1		*REAR SIDE GLASS SEALANT	Necessary	80.00 FS	*30.00 FS
37	1		*REAR FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
38	1		*REAR TAILLAMP SEALANT	Not Necessary	60.00 FS	*- FS
39	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
40	1		*REAR DOOR TRIM BOARD CLIP	Necessary	60.00 FS	*30.00 FS
41	1		*REAR FENDER CENTER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
42	1		*REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
43	1		*REAR FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
44	1		*FRONT FENDER SIDE PANEL COWLING CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,456.10	6,606.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,119.03	1,594.20
Total Parts (\$\$)	16,337.07	5,012.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	1,800.00	1,000.00
2	RUST PROOFING	New	300.00	80.00
3	SPRAY PAINT	New	1,800.00	800.00
4	TO CHECK WIRING	New	100.00	50.00
5	TO R&R REAR SIDE GLASS	New	150.00	50.00
6	TO R&R REAR COMPONENT }	New	150.00	80.00
7	TO RESET REAR AUTO DOOR MECHANISM }	New	150.00	0.00
8	TO R&R UNDERCARRIAGE PARTS	New	250.00	0.00
9	TO R&R TYRE AND BALANCING	New	50.00	0.00
10	FULL WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			4,870.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >