

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021027/KPA3Q2

Date: 15/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : PC4788D	Insured Vehicle No :	SHA2311P
Date of Loss: 25/11/2019	Nature of Claim: TP	Claim No: MCT19110593

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC4788D		
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Engine No:	1KD2588527
Reg. Date:	01/06/2016 (Man. Year: 2016)	Chassis No:	KDH2230026845
Colour:	White	Odometer:	143845 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,521.05	519.00	2,002.05	79.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	920.00	2,350.00	71.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,791.05	1,439.00	4,352.05	75.15
+ GST 7.00/7.00% (\$\$)	405.37	100.73	304.64	75.15
Nett Amount (\$\$)	6,196.42	1,539.73	4,656.69	75.15
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	27/11/2019	
Date Inspected:	29/11/2019 Inspected At:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Apr 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4788D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cut	378.00 FL	*378.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	49.00 FL	*49.00 FL
3	1		*REAR BODY PANEL RH	Repair	1,406.00 FL	*- FL
4	1		*REAR LAMP RH	Cut	265.00 FL	*265.00 FL
5	1		*REAR CORNER PANEL RH	Repair	84.00 FL	*- FL
6	1		*REAR WHEEL CAP RH	Serviceable	139.40 FL	*- FL
7	1		*REAR REVERSE SENSOR	Serviceable	280.00 FS	*- FS
8	1		*RH BODY WINDOW GLASS PRIMER	Not Necessary	120.00 FS	*- FS
9	1		*GLASS SEALANT	Not Necessary	100.00 FS	*- FS
10	1		*REAR TYRE RH	Serviceable	250.00 FS	*- FS
11	1		*REAR RH BODY PANEL STICKER	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,101.40	692.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	580.35	173.00
Total Parts (\$\$)	2,521.05	519.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	1,000.00	250.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGES PARTS TO KNOCK JACK ,CUT ,WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,400.00	500.00
3	TO APPLY ANTI RUST TREATMENT	New	150.00	0.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	50.00	20.00
5	TO REMOVE & REFIT INTERIOR ROOF LINING ,UPHOLSTERY ,PASSENGER SEATS	New	350.00	100.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
7	TO RMEOVE & REFIT RH WINDOW GLASS	New	200.00	0.00
Gross Labour Cost (\$\$)			3,270.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >