

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III19021028/APA3Q2

**Date:** 19/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> FBL3048G	<b>Insured Vehicle No :</b>	SHA4013L
Date of Loss: 15/10/2019	Nature of Claim: TP	Claim No: MCT19100334

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL3048G	Engine No:	MC46E5014650
Make & Model:	HONDA CBF190WH, 184cc	Chassis No:	LWBMC4695H1104078
Reg. Date:	17/08/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Red/White		
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,045.00	1,964.00	1,081.00	35.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	600.00	370.00	38.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,015.00</b>	<b>2,564.00</b>	<b>1,451.00</b>	<b>36.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,015.00</b>	<b>2,050.00</b>	<b>1,965.00</b>	<b>48.94</b>
<b>+ Loss of Use (4.0 x S\$25.00/day) (S\$)</b>		100.00		
<b>Nett Liability (S\$)</b>		<b>2,150.00</b>		

### INSPECTION

Date of Assignment:	27/11/2019	
Date Inspected:	27/11/2019 Inspected At:	Chin Meng Motors (HQ)
		1 Kaki Bukit Ave 6 #01-40/63, Autobay
		@ Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Apr 2020)	
<b>Parts:</b>	N/A	HONDA CBF190WH 184cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL3048G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	O/S Bent	156.00 FL	*78.00 FL
2	2		*HANDLE BAR GRIP	Not Necessary	50.00 FL	*- FL
3	1		*HANDLE BAR BALANCER	O/S Cut	24.00 FL	*12.00 FL
4	1		*BRAKE LEVER	Cut	25.00 FL	*25.00 FL
5	1		*HEADLAMP	Not Necessary	155.00 FL	*- FL
6	1		*HEADLAMP STAY	Not Necessary	45.00 FL	*- FL
7	1		*HEADLAMP TOP NOSE GARNISH	Not Necessary	45.00 FL	*- FL
8	1		*HEADLAMP SIDE GARNISH (RED & WHITE)	O/S Cut	130.00 FL	*65.00 FL
9	2		*FRONT SIGNAL LAMP	Not Necessary	50.00 FL	*- FL
10	1		*R/H MIRROR WITH BRACKET ASSY	Not Necessary	65.00 FL	*- FL
11	1		*FRONT SIDE FAIRING	O/S Cracked	320.00 FL	*160.00 FL
12	1		*SET FRONT SIDE FAIRING STICKERS	Not Necessary	65.00 FL	*- FL
13	2		*FRONT FORK	Bent	500.00 FL	*500.00 FL
14	1		*FRONT FORK CENTRE BRACKET	Damaged	65.00 FL	*65.00 FL
15	1		*FRONT FORK TOP BRACKET	Damaged	80.00 FL	*80.00 FL
16	1		*FRONT FORK CENTRE SHAFT	Damaged	80.00 FL	*80.00 FL
17	2		*FRONT FORK LOWER HOLDER BRACKET	Damaged	50.00 FL	*50.00 FL
18	1		*FRONT BRAKE DISC	Bent	65.00 FL	*65.00 FL
19	1		*FRONT BRAKE CALIPER	Cut	250.00 FL	*250.00 FL
20	1		*FRONT RIM	Cut	180.00 FL	*180.00 FL
21	1		*FRONT MUDGUARD	Deformed	55.00 FL	*55.00 FL
22	1		*FRONT R/H FOOTREST WITH BRACKET	Broken	45.00 FL	*45.00 FL
23	1		*FRONT R/H FOOTRAKE LEVER	Bent	25.00 FL	*25.00 FL
24	1		*REAR R/H FOOTREST WITH BRACKET ASSY	Cut	45.00 FL	*45.00 FL
25	1		*REAR RIM	Warped	180.00 FL	*180.00 FL
26	1		*IU UNIT	Not Necessary	170.00 FS	*- FS
27	1		*FRONT TYRE	Not Necessary	120.00 FS	*- FS
28	1		*REAR BOX	Cut	220.00 FS	*200.00 FS
29	1		*REAR BOX BRACKET	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,320.00</b>	<b>2,160.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	275.00	196.00
<b>Total Parts (\$\$)</b>	<b>3,045.00</b>	<b>1,964.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACED OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	500.00	280.00
2	TO APPLY UNDERSEAL	New	50.00	0.00
3	TO RESPRAY AFFECTED PART	New	350.00	250.00
4	TRANSPORTATION CHARGES	New	40.00	40.00
5	TO CHECK WIRINGS	New	30.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>970.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >