

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19021054/KGA3Q2  
**Date:** 12/04/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLZ112G	Insured Vehicle No :	SHC3614Z
Date of Loss:	26/11/2019	Nature of Claim:	TP
		Claim No:	MCT19110655

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ112G	Engine No:	A342J432N13B16A
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Chassis No:	WBA3A12070J720092
Reg. Date:	28/03/2013 (Man. Year: 2013)	Odometer:	125435 km
Colour:	Metallic Dark Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Continental 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,841.31	2,590.26	5,251.05	66.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,740.00	600.00	25.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,181.31</b>	<b>4,330.26</b>	<b>5,851.05</b>	<b>57.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
(S\$)	10,181.31	3,450.00	6,731.31	66.11
<b>+ GST 7.00/7.00% (S\$)</b>	712.69	241.50	471.19	66.11
<b>Nett Amount (S\$)</b>	<b>10,894.00</b>	<b>3,691.50</b>	<b>7,202.50</b>	<b>66.11</b>
<b>+ Car Rental (8.0 x S\$120.00/day) (S\$)</b>		960.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,658.95</b>		

### INSPECTION

Date of Assignment:	28/11/2019	
Date Inspected:	28/11/2019	Inspected At: 160 SIN MING DRIVE #02-20 Repairer: K Kim Hin Auto Pte Ltd
Estimated Period of Repair:	6.0 days	

4/12/2021

Adjuster Report

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2020)
<b>Parts:</b>	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ112G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S REAR DOOR	Bent	1,273.85 FL	*1,273.85 FL
2	1		*N/S REAR DOOR HINGES -TOP	Repair	58.90 FL	*- FL
3	1		*N/S REAR DOOR HINGES -BOTTOM	Repair	58.90 FL	*- FL
4	1		*N/S REAR DOOR CHECKER	Serviceable	81.48 FL	*- FL
5	1		*N/S REAR DOOR WEATHERSTRIP (50%)	Necessary	127.26 FS	*70.70 FS
6	1		*N/S REAR DOOR WINDOW REGULATOR	Distorted	252.70 FL	*252.70 FL
7	1		*N/S REAR DOOR WINDOW REGULATOR MOTOR	Serviceable	319.85 FL	*- FL
8	1		*N/S ROCKER PANEL	Repair	1,643.30 FL	*- FL
9	1		*N/S ROCKER PANEL REAR STEP GARNISH	Dented	93.89 FL	*93.89 FL
10	1		*N/S SIDE SKIRTING	Dented / Cut	408.90 FL	*408.90 FL
11	1		*N/S SIDE SKIRTING BRACKET -CENTRE	Necessary	47.95 FL	*47.95 FL
12	1		*N/S SIDE SKIRTING BRACKET -REAR	Not Necessary	47.95 FL	*- FL
13	1		*N/S REAR SHOCK ABSORBER	Serviceable	340.50 FL	*- FL
14	1		*N/S REAR SHOCK ABSORBER MOUNTING	Serviceable	147.55 FL	*- FL
15	1		*N/S REAR SHOCK ABSORBER STOPPER	Serviceable	42.90 FL	*- FL
16	1		*N/S REAR KNUCKLE ARM	Serviceable	1,106.95 FL	*- FL
17	1		*N/S REAR KNUCKLE ARM BEARING	Serviceable	155.80 FL	*- FL
18	1		*N/S REAR BEARING HUB	Serviceable	165.55 FL	*- FL
19	1		*N/S REAR UPPER ARM	Serviceable	318.85 FL	*- FL
20	1		*N/S REAR UPPER CONTROL ARM	Serviceable	127.55 FL	*- FL
21	1		*N/S REAR LOWER ARM	Serviceable	350.75 FL	*- FL
22	1		*N/S REAR LOWER CONTROL ARM	Serviceable	271.05 FL	*- FL
23	1		*N/S REAR TRAILING ARM	Serviceable	111.60 FL	*- FL
24	1		*N/S REAR TYRE	Not Necessary	380.00 FS	*- FS
25	1		*N/S REAR RIM	Dented	650.00 FS	*650.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,583.98</b>	<b>2,797.99</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	742.67	207.73
<b>Total Parts (\$)</b>	<b>7,841.31</b>	<b>2,590.26</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS	New	900.00	600.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS ,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	80.00
3	TO DISMANTLE AND CHECK REAR UNDERCARRIAGE .TO REPLACE AFFECTED PORTIONS	New	120.00	0.00
4	TO CONDUCT REAR WHEEL ALIGNMENT TEST	New	100.00	60.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,100.00	1,000.00
Gross Labour Cost (S\$)			<b>2,340.00</b>	<b>1,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >