

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19021060/ERA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SG6018Z	Insured Vehicle No :	SMJ8975C
Date of Loss:	07/11/2019	Nature of Claim:	TP
		Claim No:	7828941321SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG6018Z	Engine No:	50351460635145
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZXKF008277
Reg. Date:	03/12/2018 (Man. Year: 2018)	Odometer:	90123 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	854.00	527.00	327.00	38.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	854.00	527.00	327.00	38.29
	+ Loss of Use (2.0 x S\$285.00/day) (S\$)	570.00		
	+ Doc/Search Fee (S\$)	7.00		
	Nett Liability (S\$)	1,104.00		
	Global Sum Settlement (S\$)	1,100.00		

INSPECTION

Date of Assignment:	27/11/2019	
Date Inspected:	27/11/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	1.0 days	

Adjuster: CHEN TSUE YEE

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

2/16/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR RHS PORTION	New	530.00	265.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	324.00	262.00
			Gross Labour Cost (S\$)	527.00
			854.00	527.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >