

REPAIR ESTIMATE*

VEHICLE NO : SHC 3614Z

DATE 26/11/2019 14:46

MAKE :

MODEL : HYUNDAI i40

Lice

QB

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover SCV CUA			\$ 544.50
	Front Bumper Grille (RH) SCV			\$ 41.60
	Front Bumper Bracket Top (RH) XNN			\$ 22.40
	Front Bumper Bracket (RH) XNN			\$ 24.60
	Headlamp (RH) CUA			\$ 1,388.00
	Front Fender (RH) SCV BUC			\$ 566.30
	Front Fender Shield (RH) XNN			\$ 175.90
	Front Fender Retainer XNN			\$ 24.60
	Frt Wheel Hub Cap, RH DEF			\$ 107.10
	SUB TOTAL		2,647.50	\$ 2,895.00
	LESS 20% 25%		(25%)	\$ 579.00
	DISCOUNTED TOTAL		1,985.62	\$ 2,316.00
	Front Fender Advertisement Logo (RH) REC		100	\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating		\$280	\$ 350.00
	Spray Painting Charge		\$400	\$ 500.00
	Wiring		\$30	\$ 50.00
	Tuff Kote		\$20	\$ 50.00
	Frt Wheel Alignment		XNN	\$ 80.00
	TOTAL LABOUR		700	\$ 1,030.00
	ESTIMATE TOTAL		2,122.62	\$ 3,446.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

\$2,250

27/11/19 1220hrs

Parasuram@ukrauto.com

88622728

971 repair

photo