

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19021068/AKA3Q2

Date: 30/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SJT9126M **Insured Vehicle No :** SFP1200C

Date of Loss: 27/11/2019 **Nature of Claim:** TP **Claim No:** 8313675359SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9126M		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ425954
Reg. Date:	25/04/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V3J1050367
Colour:	Silver	Odometer:	23494 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,832.80	4,875.12	2,957.68	37.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,172.00	6,712.00	6,460.00	49.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,004.80	11,587.12	9,417.68	44.84
+ GST 7.00/7.00% (\$\$)	1,470.34	811.10	659.24	44.84
Nett Amount (\$\$)	22,475.14	12,398.22	10,076.92	44.84
+ Loss of Use (8.0 x S\$60.00/day) (\$\$)		480.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		12,880.22		

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 29/11/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Repair	778.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
3	1		*FRONT FENDER REAR BRACKET -RH	Not Necessary	25.00 FS	*- FS
4	1		*FRONT FENDER CENTRE BRACKET -RH	Not Necessary	35.00 FS	*- FS
5	1		*FRONT DOOR -RH	Dented	2,279.00 FS	*1,823.20 FS
6	1		*FRONT DOOR OUTER SEAL -RH	Necessary	146.00 FS	*116.80 FS
7	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
8	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
9	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	218.00 FS	*- FS
10	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
11	1		*TYRE PRESSURE DATA PLATE	Not Necessary	26.00 FS	*- FS
12	1		*REAR DOOR -RH	Dented	2,279.00 FS	*1,823.20 FS
13	1		*REAR DOOR OUTER SEAL -RH	Not Necessary	146.00 FS	*- FS
14	1		*BONDING AGENT	Necessary	116.80 FS	*116.80 FS
15	1		*CLEANING SOLUTION	Necessary	65.00 FS	*35.92 FS
16	1		*REAR DOOR ATTACHMENT PARTS	Necessary	117.00 FS	*51.68 FS
17	1		*REAR DOOR CATCH	Not Necessary	85.00 FS	*- FS
18	1		*REAR ALUMINIUM RIM -RH	Cut	666.00 FS	*532.40 FS
19	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
20	1		*SUNDRIES	Necessary	400.00 FS	*107.52 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **7,832.80** **4,875.12**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS OUTSIDE TEMEPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	560.00	560.00
4	TO DISMANTLE RHS FRONT DOOR PANEL TRIM .TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	300.00	0.00
5	TO DISMANTLE FRONT BUMPER ,RHS FRONT FENDER ,RHS FRONT DOOR RHS REAR DOOR AND REAR BUMPER .TO RENEW RHS FRONT FENDER ,RHS FRONT DOOR AND RHS REAR DOOR .TO REPAIR RHS SILL PANEL AND RHS REAR FENDER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	4,900.00	2,000.00
6	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER ,RHS FRONT DOOR ,RHS REAR DOOR ,DOOR HANDLE ,RHS SILL PANEL ,RHS REAR FENDER AND REAR BUMPER	New	6,300.00	3,400.00
7	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,172.00	6,712.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >