

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19021071/R1YF3E2

Date: 17/11/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-391739-CA
Claimant Vehicle No :	SKP984X	Insured Vehicle No :	FBF7802B
Date of Loss:	06/11/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-001383

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP984X	Engine No:	CAYAB4662
Make & Model:	VOLKSWAGEN TOURAN, 1.6 TDI (A)	Chassis No:	WVGZZZ1TZFW000771
Reg. Date:	13/08/2014 (Man. Year: 2014)	Odometer:	162916 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,864.00	3,609.00	255.00	6.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,430.00	1,130.00	44.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,424.00	5,039.00	1,385.00	21.56
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	6,424.00	4,000.00	2,424.00	37.73

INSPECTION

Date of Assignment:	28/11/2019		
Date Inspected:	28/11/2019	Inspected At:	K's Performance & Services (HQ) 67 Yunnan Drive 3 Singapore 637954
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2020)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.6 TDI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP984X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	1,380.00 FL	*1,380.00 FL
2	1		*FRONT O/S FENDER	Bent	530.00 FL	*530.00 FL
3	1		*FRONT O/S HEADLAMP	Scratched	1,100.00 FL	*1,100.00 FL
4	1		*SIDE MIRROR O/S	Broken	600.00 FL	*600.00 FL
5	1		*FRONT O/S RIM	Scratched	495.00 FS	*300.00 FS
6	1		*FRONT BUMPER RETAINER (PAIR)	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,225.00	3,970.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	361.00	361.00
Total Parts (\$\$)	3,864.00	3,609.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE,REPLACE AND REALIGN ALL DAMAGE PARTS	New	1,100.00	500.00
2	ELECTRICAL TESTING TO ENSURE FUNCTIONAL	New	40.00	30.00
3	CHASSIS/WHEEL ALIGNMENT	New	100.00	60.00
4	APPLY ANTIRUST COATING TO ALL THE AFFECTED PARTS AFTER REPAIR	New	120.00	40.00
5	TO PROVIDE SPRAY PAINTING SERVICE TO ALL AFFECTED EXTERIOR PANELS EG.BONNET,BUMPER,FENDER,DOOR,SIDE MIRROR COVER,ETC	New	1,200.00	800.00
Gross Labour Cost (\$\$)			2,560.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >