



Your Ref : DMPC1700327H

Date: 13th December 2019

Our Ref : CC3/ICS17009675/K1ea3s2-1

M/s ECICS Ltd

7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987
(The Motor Claims Department)

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHA 6143G
ACCIDENT ON 16/05/2017 INSURED VEHICLE SGT 2203E**

Instruction was received to inspect the vehicle Reg. No. SHA 6143G. The inspection was conducted on 17/05/2017 at the premises of M/s: Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following information were recorded: -


Registration Number	: SHA 6143G
Make & Model	: Hyundai Sonata (A)
Year of Registration	: 2010
Engine Capacity	: 1991cc
Body Colour	: Blue
Chassis Number	: KMHET41VMAA794220
Speedometer Reading	: 44644 km

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Book Value	S\$ 19,918.77 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 14,848.17)
Nett Liability	<u>S\$ 5,070.60 (est)</u>

Vehicle Inspected By:


KALVIN ANG WEI KUN
Automotive Assessor / Investigator


K.K.LAU CPT(RET)
*BEng(Hons), B. Bus, MBA, PEng(UK), PE(USA),
MASME(USA), MInstAEA(UK), MIRTE, MCI Arb
REGD Auto Consultant-SAE, Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.