

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19021098/ESD3E2

**Date:** 14/09/2020

### REFERENCE

Insured/Claimant:	REGINA KING IN LIEM	Policy No:	1800096948-01	
Date of Loss:	26/11/2019	Nature of Claim:	OD	Claim No: 3865864190SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE435Y			
Make & Model:	AUDI Q3, 1.4 TFSI (A)		Engine No:	CZD886385
Reg. Date:	14/11/2019 (Man. Year: 2019)		Chassis No:	WAUZZZF37L1012161
Colour:	Grey		Odometer:	377 km
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$136,000.00			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,939.00	785.60	7,153.40	90.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,972.00	3,097.00	3,875.00	55.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,911.00</b>	<b>3,882.60</b>	<b>11,028.40</b>	<b>73.96</b>
<b>- Excess (\$\$)</b>	1,300.00	1,300.00	0.00	0.00
<b>(\$\$)</b>	13,611.00	2,582.60	11,028.40	81.03
<b>+ GST 7.00/7.00% (\$\$)</b>	952.77	180.78	771.99	81.03
<b>Nett Amount (\$\$)</b>	<b>14,563.77</b>	<b>2,763.38</b>	<b>11,800.39</b>	<b>81.03</b>

### INSPECTION

Date of Assignment:	29/11/2019	
Date Inspected:	29/11/2019	Inspected At: 281 ALEXANDRA ROAD
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,411.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	389.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	53.00 FS	*- FS
4	1		*MOLDING	Not Necessary	324.00 FS	*- FS
5	1		*FRONT BUMPER FRONT SPOILER	Repair	693.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	139.00 FS	*- FS
7	1		*MOLDING-LH	Not Necessary	150.00 FS	*- FS
8	1		*ULTRASOUND SENSOR SUPPORT-LH	Not Necessary	24.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	35.00 FS	*- FS
10	1		*FRONT PARKING AID SENSOR	Not Necessary	231.00 FS	*- FS
11	4		*PARKING AID SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
12	1		*FRONT FENDER-LH	Repair	1,174.00 FS	*- FS
13	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
14	1		*FRONT FENDER BRACE-LH	Not Necessary	80.00 FS	*- FS
15	1		*SOUND ABS-LH UPPER	Not Necessary	27.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	223.00 FS	*- FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	635.00 FS	*- FS
18	2		*FRONT WHEEL COVER-LH/RH	Necessary	982.00 FS	*785.60 FS
19	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>7,939.00      785.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
3	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,900.00	1,925.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>6,972.00</b>	<b>3,097.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >