

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19021108/AGYD3E2

Date: 28/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000990694

Claimant Vehicle No : SGD7307R

Insured Vehicle No : SLN6530G

Date of Loss: 28/11/2019

Nature of Claim: TP

Claim No: 234117

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGD7307R**

Make & Model: LEXUS RX200T, 2.0 (A)

Engine No: 8ARW291017

Reg. Date: 23/06/2016 (Man. Year: 2016)

Chassis No: JTJBAMCA502007013

Colour: Grey

Odometer: 25646 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R20

Rear Tyre Size: 235/55 R20

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,633.66	7,198.60	8,435.06	53.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	2,020.00	2,230.00	52.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,883.66	9,218.60	10,665.06	53.64
Approved Total (Overridden) (S\$)		7,300.00		
Nett Amount (S\$)	19,883.66	7,300.00	12,583.66	63.29

INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 29/11/2019 Inspected At:

1 Kaki Bukit Avenue 6 #01-34

Repairer : Hua Meng Spray Painting

Workshop (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2020)
Parts:	M1-SUV	LEXUS RX200T 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD7307R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	41.20 FL	*41.20 FL
2	1		*REAR TAILGATE	Dented	2,624.60 FL	*2,453.00 FL
3	1		*REAR TAILGATE UPPER LOCK	Not Necessary	1,071.40 FL	*- FL
4	1		*REAR TAILGATE LOWER LOCK	Not Necessary	57.60 FL	*- FL
5	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	781.00 FL	*- FL
6	1		*REAR TAILGATE INNER COVER	Not Necessary	761.60 FL	*- FL
7	1		*REAR TAILGATE INNER HANDLE	Not Necessary	93.10 FL	*- FL
8	2		*REAR TAILGATE INNER SIDE RUBBER	Not Necessary	818.00 FL	*- FL
9	2		*REAR TAILGATE INNER SIDE RUBBER GARNISH	Not Necessary	828.60 FL	*- FL
10	2		*REAR TAILGATE HINGES	Not Necessary	297.00 FL	*- FL
11	2		*REAR TAILGATE SIDE REFLECTOR	Not Necessary	904.20 FL	*- FL
12	1		*REAR TAILGATE CENTRE EMBLEM	Necessary	215.20 FL	*215.20 FL
13	1		*REAR TAILGATE LEXUS EMBLEM	Necessary	80.30 FL	*80.30 FL
14	1		*REAR TAILGATE RX EMBLEM }	Necessary	82.50 FL	*82.50 FL
15	1		*REAR TAILGATE 200T EMBLEM }	Necessary	-	-
16	1		*REAR TAILGATE HANDLE	Not Necessary	310.10 FL	*- FL
17	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	486.20 FL	*- FL
18	1		*REAR END PANEL	Dented	875.60 FL	*875.60 FL
19	1		*REAR END PANEL INNER TOP GARNISH	Cracked	470.30 FL	*470.30 FL
20	1		*REAR BUMPER	Distorted	1,094.50 FL	*1,094.50 FL
21	2		*REAR BUMPER SIDE HOLDER	Necessary	255.80 FL	*255.80 FL
22	2		*REAR BUMPER SIDE REFLECTOR	Cracked	131.60 FL	*131.60 FL
23	1		*REAR BUMPER LOWER CENTRE GARNISH	Deformed	544.50 FL	*544.50 FL
24	2		*REAR BUMPER LOWER SIDE GARNISH	Deformed	332.20 FL	*332.20 FL
25	1		*REAR BUMPER REINFORCEMENT	Bent	474.80 FL	*474.80 FL
26	1		*REAR BUMPER SPONGE	Cracked	137.50 FL	*137.50 FL
27	2		*REAR BUMPER BRACKET	Not Necessary	96.80 FL	*- FL
28	2		*REAR EXHAUST PIPE CHROME	Not Necessary	270.20 FL	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	66.00 FL	*30.00 FL
30	1		*REAR TAILGATE CAMERA	Not Necessary	800.00 FS	*- FS
31	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	1,870.00 FS	*520.00 FS
32	1		*REAR TAILGATE LOCK SENSOR	Cracked	181.50 FS	*181.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,053.90 7,920.50
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,420.24 721.90

Total Parts (\$\$) 15,633.66 7,198.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
2	TO SUPPLY REAR END PANEL SEALANT	New	200.00	60.00
3	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	60.00
4	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	80.00
5	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	60.00
6	REMOVE & REINSTALL EXHAUST PIPE	New	150.00	0.00
7	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
8	RESPRAY PAINTING	New	1,400.00	850.00
9	TUFF KOTE	New	150.00	60.00
Gross Labour Cost (\$)			4,250.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >