Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021120/T1GA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SJL4939J Insured Vehicle No: SHC8934S

Vehicle No:

Date of Loss: Nature of Claim: TP 22/11/2019 Claim No: MCT19110556

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJL4939J Reg No:

Make & Model: HONDA JAZZ, 1.3 L (A) Engine No: L13Z11005819

Chassis No: Reg. Date: 28/11/2008 (Man. Year: 2008) JHMGE68509S205816

Colour: White Odometer: 281938 km

Engine Capacity: 1339 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16 Front Left Side: Rear Left Side: Firenza 6 mm Firenza 6 mm Front Right Side: Rear Right Side: Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,136.44	2,218.20	918.24	29.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	1,190.00	350.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,676.44	3,408.20	1,268.24	27.12
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	4,676.44	2,700.00	1,976.44	42.26
+ GST 7.00/7.00% (S\$)	327.35	189.00	138.35	42.26
Nett Amount (S\$)	5,003.79	2,889.00	2,114.79	42.26
+ Car Rental (4.0 x S\$107.00/day) (S\$) + Doc/Search Fee (S\$)		428.00		
		29.00		
Net	t Liability (S\$)	3,346.00		

INSPECTION

Date of Assignment: 28/11/2019

Date Inspected: 29/11/2019 Inspected At: Yew Tee Automobile Tech Pte Ltd

(HQ)

Blk 6 Woodlands Road 399F,, Yew

Tee Ind Estate Singapore 678006

Estimated Period of Repair: 5.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2020)

Parts: 144 HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL4939J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

1			Condition	Repairer's	Amount
	1	*FRONT DOOR LH	Dented	757.20 FL	*757.20 FL
2	1	*FRONT DOOR SIDE MIRROR LH	Cracked	527.10 FL	*527.10 FL
3	1	*FRONT DOOR SIDE MIRROR MOTOR LH	Not Necessary	384.90 FL	*-FL
4	1	*FRONT DOOR SIDE MIRROR GLASS LH	Not Necessary	214.30 FL	*-FL
5	1	*FRONT DOOR SIDE MIRROR COVER LH	Missing	108.60 FL	*108.60 FL
6	1	*FRONT DOOR SIDE MIRROR SIGNAL LAMP LI	Distorted	119.40 FL	*119.40 FL
7	1	*FRONT FENDER LH	Repair	435.80 FL	*-FL
8	1	*FRONT FENDER QUARTER GLASS LH	Cracked	358.60 FL	*358.60 FL
9	1	*FRONT FENDER QUARTER GLASS GARNISH	LH Repair	112.80 FL	*- FL
10	1	*FRONT FENDER QUARTER GLASS MOULDING	GLH Necessary	58.60 FL	*58.60 FL
11	1	*REAR DOOR LH	Dented	799.50 FL	*799.50 FL
12	1	*REAR FENDER LH (NPA)	Repair	0.00 FL	*-FL
13	1	*FRONT FENDER QUARTER GLASS SEALANT	LH Necessary	35.00 FS	*35.00 FS
F=Fran	nchise	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)	3,911.80	2,764.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					545.80

Report was unsubmitted during this print-out.

Total Parts (S\$) 3,136.44

2,218.20

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE AND REFIT FRONT FENDER GLASS.	New	60.00	40.00
2	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	680.00	500.00
3	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	800.00	650.00
	Gross Labour Cost (S\$)		1,540.00	1,190.00
	Report was unsubmitted durir	ng this print-out.		

< END OF ESTIMATES >