

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1911/014
Policy No:	5079341740-03	Date of Loss:	22/11/2019
Vehicle Reg. No.:	<b>SJL4939J</b>	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHC8934S
Any Injuries?	no	Contact No:	
Insured/Claimant:	NURULAFIAH BINTE NIZLAN	Driver:	KAMAL ADAM LITAK
Make/Model:	Honda, JAZZ - GK3 / GK5	Vehicle Reg. Date:	28 Nov 2008
Vehicle Colour:	WHITE	Engine Number:	L13Z11005819
Chassis No:	JHMGE68509S205816	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	7

Description of Accident/loss COLLISION-OPENING DOOR OF VEHICLE  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	3,101.44
Miscellaneous Items	35.00
Labour	740.00
Paintwork Labour	800.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>4,676.44</b>
<b>GST 7.00%(S\$):</b>	<b>327.35</b>
<b>Nett Amount(S\$):</b>	<b>5,003.79</b>

This claim is handled by: SHUYI

**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT DOOR LH	757.20	-20.00	605.76
2	1	FRONT DOOR SIDE MIRROR LH	527.10	-20.00	421.68
3	1	FRONT DOOR SIDE MIRROR MOTOR LH	384.90	-20.00	307.92
4	1	FRONT DOOR SIDE MIRROR GLASS LH	214.30	-20.00	171.44
5	1	FRONT DOOR SIDE MIRROR COVER LH	108.60	-20.00	86.88
6	1	FRONT DOOR SIDE MIRROR SIGNAL LAMP LH	119.40	-20.00	95.52
7	1	FRONT FENDER LH	435.80	-20.00	348.64
8	1	FRONT FENDER QUARTER GLASS LH	358.60	-20.00	286.88
9	1	FRONT FENDER QUARTER GLASS GARNISH LH	112.80	-20.00	90.24
10	1	FRONT FENDER QUARTER GLASS MOULDING LH	58.60	-20.00	46.88
11	1	REAR DOOR LH	799.50	-20.00	639.60
12	1	REAR FENDER LH	0.00	0.00	0.00
<b>Total Parts (\$\$)</b>					<b>3,101.44</b>

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER QUARTER GLASS SEALANT LH	35.00	0.00	35.00
<b>Sub Total (\$\$)</b>					<b>35.00</b>

**Estimates On Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Front Fender Glass.	60.00	0.00	60.00
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	680.00	0.00	680.00
<b>Gross Labour Cost (\$\$)</b>					<b>740.00</b>

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00
<b>Gross Labour Cost (\$\$)</b>					<b>800.00</b>

&lt; END OF ESTIMATES &gt;