

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021157/APA3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SGT1007L	Insured Vehicle No :	SHA7241A
Date of Loss: 27/11/2019	Nature of Claim: TP	Claim No: MCT19110703

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT1007L		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0B45542
Reg. Date:	21/06/2018 (Man. Year: 2018)	Chassis No:	ZWR800316659
Colour:	White	Odometer:	37563 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,604.00	3,414.25	4,189.75	55.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,420.00	1,610.00	3,810.00	70.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,024.00	5,024.25	7,999.75	61.42
+ GST 7.00/7.00% (S\$)	911.68	351.70	559.98	61.42
Nett Amount (S\$)	13,935.68	5,375.95	8,559.73	61.42
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,025.40		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment:	28/11/2019	
Date Inspected:	29/11/2019	Inspected At: Jack Cars Enterprise Pte Ltd BLK3007 UBI ROAD 1 #01-450 Singapore 408700
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2020)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT1007L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	900.00 FL	*900.00 FL
2	1		*REAR BUMPER BRACKET -LEFT	Necessary	42.00 FL	*42.00 FL
3	1		*REAR BOOT	Dented	2,400.00 FL	*1,712.00 FL
4	1		*REAR BOOT WEATHERSTRIP	Cut	380.00 FL	*380.00 FL
5	1		*REAR BOOT INNER COVER	Not Necessary	760.00 FL	*- FL
6	1		*REAR BOOT CHROME GARNISH	Not Necessary	750.00 FL	*- FL
7	1		*REAR BOOT LOCK	Damaged	680.00 FL	*- FL
8	1		*REAR END PANEL	Dented	800.00 FL	*- FL
9	1		*REAR END PANEL TOP COVER	Deformed	260.00 FL	*260.00 FL
10	1		*REAR SIDE PAD-LEFT	Not Necessary	380.00 FL	*- FL
11	1		*TAIL LAMP -LEFT	Not Necessary	900.00 FL	*- FL
12	1		*SPARE TYRE COMPARTMENT COVER (BY AIR)	Cracked	1,360.00 FL	*845.00 FL
13	1		*TOW HOOK COVER	Deformed	45.00 FS	*45.00 FS
14	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
15	1		*HYBRID STICKER	Necessary	65.00 FS	*65.00 FS
16	1		*HONDA EMBLEM	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,007.00	4,449.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,403.00	1,034.75
Total Parts (\$\$)	7,604.00	3,414.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	2,000.00	600.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	2,400.00	600.00
3	TO CHECK LIGHTING SYSTEM,WIRING& REWIRE	New	250.00	30.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	120.00	80.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	180.00	60.00
6	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	200.00	120.00
7	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	New	150.00	60.00
8	ANTI RUST TREATMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			5,420.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >