Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19021158/APA3Q2

Date: 19/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant

SGH7228P Insured Vehicle No: SHC8045H Vehicle No:

Date of Loss: ΤP 23/11/2019 Nature of Claim: Claim No: MCT19110569

DESCRIPTION & IDENTIFICATION OF VEHICLE

SGH7228P Reg No:

NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD Make & Model: Engine No: HR16972648B

4DR (A)

Reg. Date: 25/08/2015 (Man. Year: 2015) Chassis No: MNTBBAB17Z0024513

Odometer: Colour: **Bronze** 62530 km

Engine Capacity: 1598 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,529.98	2,774.97	755.01	21.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,160.00	330.00	22.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,019.98	3,934.97	1,085.01	21.61
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	5,019.98	3,100.00	1,919.98	38.25
+ Car Rental (4.0 x S\$10	00.00/day) (S\$)	400.00		
Ne	tt Liability (S\$)	3,500.00		

INSPECTION

Date of Assignment: 27/11/2019

Date Inspected: 27/11/2019 Inspected At: Chin Meng Motors (HQ)

1 Kaki Bukit Ave 6 #01-40/63, Autobay

@ Kaki Bukit Singapore 417883

Estimated Period of Repair: 5.0 days

Manager: CHEW HSIAO TONG Adjuster: ADRIAN LING

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2020)		
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	: (Unsubmitted, no print-code for SGH7228P)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info:	Items/values i	not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H DOOR	Dented	918.20 FN	*918.20 FN
2	1		*FRONT R/H DOOR HINGE	Lower Bent	142.60 FN	*71.30 FN
3	1		*FRONT R/H DOOR CHECK	Not Necessary	42.80 FN	*- FN
4	1		*FRONT R/H DOOR WEATHERSTRIP	Not Necessary	90.80 FN	*- FN
5	1		*FRONT R/H DOOR PROTECTOR (CHROME)	Necessary	254.70 FN	*254.70 FN
6	2		*FRONT R/H DOOR STICKER	Necessary	46.00 FN	*46.00 FN
7	1		*FRONT R/H DOOR VISOR	Necessary	55.00 FN	*55.00 FN
8	1		*FRONT R/H DOOR OUTER MOULDING (CHROME)	Not Necessary	141.00 FN	*- FN
9	1		*FRONT R/H DOOR INNER BOARD	Cracked	347.60 FN	*347.60 FN
10	1		*FRONT R/H DOOR GEAR	Not Necessary	115.80 FN	*- FN
11	1		*FRONT R/H DOOR INNER LOCK	Not Necessary	257.20 FN	*- FN
12	1		*FRONT R/H FENDER	Dented	722.60 FN	*722.60 FN
13	1		*FRONT R/H FENDER INNER SHIELD	Not Necessary	98.00 FN	*- FN
14	1		*R/H SKIRTING	Deformed	637.90 FN	*637.90 FN
15	6		*R/H SKIRTING CLIPS	Necessary	52.00 FN	*30.00 FN
F=Fra	anchise	part. N=Net	tltemDisc.		-	
				Sub Total (S\$)	3,922.20	3,083.30
			- Nett Item Discount on N Items 10	.00/10.00% (S\$)	392.22	308.33
				Total Parts (S\$)	3,529.98	2,774.97

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS ASMENTIONED ABOVE ETC	New	650.00	500.00
2	TO RESPRAY AFFECTED PART	New	750.00	600.00
3	TO APPLY UNDERSEAL	New	60.00	30.00
4	TO REMOVE & REFIT OF WIRINGS	New	30.00	30.00
	Gross Labor	ır Cost (S\$)	1,490.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >