

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19021160/FKA3N2**Date:** 21/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant**Vehicle No :** SHA4645M**Insured Vehicle No :** SLQ8911L

Date of Loss: 27/11/2019

Nature of Claim: TP

Claim No: 9608218631SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA4645M**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU695223

Reg. Date: 22/12/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU097306

Colour: Blue

Odometer: 403468 km

Engine Capacity: 1685 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	775.20	692.40	82.80	10.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	740.00	140.00	15.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,655.20	1,432.40	222.80	13.46
+ GST 7.00/7.00% (S\$)	115.86	100.27	15.59	13.46
Nett Amount (S\$)	1,771.06	1,532.67	238.39	13.46
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$112.67/day) (S\$)		225.34		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,865.50		
Global Sum Settlement (S\$)		1,850.00		

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 29/11/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER ASSY -RR BUMPE	Cracked	553.00 FL	*553.00 FL	
2	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL	
3	1		*COVER -RR BUMPER LWR	Scratched	228.00 FL	*228.00 FL	
4	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS	
5	1		*ABSORBER -RR BUMPER	Not Necessary	103.50 FL	*- FL	
					Sub Total (\$\$)	956.50	853.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	181.30	160.60
					Total Parts (\$\$)	775.20	692.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	300.00	240.00
2	SPRAYPAINT CHARGE	New	200.00	200.00
3	CHECK ALL LIGHTING	New	50.00	20.00
4	RENEW ADVERTISEMENT BUMPER STICKER	New	50.00	50.00
5	RENEW ADVERTISEMENT FENDER STICKER	New	200.00	200.00
6	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$)			880.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >