

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021163/KHA3Q2

Date: 15/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082065

Claimant
Vehicle No : SMA6532H **Insured Vehicle No :** SMK1938B

Date of Loss: 04/11/2019 Nature of Claim: TP Claim No: 2933895921SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6532H		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Engine No:	2ZR6907930
Reg. Date:	14/06/2018 (Man. Year: 2016)	Chassis No:	ZVW508036536
Colour:	Metallic Grey	Odometer:	92047 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,940.37	831.39	4,108.98	83.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	800.00	620.00	43.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,360.37	1,631.39	4,728.98	74.35
+ GST 7.00/7.00% (S\$)	445.23	114.20	331.03	74.35
Nett Amount (S\$)	6,805.60	1,745.59	5,060.01	74.35
+ Car Rental (4.0 x S\$79.00/day) (S\$)		316.00		
+ Doc/Search Fee (S\$)		7.48		
Nett Liability (S\$)		2,069.07		

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 02/12/2019 Inspected At:

385 SIN MING DRIVE
Repairer: Esteem Performance Pte Ltd
(HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Serviceable	2,531.60 FL	*- FL
2	1		*FRONT BUMPER	Repair	450.80 FL	*- FL
3	10		*FRONT BUMPER CLIP	Not Necessary	40.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT -UPPER	Repair	711.50 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	107.20 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	107.20 FL	*- FL
7	1		*FRONT BUMPER UPPER GRILLE	Serviceable	321.90 FL	*- FL
8	1		*FRONT BUMPER EMBLEM	Serviceable	87.10 FL	*- FL
9	1		*FOG LAMP RH	Serviceable	910.70 FL	*- FL
10	1		*RH FRONT FENDER	Bent	868.70 FL	*868.70 FL
11	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	185.64 FL	*- FL
12	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	25.00 FL	*- FL
13	1		*RHF FENDER WORDING HYBRID	Necessary	44.17 FL	*44.17 FL
14	1		*RH FRONT HUB CAB	Dented	195.65 FL	*195.65 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,587.16	1,108.52
- List Item Discount on L Items 25.00/25.00% (\$)	1,646.79	277.13
Total Parts (\$)	4,940.37	831.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER)	New	600.00	300.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER)	New	600.00	400.00
3	TO CHECK WIRING	New	50.00	10.00
4	TO TUFF COAT	New	50.00	30.00
5	TO DO WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			1,420.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >