

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19021165/AGA3Q2

Date: 28/04/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0003414
Claimant Vehicle No :	SKQ6859E	Insured Vehicle No :	SMP6333L
Date of Loss:	27/11/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001543

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ6859E	Engine No:	D4162T2989326
Make & Model:	VOLVO V40, 1.6 (A)	Chassis No:	YV1MV845BF2188665
Reg. Date:	19/12/2014 (Man. Year: 2014)	Odometer:	120948 km
Colour:	Blue		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,787.00	6,784.05	6,002.95	46.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,000.00	2,110.00	51.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,897.00	8,784.05	8,112.95	48.01
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	16,897.00	7,000.00	9,897.00	58.57
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/11/2019	
Date Inspected:	28/11/2019 Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2020)
Parts:	144	VOLVO V40 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ6859E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,782.00 F	*1,782.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
3	1		*FRONT L/H BUMPER SIDE RETAINER	Damaged	86.00 F	*86.00 FL
4	1		*FRONT L/H BUMPER FOG LAMP	Not Necessary	285.00 F	*- FL
5	1		*FRONT L/H HEADLAMP	Cut	1,280.00 F	*1,280.00 FL
6	1		*FRONT L/H HEADLAMP LOWER BRACKET	Cracked	68.00 F	*68.00 FL
7	1		*FRONT L/H FENDER	Distorted	982.00 F	*982.00 FL
8	1		*FRONT L/H FENDER COWLING	Deformed	182.00 F	*182.00 FL
9	8		*FRONT L/H FENDER COWLING CLIP	Necessary	52.00 F	*30.00 FL
10	1		*FRONT L/H SIDE MIRROR ASSY	Not Necessary	785.00 F	*- FL
11	1		*FRONT L/H TYRE	Not Necessary	350.00 F	*- FL
12	1		*FRONT L/H RIM	Cut	1,080.00 FS	*800.00 FS
13	1		*FRONT L/H LOWER ARM	Bent	278.00 F	*278.00 FL
14	1		*FRONT L/H UPPER ARM	Not Necessary	299.00 F	*- FL
15	1		*FRONT L/H TRAILING ARM	Not Necessary	302.00 F	*- FL
16	1		*FRONT L/H KNUCKLE ARM	Damaged	695.00 F	*695.00 FL
17	1		*FRONT L/H KNUCKLE ARM BEARING	Necessary	294.00 F	*294.00 FL
18	1		*FRONT L/H SHOCK ABSORBER	Bent	592.00 F	*592.00 FL
19	1		*FRONT L/H DRIVE SHAFT	Not Necessary	1,295.00 F	*- FL
20	1		*FRONT STEERING RACK	Not Necessary	2,035.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,787.00	7,099.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	314.95
Total Parts (\$\$)	12,787.00	6,784.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT UNDERCARRIAGE ,DRIVE SHAFT & STEERING RACK	New	480.00	220.00
2	TO RESET COMPUTER	New	280.00	150.00
3	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	50.00
6	TOWING FEE	New	150.00	120.00
7	PANEL BEATING	New	1,400.00	600.00
8	SPRAY PAINTING	New	1,400.00	750.00
Gross Labour Cost (\$\$)			4,110.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >