

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19021172/KHA3Q2**Date:** 28/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBG852Y **Insured Vehicle No :** SLH1931Y

Date of Loss: 04/10/2019 Nature of Claim: TP Claim No: 2151723423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG852Y**

Make & Model: NISSAN NV200, 1.5 D ABS AIRBAG 2WD 6DR (M) Engine No: K9KC400D056418

Reg. Date: 30/05/2017 (Man. Year: 2016) Chassis No: VSKYBAM20Z0139993

Colour: White Odometer: 54914 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,794.51	4,591.83	1,202.68	20.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,390.00	1,590.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,774.51	5,981.83	2,792.68	31.83
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	8,774.51	4,750.00	4,024.51	45.87
+ GST 7.00/7.00% (S\$)	614.22	332.50	281.72	45.87
Nett Amount (S\$)	9,388.73	5,082.50	4,306.23	45.87
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		5,911.50		
Global Sum Settlement (S\$)		5,910.00		

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 02/12/2019 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE L/H	Bent	1,413.10 FN	*1,413.10 FN
2	1		*NISSAN LOGO	Necessary	58.70 FN	*58.70 FN
3	1		*NV200 EMBLEM	Necessary	137.50 FN	*137.50 FN
4	1		*TAIL GATE LOCK L/H	Repair	175.50 FN	*- FN
5	1		*TAIL GATE R/H	Bent	1,193.70 FN	*1,193.70 FN
6	1		*TAIL GATE LOCK R/H	Repair	175.20 FN	*- FN
7	1		*TAIL GATE RUBBER SEAL R/H (50%)	Cut	148.05 FS	*82.25 FS
8	1		*TAIL GATE INNER TRIM R/H	Serviceable	245.10 FN	*- FN
9	1		*REAR BUMPER SPONGE	Cracked	183.80 FN	*183.80 FN
10	2		*REAR BUMPER BRACKET	Repair	126.40 FN	*- FN
11	1		*REAR BUMPER	Buckled / Cut	770.80 FN	*770.80 FN
12	1		*REAR END PANEL	Bent	335.60 FN	*335.60 FN
13	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
14	1		*5 PAX STICKER	Necessary	15.00 FS	*15.00 FS
15	1		*REAR W/SCREEN SEALANT L/H	Necessary	65.00 FS	*40.00 FS
16	1		*REAR W/SCREEN MOULDING L/H	Not Necessary	135.00 FS	*- FS
17	1		*REAR BODY WEATHERSTRIP (50%)	Distorted / Dented	173.80 FS	*86.90 FS
18	6		*REAR BUMPER CLIP	Necessary	28.80 FS	*28.80 FS
19	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR W/SCREEN SEALANT R/H	Necessary	65.00 FS	*40.00 FS
21	1		*ADVERTISEMENT ON TAIL GATE R/H	Necessary	280.00 FS	*280.00 FS
22	1		*COMPANY TEL NO.AND LETTERING ON L/H	Necessary	120.00 FS	*120.00 FS
23	1		*REAR W/SCREEN MOULDING R/H	Not Necessary	135.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	6,276.05	5,001.15
- Nett Item Discount on N Items 10.00/10.00% (S\$)	481.54	409.32
Total Parts (S\$)	5,794.51	4,591.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER TAIL GATE COMPONENTS TO NEW GATE L/H	New	150.00	60.00
2	TRANSFER TAIL GATE COMPONENTS TO NEW GATE R/H	New	150.00	60.00
3	REMOVE & REINSTALL TAIL GATE REAR W/SCREEN R/H & L/H	New	360.00	160.00
4	RUST PROOFING TREATMENT	New	120.00	60.00
5	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,100.00	550.00
6	TO KNOCK AND STRAIGHTEN REAR CHASSIS FRAME ,CUT OFF REAR END PANEL AND CHANGE ALL NECESSARY PARTS	New	1,100.00	500.00
Gross Labour Cost (\$\$)			2,980.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >