

ASS. REC. BY: Sun Pin

REF:

NTUC NS/INC 1902173/af307

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJW 18147Policy No. 5111585315 (01/08/2019 - 31/07/2020)

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 6426A Yr Regn: 19/12/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota PRIUS 4 c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading 307520 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTRKB3FUX03578944

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 28/11/2019 D.O.I. 29/11/2019Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHD 6426A - CC3/CTE 1900/1020/3003 120A - 24/01/2019 TP

SJW 18147 - NA / CTI 18147/15781/24 200 - 26/03/2019 TAX/11/19/2132

SJW 18147

SHA 555R

Confirm with Poh Suan

Finalize \$9325.96 @ 7 days (P/P) chkd @ 27159.38, 24%

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: TRLump Sum / L.E.D.: 9325.96Days Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 160

Transportation:

S + RS: \$

Photos

Others

TOTAL

160

Shiau Chan (LKKAUTO)

From: MTCL@income.com.sg
Sent: Thursday, 26 December 2019 2:01 PM
To: Shiau Chan (LKKAUTO)
Subject: FW: REQUEST CLAIM NUMBER

Dear all,

Claim created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 26 December 2019 11:30 AM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

TP Claims against NTUC Income: Follow-Through Survey

Date : 26/12/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.
1	MT/1073437-002	SMRT TAXIS PTE LTD	SHD 6426A	SJW 1814Y	

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident:
Vehicle No. (For Motor): Certificate Number:

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5111585315		EC CARZ RENTAL	53353843B	GPC	Third Party	SJW1814Y	SJW1814Y	01/08/2019	31/07/2020

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6426A
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8280428
Chassis No.:	JTDKB3FUX03578944
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$25,802.00
Total Rebate Amount:	\$29,552.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2019 13:11
Date Of Accident	28/11/2019 08:20
Exact Location Of Accident	CTE TOWARDS SLE EXIT TO YIO CHU KANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6426A
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	HOE LAI HOCK MICHAEL
NRIC No	S1538748C
Date Of Birth	05/04/1962
Occupation	OUTDOOR
Date Of Driving Pass	01/06/1987
Driving Experience	32 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	575
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CTE TOWARDS SLE EXIT TO YIO CHU KANG WITH ONE MALE INDIAN PASSENGER, THE FRONT VEHICLE SHA555R SLOW DOWN AND STOPPED , I APPLY MY BRAKE AND I FELT AN IMPACT FROM MY REAR, DUE TO THE IMPACT MY VEHICLE MOVE FORWARD AND HIT THE FRONT VEHICLE SHA555R. I ALIGHTED AND CHECKED MY VEHICLE INVOLVED IN THE CHAIN COLLISION . THE REAR VEHICLE SJW1814Y HAD HIT ONTO MY REAR OF MY TAXI. NO INJURY

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW1814Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ROY LEK WEI ZHUANG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHA555R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

MOHAMMAD BAHARIN BIN ISMAIL

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

	CTE TOWARDS SLE						B	A	C	YIO CHU KANG EXIT
A - SHD 6426A →	-	-	-	-	-					
R B - SJW 1874 Y →	-	-	-	-	-	-	-	-	-	
T C - SHK 555 R →	-	-	-	-	-	-	-	-	-	
→	-	-	-	-	-	-	-	-	-	
→	-	-	-	-	-	-	-	-	-	
→	-	-	-	-	-	-	-	-	-	

[illegible]

[Signature] 28/1/19
Reporting Centre Personnel's Signature
Name:

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :

TAX/11/19/2132

Type of Repair : Accident Repair

Vehicle Registration Number : SHD6426A

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9532-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 28/11/2019 12:20 AM

Vehicle Age(In Months) : 23

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	✓ CR4
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.00	82.00	25.00	61.72	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Giv	✓ X SVC
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace	✓ SCH
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Giv	✓ X SVC
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	✓ 1/3 NEC
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Giv	✓ X SVC
One Time Key In	Main			CLIPS PIECE, FRT & RH BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ NEC

Total Spare Part Cost 22,290.02

Surveyor Total 6,628.90

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 22,290.02

Final Sur Total 6,628.90

SMRT Recommendation										Surveyor Approval				
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER, ENGINE UNDER, REAR	1	36.50	36.50	25.00	27.38	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace * /	CRA
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check * X	SVC
One Time Key In	Main			MIRROR OUTER GLASS, LH	1	143.10	143.10	25.00	107.32	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER, OUTER MIRROR HOLE, LH	1	63.80	63.80	25.00	47.85	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			COVER, OUTER MIRROR, LH NO.2	1	39.40	39.40	25.00	29.55	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	1,243.90	25.00	932.93	Replace	0	0	Not Giv. * X	SVC
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Giv. * X	SVC

Total Spare Part Cost 22,290.02

Surveyor Total 6,628.90

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 22,290.02

Final Sur Total 6,628.90

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	576.00	25.00	432.00	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Check	X SVC
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	697.20	Replace	/ BD
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	X SVC
One Time Key In	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Check	X SVC
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	25.00	339.08	Replace	1	339.08	Replace	/ Jamed
One Time Key In	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	29.90	25.00	22.42	Replace	1	22.42	Replace	/ NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	29.90	25.00	22.42	Replace	1	22.42	Replace	/ NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	1	14.77	Replace	✓ NEC
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.10	Replace	/ BT
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	/ CR 4.
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	/ BR
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	/ SCH

Total Spare Part Cost 22,290.02

Surveyor Total 6,628.90

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 22,290.02

Final Sur Total 6,628.90

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	/ SCH
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ Nec
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	/ short
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	1	175.73	Replace	/ CR4
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	1	166.95	Replace	/ CRA
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	472.35	Replace	/ DP
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SUPPORT S/A UPPER,	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	833.10	833.10	25.00	699.83	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER , LH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			LAMP ASSY, SIDE MIRROR TURN SIGNAL , LH	1	162.20	162.20	10.00	145.98	Replace	0	0	Not Giv	X SVC

Total Spare Part Cost 22,290.02

Surveyor Total 6,628.90

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 22,290.02

Final Sur Total 6,628.90

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,283.90	1,283.90	10.00	1,155.51	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	89.50	89.50	25.00	67.13	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ NEC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	X SVC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Check	X SVC
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	/ NEC.
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	/ CRU
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Giv	X RPT

Total Spare Part Cost 22,290.02

Surveyor Total 6,628.90

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 22,290.02

Final Sur Total 6,628.90

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Giv	X RPT
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Check	X SVC
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	/ Nec
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00 -6.00	Replace	/ Nec
Total Spare Part Cost									22,290.02	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									22,290.02	Final Sur Total				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	576.00	200	/
2	Main	TO REPAIR REAR PORTION	576.00	500	/
Total:			1,152.00 2152	700.00 1200	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	/
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
4	Main	TO RESPRAY APRON PANEL LH	180.00	0	
5	Main	RESPRAY MIRROR COVER LH	180.00	0	
6	Main	TO RESPRAY FRONT DOOR LH	378.00	0	
7	Main	TO RESPRAY REAR DOOR LH	378.00	0	
8	Main	TO RESPRAY RIM	180.00	0	
9	Main	TO RESPRAY REAR FENDER LH	378.00	0	
Total:			4,626.00 5346	920.00 1300	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
10	Main	TO RESPRAY TAIL GATE	378.00	200	
11	Main	TO RESPRAY REAR SPOILER	180.00	0	
12	Main	TO RESPRAY BUMPER BEAM	180.00	80	
13	Main	TO RESPRAY REAR BUMPER	378.00	200	
14	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	90	
15	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
16	Main	TO RESPRAY REAR PANEL	180.00	80	
17	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
18	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	90	
Total:			4,626.00	920.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	80	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
5	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
6	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
7	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
8	Main	TO REPLACE SUNDRY PARTS	100.00	20	
9	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
10	Main	TO WASH AND VACUUM	60.00	0	
11	Main	TOWING CHARGE	56.00	0	
Total:			1,116.00	160.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	22,290.02	6,628.90
Total Labour Cost	1,352.00	700.00
Total Spray Painting	4,628.00	920.00
Other	1,116.00	160.00
Overall Total	29,384.02	8,408.90
Lump Sum Repair Option	☒	☐
Lump Sum Total	29,400.00	8,408.90
Surveyor Approved Amount		8,408.90
No of Repair Days*	10	5
Remarks	-	P/P Repair. Take before spray photo.
Surveyor Name		Sun Pin (LKK)
Signature		 2/12/19
Survey Date	29/11/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

36485.34

36485.34

Section A - Accident Details

Registration Number	SHD6426A
Case Reference Number	TAX/11/19/2132
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HOE LAI HOCK MICHAEL
Type of Accident	Head to Rear
Accident Date and Time	28/11/2019 8:20 AM
Accident Reported Date and Time	28/11/2019 11:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	28/11/2019 10:05 AM
Replacement Vehicle issued?	No
Job Card Number	24104609
Special Instruction to ARC, if any	FRONT AND REAR PORTION DAMAGE
Prepared Date and Time	28/11/2019 5:42 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,152.00	\$1,200.00
Total Spray Cost	\$5,346.00	\$1,300.00
Total Spare Part Cost	\$22,290.02	\$0,665.96
Total Other Cost	\$1,116.00	\$160.00
TOTAL COST	\$30,904.02	\$9,325.96 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	7.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	09/12/2019 9:29 AM	07/12/2019 1:44 PM
Signature		
Remarks	Total number of repair days = 7 days. SUP = + 2 days.	P/P Repair, Take before spray photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0325	Invoice Number	
Quotation Date	21.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$676.00	\$200.00
TO REPAIR REAR PORTION	\$676.00	\$500.00
TO REPAIR REAR SPARE TYRE PANEL	\$200.00	\$100.00 <i>supp</i>
TO REPAIR PANEL SIDE ROOF LH	\$150.00	\$100.00 <i>supp</i>
TO REPAIR PANEL SIDE ROOF RH	\$150.00	\$100.00 <i>supp</i>
TO REPAIR REAR CHASSIS	\$300.00	\$200.00 <i>supp</i>
Total Labour	\$2,152.00	\$1,200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY REAR DOOR LH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$60.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$90.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$80.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$90.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00 <i>supp</i>
TO RESPRAY PANEL SIDE ROOF RH	\$180.00	\$100.00 <i>supp</i>
TO RESPRAY REAR BOTH MEMBERS	\$180.00	\$80.00 <i>supp</i>
TO RESPRAY PANEL SIDE ROOF LH	\$180.00	\$100.00 <i>supp</i>
Total Spray Painting & Panel Beating	\$5,345.00	\$1,300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$0.00
Total Other Costs	\$1,116.00	\$160.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace ✓
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check X
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check X
		52127479 07	COVER, FR BUMPER RH	0.00	\$26.10	0.00	\$0.00	Replace	Not Given X
		52128479 08	COVER, FR BUMPER LH	1.00	\$26.10	25.00	\$21.08	Replace	Replace ✓
		52114471 90	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Check X
		53395470 40	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Not Given X
		75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace ✓
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given X
		52161180 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace ✓
		52535500 60	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given X
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given X
		51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given X
		51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given X
		51443470 20	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given X
		51444470 10	COVER, ENGINE UNDER SIDE LH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given X
		51442470 30	COVER, ENGINE UNDER, REAR	0.00	\$36.50	0.00	\$0.00	Replace	Not Given X
		53101470 80	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given X
		81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace ✓
		81056476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check X
		87961474 40	MIRROR OUTER GLASS, LH	0.00	\$143.10	0.00	\$0.00	Replace	Not Given Y
		87948472 50	COVER, OUTER MIRROR HOLE, LH	0.00	\$63.80	0.00	\$0.00	Replace	Not Given X
		87948472 50	COVER, OUTER MIRROR, LH NO.2	0.00	\$39.40	0.00	\$0.00	Replace	Not Given X
		87002471 52	PANEL SUB-ASSY, FRONT DOOR LH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
55 Woodlands Industrial Park S4, Singapore 737788
FAX Number : 63446522
Estimator Telephone Number : 68828221
Accident Reporting Number : 68823072

Date Generated : 24/12/2018

User ID : Pothuan

6700447210	PANEL SUB-ASSY, REAR DOOR, LH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given	X
4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	Y
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	Y
7566047900	MOULDING ASSY, BODY ROCKER PANEL, LH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given	Y
6160247160	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.80	0.00	\$0.00	Replace	Check	Y
6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$929.80	25.00	\$697.20	Replace	Replace	Y
7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	Y
6775047080C0	TAILGATE BOARD ASSY	0.00	\$251.50	0.00	\$0.00	Replace	Check	X
6935047050	TAIL GATE LOCK ASSY, BACK DOOR	1.00	\$452.10	25.00	\$339.08	Replace	Replace	Y
6943052050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	Y
7608547916	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X
7557447040	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$29.90	25.00	\$22.43	Replace	Replace	Y
7557347110	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$29.90	25.00	\$22.43	Replace	Replace	Y
7557547051	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$19.70	25.00	\$14.78	Replace	Replace	Y
5202347030	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace	Y
5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	Y
5256647900	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	Y
5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	Y
8156147010	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	Y
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	Y
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	Y
5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check	X
5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$234.30	25.00	\$175.73	Replace	Replace	Y
6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$168.95	Replace	Replace	Y
5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$629.80	25.00	\$472.35	Replace	Replace	Y
8122047020	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X
5320547900	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Not Given	Y
5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	Y
5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	Y
5302647010	SUPPORT SUB-ASSY, LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Not Given	Y
5380247100	FENDER SUB-ASSY, FR, LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	Y
5370247101	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Not Given	Y
8174047010	LAMP ASSY, SIDE MIRROR TURN SIGNAL, LH	0.00	\$162.20	0.00	\$0.00	Replace	Not Given	Y
8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given	X
8794547060A1	COVER, OUTER MIRROR, LH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given	Y
5246247030	PAD, RR BUMPER, RH & LH, 1	1.00	\$3.80	25.00	\$2.85	Replace	Replace	Y
5246247020	PAD, RR BUMPER, RH & LH, 2	1.00	\$3.80	25.00	\$2.85	Replace	Replace	Y
5246247010	PAD, RR BUMPER, RH & LH, 3	1.00	\$3.80	25.00	\$2.85	Replace	Replace	Y
5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check	X
5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Check	X

	5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	
	5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	X
	5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	X
	5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
	8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	8155147151	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	8158147010	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	8159147010	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	5831147130	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Check	X
		SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	
		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	
Total				\$27,710.34		\$6,665.96			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

7 days

P/P

9325.96

6665.96
+ 1200.00
+ 1460.00

9325.96

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX / 11 / 19 / 2132	Date of Collection	2 / 12 / 19
Vehicle No	SHD 6426 A	Date of Request	4 / 12 / 19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	3 DAYS - 2 days

S/N	Part Number	Part Description	Quantity	Unit Price	
	4636,37,38,39	To Repair Spare Tyre Panel		\$ 200.00	100 /
	4640,41,42	To Repair LH Side Roof Panel		\$ 150.00	100 /
	4643,44,45	To Repair RH Side Roof Panel		\$ 150.00	100 /
	4646,47,48	To Repair Rear RH & LH Chassis Member		\$ 300.00	200 /
		To Respray Spare Tyre Panel		\$ 150.00	100 /
		To Respray LH Side Roof Panel		\$ 150.00	100 /
		To Respray RH Side Roof Panel		\$ 150.00	100 /
		To Respray Rear RH & LH Chassis Member		\$ 180.00	80 /

<<< Please submit photographs for damaged parts >>>

I, (Name) CHIA

(Position) _____

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

..........

Signature of person making this declaration
[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PU / WOC / Reservation Number
Photo Submitted	YES / NO	Date of submission

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19021178/Qqf3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 16-01-2020	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJW 1814Y	Veh. Inspected	SHD 6426A
Policy No.	5111585315	Coverage (\$)	0.00
Claim No.	MT/1073437-002	Excess (\$)	0.00
Assign From		Assign Date	29/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FUX03578944	Colour	MAROON
Odometer	307520	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/11/2019	Inspection Date	29/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6426A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, FR BUMPER (DISC 25%)	CRUMPLED	495.50	371.63
1	COVER, FR BUMPER LH (DISC 25%)	SCRATCHED	28.10	21.08
1	EMBLEM ASSY FRONT (DISC 25%)	NECESSARY	87.10	65.33
10	CLIPS PIECE, FRT BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	DENTED	929.60	697.20
1	TAIL GATE LOCK ASSY, BACK DOOR (DISC 25%)	JAMMED	452.10	339.08
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH (DISC 25%)	NECESSARY	29.90	22.43
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH (DISC 25%)	NECESSARY	29.90	22.43
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	19.70	14.78
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	COVER, RR BUMPER ASSY (DISC 25%)	CRUMPLED	423.90	317.93
1	FILLER, RR BUMPER, LH (DISC 25%)	BROKEN	119.90	89.93
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	SCRATCHED	14.80	11.10
1	COVER, REAR FLOOR UNDER, LH (DISC 25%)	CRUSHED	234.30	175.73
1	COVER, REAR FLOOR UNDER CENTER (DISC 25%)	CRACKED	222.60	166.95
1	END PANEL SUB-ASSY, BODY LOWER BACK (DISC 25%)	DENTED	629.80	472.35
2	PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	NECESSARY	3.80	2.85
2	PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	NECESSARY	3.80	2.85
2	PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	NECESSARY	3.80	2.85
10	CLIPS PIECE, RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CRUMPLED	558.30	418.73
1	UNIT, HEADLAMP, LH (DISC 10%)	CRACKED	2,558.90	2,303.01
1	LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	SCRATCHED	486.80	438.12
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SUPPORT, FR BUMPER RH	SERVICEABLE	76.90	-

Report Ref No. NS/INC19021178/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT, FR BUMPER LH	SERVICEABLE	82.30	-
1	COVER, FR BUMPER RH	SERVICEABLE	28.10	-
1	BRACKET, FR BUMPER	SERVICEABLE	99.80	-
1	SEAL, HOOD TO FR END	SERVICEABLE	24.40	-
1	GRILLE, RADIATOR	SERVICEABLE	165.00	-
2	RETAINER, FR BUMPER, LH & RH	SERVICEABLE	8.50	-
1	COVER ASSY, ENGINE	SERVICEABLE	180.10	-
1	SET COVER ASSY, ENGINE UNDER CENTER	SERVICEABLE	452.80	-
1	COVER, ENGINE UNDER CENTER	SERVICEABLE	94.50	-
1	COVER, ENGINE UNDER SIDE RH	SERVICEABLE	76.90	-
1	COVER, ENGINE UNDER SIDE LH	SERVICEABLE	76.90	-
1	COVER, ENGINE UNDER, REAR	SERVICEABLE	36.50	-
1	GRILLE SUB-ASSY	SERVICEABLE	335.60	-
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	SERVICEABLE	486.40	-
1	MIRROR OUTER GLASS, LH	SERVICEABLE	143.10	-
1	COVER, OUTER MIRROR HOLE, LH	SERVICEABLE	63.80	-
1	COVER, OUTER MIRROR, LH NO.2	SERVICEABLE	39.40	-
1	PANEL SUB-ASSY, FRONT DOOR LH	SERVICEABLE	1,249.60	-
1	PANEL SUB-ASSY, REAR DOOR, LH	SERVICEABLE	1,243.90	-
1	WHEEL, DISC	SERVICEABLE	1,555.10	-
1	TYRE	SERVICEABLE	126.74	-
1	MOULDING ASSY, BODY ROCKER PANEL, LH	SERVICEABLE	576.00	-
1	PANEL SUB-ASSY, FENDER REAR LH	SERVICEABLE	824.80	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	SERVICEABLE	891.20	-
1	TAILGATE BOARD ASSY	SERVICEABLE	251.50	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	SERVICEABLE	24.90	-
1	SPOILER, SUB-ASSY, REAR	SERVICEABLE	1,322.10	-
1	LENS & BODY ASSY, RR BUMPER, RH	SERVICEABLE	486.80	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	LAMP ASSY, FOG, LH	SERVICEABLE	910.20	-
1	SUPPORT S/A UPPER,	SERVICEABLE	364.90	-
1	SUPPORT S/A RH	SERVICEABLE	237.00	-
1	SUPPORT S/A LH	SERVICEABLE	237.00	-

Report Ref No. NS/INC19021178/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT SUB-ASSY LOWER	SERVICEABLE	397.40	-
1	FENDER SUB-ASSY, FR, LH	SERVICEABLE	933.10	-
1	APRON SUB-ASSY, FRONT FENDER, LH	SERVICEABLE	944.20	-
1	LAMP ASSY, SIDE MIRROR TURN SIGNAL, LH	SERVICEABLE	162.20	-
1	MIRROR ASSY, OUTER REAR VIEW, LH	SERVICEABLE	1,283.90	-
1	COVER, OUTER MIRROR, LH	SERVICEABLE	89.50	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	RETAINER, RR BUMPER, LH	SERVICEABLE	111.50	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	438.10	-
1	LENS & BODY, REAR COMBINATION LAMP, LH	SERVICEABLE	438.10	-
1	SPARE TYRE PANEL, PAN, REAR FLOOR	SERVICEABLE	564.80	-
1	LENS & BODY ASSY, RR BUMPER, RH	REPEATED	486.80	-
1	LENS & BODY ASSY, RR BUMPER, LH	REPEATED	486.80	-
			27,871.34	6,665.96
LABOUR				
	PANEL BEATING & BODY WORK.		2,152.00	1,200.00
	SPRAY PAINT.		5,346.00	1,300.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	60.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-

Report Ref No. NS/INC19021178/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGE.	NOT NECESSARY	56.00	-
			8,614.00	2,660.00
	GRAND TOTAL		36,485.34	9,325.96
RECOMMENDED COST OF REPAIRS (CONFIRMED)				9,325.96

Report Ref No. NS/INC19021178/Qqf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.