

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Apr 2015 15:33 Edit Reg		14 Apr 2015 00:00 Edit Adj Rpt	S\$19,600.00 Edit Estimates	S\$19,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Tan Keng Wan , ID: S1157860H, Tel: +6598769229									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.: SHD5090R		Date of Loss: 10/04/2015 01:00 - :59 [66 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2975344266SG		Policy/Cover Note No.: 2100295716 (Comprehensive) Coverage: 30/03/2015 - 29/03/2016							
Vehicle Reg. No. (Insured): SKE7469D		Policy No. (Claimant): D-12047359MFSH/2102							
Excess:									
Repairer: Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Rparthiban, Theerthan] Theerthan.Parthiban@aig.com									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/12/2019]									
Driver/Custodian (Insured): TAN HONGSHEN MARK (), NRIC: S8614424G Email:									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (16/03/2020): Alert - Adj Mandate Approved (S\$11841.81) - SHD5090R - Claim Handler: Rparthiban... - AIG_SG (28/11/2019): Report Send Back Alerts - SHD5090R (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD5090R (2975344266SG)**
[SKE7469D]
TP
TRANS-CAB SERVICES PTE LTD
Apr 10 2015 1:00AM
[Tan Keng Wan]
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)
▼

Letters/Correspondences

1 per page ▼

☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page ▼

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/04/15 14:37	General View		Load JPG	☒
2	17/04/15 14:37	General View		Load JPG	☒
3	17/04/15 14:37	General View		Load JPG	☒
4	17/04/15 14:37	General View		Load JPG	☒
5	17/04/15 14:37	General View		Load JPG	☒
6	17/04/15 14:37	General View		Load JPG	☒
7	17/04/15 14:37	General View		Load JPG	☒
8	17/04/15 14:37	General View		Load JPG	☒
9	17/04/15 14:37	General View		Load JPG	☒
10	17/04/15 14:37	General View		Load JPG	☒
11	17/04/15 14:37	General View		Load JPG	☒
12	17/04/15 14:37	General View		Load JPG	☒
13	17/04/15 14:37	General View		Load JPG	☒
14	17/04/15 14:37	General View		Load JPG	☒
15	17/04/15 14:37	General View		Load JPG	☒
16	17/04/15 14:38	General View		Load JPG	☒
17	17/04/15 14:38	General View		Load JPG	☒
18	17/04/15 14:38	General View		Load JPG	☒
19	17/04/15 14:38	General View		Load JPG	☒
20	17/04/15 14:38	General View		Load JPG	☒
21	17/04/15 14:38	General View		Load JPG	☒
22	17/04/15 14:38	General View		Load JPG	☒
23	17/04/15 14:38	General View		Load JPG	☒
24	17/04/15 14:38	General View		Load JPG	☒
25	17/04/15 14:38	General View		Load JPG	☒
26	17/04/15 14:38	General View		Load JPG	☒
27	17/04/15 14:38	General View		Load JPG	☒
28	17/04/15 14:38	General View		Load JPG	☒
29	17/04/15 14:38	General View		Load JPG	☒
30	17/04/15 14:38	General View		Load JPG	☒
31	17/04/15 14:38	General View		Load JPG	☒
32	17/04/15 14:38	General View		Load JPG	☒
33	17/04/15 14:38	General View		Load JPG	☒
34	17/04/15 14:38	General View		Load JPG	☒
35	17/04/15 14:38	General View		Load JPG	☒
36	17/04/15 14:38	General View		Load JPG	☒
37	17/04/15 14:38	General View		Load JPG	☒

Letters/Correspondences				1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	17/04/15 14:38	General View	1	Load JPG	✓

Documentation				1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/04/15 14:36	TP GIA & POLICE REPORT	1	Load PDF	
2	12/05/16 20:25	EMAIL TO WP REPORT	1	Load PDF	
3	13/05/16 14:14	LETTER TO OI	1	Load PDF	
4	18/12/19 10:56	LOD, FINAL INVOICE, RENTAL SUPPORTING DOCS,ATA, LTA SEARCH	1	Load PDF	
5	18/12/19 11:40	EMAIL TO AIG - MANDATE REQUEST	1	Load PDF	
6	15/04/20 11:25	Authorisation to Act	1	Load PDF	
7	15/04/20 11:25	LOD	1	Load PDF	
8	15/04/20 11:25	LTA SEARCH	1	Load PDF	
9	15/04/20 11:25	Release Voucher	1	Load PDF	
10	15/04/20 11:25	RENTAL MILEAGE	1	Load PDF	
11	15/04/20 11:25	RENTAL RECEIPT	1	Load PDF	
12	15/04/20 11:25	WORKSHOP INVOICE	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	16/04/15 09:22	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKE7469D (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SHD5090R (TP veh)		
Date of Accident:	10/04/2015		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	: \$	139,222.66	
Final Repair Cost	: \$	11,800.00	
Loss of Use	: \$	_____ days at \$0.00 per day	
Rental (if any)	: \$	29 days	
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	11,800.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u>:		Agreed Liability _____ 50 _____ (%)	
B) For <u>GIA Registered Workshop</u>:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	: \$	11,800.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

15 Apr
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG15006369/KKA3S2-1**Date:** 15/04/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100295716
Claimant Vehicle No :	SHD5090R	Insured Vehicle No :	SKE7469D
Date of Loss:	10/04/2015	Nature of Claim:	TP
		Claim No:	2975344266SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5090R		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ3238627
Reg. Date:	30/09/2009 (Man. Year: 2009)	Chassis No:	JTDER12W803003147
Colour:	Red	Odometer:	0 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 3 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	91,894.64	17,555.83	74,338.81	80.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	38,220.00	6,910.00	31,310.00	81.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	130,114.64	24,465.83	105,648.81	81.20
Approved Total (Overridden) (S\$)		19,600.00		
(S\$)	130,114.64	19,600.00	110,514.64	84.94
+ GST 7.00/7.00% (S\$)	9,108.02	1,372.00	7,736.02	84.94
Nett Amount (S\$)	139,222.66	20,972.00	118,250.66	84.94
+ Car Rental (29.0 x S\$93.09/day) (S\$)		2,699.61		
(S\$)		23,671.61		
Liabe Amount (50.00%) (S\$)		11,835.81		
+ Doc/Search Fee (S\$)		6.00		
Nett Liability (S\$)		11,841.81		
Global Sum Settlement (S\$)		11,800.00		

INSPECTION

Date of Assignment:	14/04/2015	
Date Inspected:	14/04/2015	Inspected At: Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1 Singapore 729346
Estimated Period of Repair:	24.0 days	

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	487.80 FL	*487.80 FL
2	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	105.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	270.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	215.60 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	68.00 FL	*68.00 FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	68.00 FL	*- FL
7	1		*FRONT BUMPER BRACKET LH	Not Necessary	49.00 FL	*- FL
8	1		*FRONT BUMPER BRACKET RH	Not Necessary	49.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	17.60 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	17.60 FL	*- FL
11	1		*FRONT SUPPORT PANEL ASSY	Not Necessary	1,018.60 FL	*- FL
12	1		*FRONT BRACE PANEL	Not Necessary	79.57 FL	*- FL
13	1		*HEADLAMP RH	Not Necessary	672.00 FL	*- FL
14	1		*HEADLAMP RH INNER PANEL	Not Necessary	732.00 FL	*- FL
15	1		*HEADLAMP LH	Not Necessary	672.00 FL	*- FL
16	1		*HEADLAMP LH INNER PANEL	Not Necessary	732.00 FL	*- FL
17	1		*RADIATOR ASSEMBLY	Not Necessary	1,890.20 FL	*- FL
18	1		*RADIATOR GRILLE	Not Necessary	169.80 FL	*- FL
19	1		*AIRCON CONDENSER	Not Necessary	1,098.16 FL	*- FL
20	1		*ENGINE SPLASH COVER RH	Not Necessary	148.50 FL	*- FL
21	1		*STEERING RACK & PINION ASSY	Not Necessary	2,639.44 FL	*- FL
22	1		*FRONT SHOCK ABSORBER ASSY RH	Bent	465.00 FL	*465.00 FL
23	1		*FRONT LOWER ARM RH	Not Necessary	517.14 FL	*- FL
24	1		*FRONT KNUCKLE ARM RH	Bent	408.95 FL	*408.95 FL
25	1		*STEERING RACK END RH	Not Necessary	205.21 FL	*- FL
26	1		*STEERING TIE-ROD END RH	Not Necessary	210.90 FL	*- FL
27	1		*FRONT STABILIZER BAR RH	Not Necessary	367.60 FL	*- FL
28	1		*FRONT STABILIZER BAR LINK RH	Not Necessary	155.50 FL	*- FL
29	1		*FRONT STABILIZER BAR BRACKET RH	Not Necessary	138.00 FL	*- FL
30	1		*FRONT STABILIZER BAR BUSH RH	Not Necessary	117.27 FL	*- FL
31	1		*DRIVE SHAFT RH	Not Necessary	855.25 FL	*- FL
32	1		*DRIVE SHAFT LH	Not Necessary	745.62 FL	*- FL
33	1		*FRONT SHOCK ABSORBER ASSY LH	Not Necessary	465.00 FL	*- FL
34	1		*FRONT LOWER ARM LH	Not Necessary	517.14 FL	*- FL
35	1		*FRONT KNUCKLE ARM LH	Not Necessary	408.95 FL	*- FL
36	1		*FRONT SEAT BELT RH	Jammed	718.50 FL	*718.50 FL
37	1		*FRONT SEAT BELT TENSION RH	Not Necessary	105.01 FL	*- FL
38	1		*FRONT SEAT BELT LH	Not Necessary	718.50 FL	*- FL
39	1		*FRONT SET BELT TENSION LH	Not Necessary	105.01 FL	*- FL
40	1		*FRONT FENDER RH	Bent	698.00 FL	*698.00 FL
41	1		*FRONT FENDER LINER RH	Cracked	307.62 FL	*307.62 FL
42	1		*FRONT FENDER INDICATOR LAMP RH	Serviceable	79.83 FL	*- FL
43	1		*FRONT FENDER INNER WHEEL HOUSE PANEL RH	Repair	595.72 FL	*- FL
44	1		*FRONT FENDER LH	Bent	698.00 FL	*698.00 FL
45	1		*FRONT FENDER LINER LH	Serviceable	307.62 FL	*- FL
46	1		*BONNET	Bent	849.30 FL	*849.30 FL
47	1		*BONNET UNDER WEATHERSTRIP SEAL	Serviceable	59.99 FL	*- FL
48	1		*BONNET HINGE RH	Repair	68.00 FL	*- FL
49	1		*BONNET HINGE LH	Repair	68.00 FL	*- FL
50	1		*BONNET MOULDING	Dented	161.97 FL	*161.97 FL
51	1		*BONNET LOCK	Repair	75.02 FL	*- FL
52	1		*BONNET CABLE	Serviceable	44.43 FL	*- FL
53	1		*BONNET CENTRE TOYOTA LOGO GARNISH	Not Necessary	232.40 FL	*- FL
54	1		*FRONT WINDSCREEN	Cracked	1,172.20 FL	*1,172.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*FRONT WINDSCREEN MOULDING	Necessary	72.00 FL	*72.00 FL
56	1		*FRONT WINDSCREEN PILLAR INNER LH	Repair	656.70 FL	*- FL
57	1		*FRONT WINDSCREEN PILLAR OUTER LH	Bent	766.20 FL	*766.20 FL
58	1		*FRONT PILLAR INNER GARNISH	Serviceable	239.40 FL	*- FL
59	1		*ROOM VIEW MIRROR	Serviceable	166.70 FL	*- FL
60	1		*WINDSCREEN WASHER TANK - FILLER NECK	Not Necessary	100.63 FL	*- FL
61	1		*WINDSCREEN WASHER TANK	Serviceable	138.33 FL	*- FL
62	1		*WINDSCREEN WASHER TANK MOTOR	Serviceable	222.38 FL	*- FL
63	1		*GEAR BOX ASSY	Not Necessary	16,629.60 FL	*- FL
64	1		*GEAR BOX CROSS MEMBER	Not Necessary	1,211.90 FL	*- FL
65	1		*GEAR BOX CROSS MEMBER BRACKET	Not Necessary	199.80 FL	*- FL
66	1		*GEAR BOX MOUNTING	Not Necessary	291.40 FL	*- FL
67	1		*ENGINE BLOCK	Not Necessary	7,927.34 FL	*- FL
68	1		*ENGINE MOUNTING SIDE	Not Necessary	174.65 FL	*- FL
69	1		*ENGINE OIL SUMP	Not Necessary	291.70 FL	*- FL
70	1		*ENGINE OIL SUMP STRAINER	Not Necessary	96.40 FL	*- FL
71	1		*ENGINE OVERHAUL GASKET	Not Necessary	51.20 FL	*- FL
72	1		*ENGINE OIL SUMP SEALANT	Not Necessary	85.00 FL	*- FL
73	1		*ENGINE SPLASH COVER RH	Not Necessary	148.50 FL	*- FL
74	1		*ENGINE SPLASH COVER LH	Not Necessary	148.50 FL	*- FL
75	1		*O/S FRONT DRIVER SEAT RH	Repair	2,458.45 FL	*- FL
76	1		*N/S FRONT PASSENGER SEAT LH	Repair	2,458.45 FL	*- FL
77	1		*FRONT DOOR RH	Bent	1,295.00 FL	*1,295.00 FL
78	1		*FRONT SIDE VIEW MIRROR RH	Serviceable	722.50 FL	*- FL
79	1		*FRONT DOOR OUTER MOULDING RH	Serviceable	161.40 FL	*- FL
80	1		*FRONT DOOR OUTER HANDLE RH	Serviceable	79.60 FL	*- FL
81	1		*FRONT DOOR OUTER HANDLE INNER SEAL RH	Serviceable	38.70 FL	*- FL
82	1		*FRONT DOOR OUTER KEY LOCK RH	Serviceable	216.70 FL	*- FL
83	1		*FRONT DOOR HINGE UPPER RH	Repair	96.30 FL	*- FL
84	1		*FRONT DOOR HINGE LOWER RH	Repair	96.30 FL	*- FL
85	1		*FRONT DOOR INNER LOCK RH	Jammed	426.60 FL	*426.60 FL
86	1		*FRONT DOOR INNER LOCK LATCH RH	Repair	98.20 FL	*- FL
87	1		*FRONT DOOR CHECK / ARRESTOR RH	Serviceable	200.00 FL	*- FL
88	1		*FRONT DOOR GLASS CHANNEL WEATHERSTRIP RH	Not Necessary	166.40 FL	*- FL
89	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	1,211.70 FL	*- FL
90	1		*FRONT DOOR WINDOW GLASS RH	Serviceable	399.70 FL	*- FL
91	1		*FRONT DOOR POWER MOTOR RH	Jammed	401.90 FL	*401.90 FL
92	1		*FRONT DOOR POWER MOTOR SWITCH RH	Not Necessary	361.20 FL	*- FL
93	1		*FRONT DOOR REGULATOR GEAR RH	Bent	131.80 FL	*131.80 FL
94	1		*FRONT DOOR CHANNEL FELT / MOULDING RH	Not Necessary	291.90 FL	*- FL
95	1		*FRONT DOOR BENQ LOCKER BULK RH	Not Necessary	301.20 FL	*- FL
96	1		*FRONT DOOR LH	Bent	1,295.00 FL	*1,295.00 FL
97	1		*FRONT SIDE VIEW MIRROR LH	Broken	722.50 FL	*722.50 FL
98	1		*FRONT DOOR OUTER MOULDING LH	Serviceable	161.40 FL	*- FL
99	1		*FRONT DOOR OUTER HANDLE LH	Dented	79.60 FL	*79.60 FL
100	1		*FRONT DOOR OUTER HANDLE INNER SEAL LH	Serviceable	38.70 FL	*- FL
101	1		*FRONT DOOR OUTER KEY LOCK LH	Not Necessary	216.70 FL	*- FL
102	1		*FRONT DOOR HINGE UPPER LH	Repair	96.30 FL	*- FL
103	1		*FRONT DOOR HINGE LOWER LH	Repair	96.30 FL	*- FL
104	1		*FRONT DOOR INNER LOCK LH	Jammed	426.60 FL	*426.60 FL
105	1		*FRONT DOOR INNER LOCK LATCH LH	Repair	98.20 FL	*- FL
106	1		*FRONT DOOR CHECK / ARRESTOR LH	Serviceable	200.00 FL	*- FL
107	1		*FRONT DOOR GLASS CHANNEL WEATHERSTRIP LH	Serviceable	166.40 FL	*- FL
108	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	1,211.70 FL	*- FL
109	1		*FRONT DOOR WINDOW GLASS LH	Serviceable	399.70 FL	*- FL
110	1		*FRONT DOOR POWER MOTOR LH	Not Necessary	401.90 FL	*- FL
111	1		*FRONT DOOR POWER MOTOR SWITCH LH	Not Necessary	361.20 FL	*- FL
112	1		*FRONT DOOR REGULATOR GEAR LH	Not Necessary	131.80 FL	*- FL
113	1		*FRONT DOOR CHANNEL FELT / MOULDING LH	Serviceable	291.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
114	1		*FRONT DOOR BENQ LOCKER BULK LH	Serviceable	301.20 FL	*- FL
115	1		*ROOF TOP PANEL	Repair	2,899.70 FL	*- FL
116	1		*ROOF TOP INNER SIDE PANEL OUTER LH	Bent	166.70 FL	*166.70 FL
117	1		*ROOF TOP INNER SIDE PANEL OUTER RH	Repair	166.70 FL	*- FL
118	1		*ROOF SIDE MOULDING - ROOF GULTER LH	Necessary	201.30 FL	*201.30 FL
119	1		*ROOF SIDE MOULDING - ROOF GULTER RH	Serviceable	201.30 FL	*- FL
120	1		*ROOF LINING	Serviceable	1,898.60 FL	*- FL
121	1		*CENTRE PILLAR OUTER LH	Repair	321.40 FL	*- FL
122	1		*CENTRE PILLAR INNER LH	Repair	431.70 FL	*- FL
123	1		*CENTRE PILLAR OUTER RH	Bent	321.40 FL	*321.40 FL
124	1		*CENTRE PILLAR INNER RH	Bent	431.70 FL	*431.70 FL
125	1		*CENTRE PILLAR REINFORCEMENT RH	Bent	511.90 FL	*511.90 FL
126	1		*CENTRE PILLAR INNER GARNISH - TOP RH	Not Necessary	201.70 FL	*- FL
127	1		*CENTRE PILLAR INNER GARNISH - LOWER RH	Not Necessary	296.30 FL	*- FL
128	1		*ROCKER PANEL OUTER RH	Bent	711.90 FL	*711.90 FL
129	1		*ROCKER PANEL OUTER LH	Repair	711.90 FL	*- FL
130	1		*REAR DOOR RH	Bent	1,198.00 FL	*1,198.00 FL
131	1		*REAR DOOR TOP HINGE RH	Bent	76.40 FL	*76.40 FL
132	1		*REAR DOOR BOTTOM HINGE RH	Bent	76.40 FL	*76.40 FL
133	1		*REAR DOOR INNER LOCK RH	Jammed	426.60 FL	*426.60 FL
134	1		*REAR DOOR CHECK / ARRESTOR RH	Distorted	121.40 FL	*121.40 FL
135	1		*REAR DOOR LOCK STRIKER / LATCH RH	Repair	98.20 FL	*- FL
136	1		*REAR DOOR OUTER WEATHERSTRIP MOULDING RH	Buckled	96.40 FL	*96.40 FL
137	1		*REAR DOOR OUTER HANDLE RH	Serviceable	78.40 FL	*- FL
138	1		*REAR DOOR OUTER HANDLE - RUBBER SEAL RH	Serviceable	36.40 FL	*- FL
139	1		*REAR DOOR INNER OPENING HANDLE RH	Serviceable	79.60 FL	*- FL
140	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	1,021.90 FL	*- FL
141	1		*REAR DOOR KICKING PLATE / STEP GARNISH RH	Not Necessary	231.90 FL	*- FL
142	1		*REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP RH	Not Necessary	121.30 FL	*- FL
143	1		*REAR DOOR WINDOW GLASS CHANNEL HOLDER RH	Not Necessary	101.30 FL	*- FL
144	1		*REAR DOOR CHANNEL WEATHERSTRIP / FELT RH	Not Necessary	139.70 FL	*- FL
145	1		*REAR DOOR INTERIOR LIGHT SWITCH RH	Not Necessary	96.40 FL	*- FL
146	1		*REAR DOOR REGULATOR GEAR RH	Bent	198.40 FL	*198.40 FL
147	1		*REAR DOOR REGULATOR HANDLE RH	Serviceable	96.20 FL	*- FL
148	1		*REAR DOOR LH	Bent	1,198.00 FL	*1,198.00 FL
149	1		*REAR DOOR TOP HINGE LH	Repair	76.40 FL	*- FL
150	1		*REAR DOOR BOTTOM HINGE LH	Repair	76.40 FL	*- FL
151	1		*REAR DOOR INNER LOCK LH	Jammed	426.60 FL	*426.60 FL
152	1		*REAR DOOR CHECK / ARRESTOR LH	Serviceable	121.40 FL	*- FL
153	1		*REAR DOOR LOCK STRIKER / LATCH LH	Repair	98.20 FL	*- FL
154	1		*REAR DOOR OUTER WEATHERSTRIP MOULDING LH	Buckled	96.40 FL	*96.40 FL
155	1		*REAR DOOR OUTER HANDLE LH	Dented	78.40 FL	*78.40 FL
156	1		*REAR DOOR OUTER HANDLE - RUBBER SEAL LH	Not Necessary	36.40 FL	*- FL
157	1		*REAR DOOR INNER OPENING HANDLE LH	Serviceable	79.60 FL	*- FL
158	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	1,021.90 FL	*- FL
159	1		*REAR DOOR KICKING PLATE / STEP GARNISH LH	Not Necessary	231.90 FL	*- FL
160	1		*REAR DOOR GLASS LH	Serviceable	366.70 FL	*- FL
161	1		*REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP LH	Serviceable	121.30 FL	*- FL
162	1		*REAR DOOR WINDOW GLASS CHANNEL HOLDER LH	Serviceable	101.30 FL	*- FL
163	1		*REAR DOOR CHANNEL WEATHERSTIP / FELT LH	Serviceable	139.70 FL	*- FL
164	1		*REAR DOOR INTERIOR LIGHT SWITCH LH	Serviceable	96.40 FL	*- FL
165	1		*REAR DOOR REGULATOR GEAR LH	Not Necessary	198.40 FL	*- FL
166	1		*REAR DOOR REGULATOR HANDLE LH	Serviceable	96.20 FL	*- FL
167	1		*REAR BUMPER	Repair	487.80 FL	*- FL
168	1		*REAR BUMPER STAY LH	Serviceable	20.00 FL	*- FL
169	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	57.30 FL	*- FL
170	1		*REAR BUMPER SIDE SUPPORT LH	Serviceable	87.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
171	1		*REAR BUUMPER REFLECTORS LH	Serviceable	55.00 FL	*- FL
172	1		*REAR BUMPER SIDE SUPPORT RH	Serviceable	87.30 FL	*- FL
173	1		*REAR BUMPER REFLECTORS RH	Serviceable	55.00 FL	*- FL
174	1		*REAR END PANEL INNER	Repair	280.70 FL	*- FL
175	1		*REAR END PANEL OUTER	Repair	519.80 FL	*- FL
176	1		*REAR END PANEL INNER TRIM	Serviceable	219.87 FL	*- FL
177	1		*REAR LUGGAGE FLOOR PANEL	Repair	791.70 FL	*- FL
178	1		*REAR LUGGAGE FLOOR PANEL TRIM BOARD	Serviceable	311.90 FL	*- FL
179	1		*REAR LUGGAGE FLOOR PANEL INSULATOR	Not Necessary	481.40 FL	*- FL
180	1		*TAILGATE LID	Repair	1,233.70 FL	*- FL
181	1		*TAILGATE LID CENTRE TOYOTA LOGO BADGE	Necessary	68.00 FL	*68.00 FL
182	1		*TAILGATE LID WEATHERSTRIP	Serviceable	286.90 FL	*- FL
183	1		*TAILGATE LID LOCK - TOP	Repair	388.80 FL	*- FL
184	1		*TAILGATE LID LOCK - BOTTOM	Repair	32.83 FL	*- FL
185	1		*TAILGATE LID OUTER CHROME GARNISH	Serviceable	214.50 FL	*- FL
186	1		*TAILGATE LID INNER HANDLE	Serviceable	17.47 FL	*- FL
187	1		*TAILGATE LID INNER TRIM BOARD	Serviceable	258.28 FL	*- FL
188	1		*TAILGATE HINGE RH	Repair	150.00 FL	*- FL
189	1		*TAILGATE HINGE LH	Repair	150.00 FL	*- FL
190	1		*TAILGATE LID INNER GARNISH TOP	Serviceable	204.60 FL	*- FL
191	1		*TAILGATE LID DAMPER STAY RH	Serviceable	224.70 FL	*- FL
192	1		*TAILGATE LID DAMPER STAY LH	Serviceable	224.70 FL	*- FL
193	1		*REAR SPOILER	Serviceable	986.10 FL	*- FL
194	1		*TAILGATE SCUFF PLATE	Serviceable	204.60 FL	*- FL
195	1		*REAR SPOILER THIRD BRAKE LIGHT	Serviceable	219.40 FL	*- FL
196	1		*REAR WINDSCREEN GLASS WITH HEATER	Shattered	988.70 FL	*988.70 FL
197	1		*REAR FENDER LH	Bent	1,013.60 FL	*1,013.60 FL
198	1		*REAR FENDER PANEL DECK TRIM SIDE LH	Serviceable	615.00 FL	*- FL
199	1		*REAR FENDER INNER WHEEL HOUSE PANEL LH	Repair	621.10 FL	*- FL
200	1		*REAR FENDER INNER BOTTOM TRIM LH	Serviceable	348.70 FL	*- FL
201	1		*REAR FENDER INNER COWLING LH	Serviceable	232.10 FL	*- FL
202	1		*REAR FENDER 1/4 GLASS WITH MOULDING LH	Shattered	429.80 FL	*429.80 FL
203	1		*REAR FENDER RH	Bent	1,013.60 FL	*1,013.60 FL
204	1		*REAR FENDER PANEL DECK TRIM SIDE RH	Serviceable	615.00 FL	*- FL
205	1		*REAR FENDER INNER WHEEL HOUSE PANEL RH	Repair	621.10 FL	*- FL
206	1		*REAR FENDER INNER BOTTOM TRIM RH	Serviceable	348.70 FL	*- FL
207	1		*REAR FENDER INNER COWLING RH	Serviceable	232.10 FL	*- FL
208	1		*PETROL TANK	Serviceable	961.70 FL	*- FL
209	1		*CNG BOARD COVER	Serviceable	120.00 FL	*- FL
210	1		*SPARE TYRE FASTENER BOLT	Repair	362.00 FL	*- FL
211	1		*TYRE MECHANICAL JACK	Repair	216.90 FL	*- FL
212	1		*TYRE MECHANICAL JACK HOLDER BRACKET	Repair	166.30 FL	*- FL
213	1		*REAR EXHAUST BOX	Repair	788.50 FL	*- FL
214	1		*REAR SHOCK ABSORBER RH	Not Necessary	311.40 FL	*- FL
215	1		*REAR AXLE ASSEMBLY WITH AXLE SHAFT	Not Necessary	2,911.70 FL	*- FL
216	1		*REAR AXLE HOUSING	No such part	1,991.70 FL	*- FL
217	1		*REAR LAMP LH	Cracked	496.43 FL	*496.43 FL
218	1		*REAR LAMP RH	Not Necessary	496.43 FL	*- FL
219	1		*REAR LAMP INNER PANEL LH	Repair	540.00 FL	*- FL
220	1		*REAR LAMP INNER PANEL RH	Repair	540.00 FL	*- FL
221	1		*REAR SEAT BELT RH	Serviceable	618.50 FL	*- FL
222	1		*REAR SEAT BELT TENSION RH	Serviceable	75.10 FL	*- FL
223	1		*REAR SEAT BELT LH	Serviceable	618.50 FL	*- FL
224	1		*FRONT SEAT BELT TENSION LH	Serviceable	75.10 FL	*- FL
225	1		*FRONT LICENCE PLATE	Bent	35.00 FS	*25.00 FS
226	1		*SET FRONT FENDER LINER CLIP LH	Not Necessary	12.00 FS	*- FS
227	1		*SET FRONT FENDER LINER CLIP RH	Necessary	12.00 FS	*12.00 FS
228	1		*FRONT TYRE RH (60%)	Punctured	180.00 FS	*108.00 FS
229	1		*FRONT TYRE RIM RH (LOCAL PURCHASE)	Bent	120.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
230	1		*FRONT TYRE RIM HUB CAP RH	Not Necessary	200.00 FS	*- FS
231	1		*FRONT TYRE LH	Not Necessary	180.00 FS	*- FS
232	1		*FRONT TYRE RIM LH	Not Necessary	120.00 FS	*- FS
233	1		*FRONT DOOR WEATHERSTRIP RH (50%)	Cut	157.80 FL	*78.90 FL
234	1		*FRONT DOOR WEATHERSTRIP LH (50%)	Cut	157.80 FL	*78.90 FL
235	1		*REAR DOOR WEATHERSTRIP RH (50%)	Cut	161.40 FL	*80.70 FL
236	1		*REAR DOOR WEATHERSTRIP LH (50%)	Cut	161.40 FL	*80.70 FL
237	1		*FRONT TYRE RIM HUB CAP LH	Not Necessary	200.00 FS	*- FS
238	1		*SET RADIATOR GRILLE CLIP	Not Necessary	18.00 FS	*- FS
239	1		*FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
240	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Necessary	60.00 FS	*30.00 FS
241	2		*FRONT ERP STICKER	Necessary	40.00 FS	*26.00 FS
242	1		*SET ENGINE SPLASH COVER CLIP RH	Not Necessary	12.00 FS	*- FS
243	1		*SET ENGINE SPLASH COVER CLIP LH	Not Necessary	12.00 FS	*- FS
244	1		*SET REAR BUMPER FASTENER CLIP	Not Necessary	30.00 FS	*- FS
245	1		*SET REAR END PANEL INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
246	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	300.00 FS	*- FS
247	1		*REAR EXHAUST MOUNTING	Serviceable	45.80 FS	*- FS
248	2		*CNG STICKER	Necessary 1pc Only	60.00 FS	*15.00 FS
249	1		*TAILGATE STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
250	1		*TAILGATE STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
251	1		*TAILGATE STICKER TRANS-LINK	Not Necessary	30.00 FS	*- FS
252	2		*REAR WINDSCREEN SEALANT	Necessary 1pc Only	80.00 FS	*40.00 FS
253	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	60.00 FS	*30.00 FS
254	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	24.00 FS	*- FS
255	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	24.00 FS	*- FS
256	1		*REAR FENDER 1/4 GLASS INNER SPONGE SEAL	Necessary	80.00 FS	*30.00 FS
257	2		*REAR FENDER 1/4 GLASS SEALANT	Necessary	120.00 FS	*40.00 FS
258	1		*REAR FENDER INNER COWLING CLIP LH	Not Necessary	36.00 FS	*- FS
259	1		*REAR FENDER INNER COWLING CLIP RH	Not Necessary	36.00 FS	*- FS
260	1		*REAR SPARE TYRE LH	Serviceable	180.00 FS	*- FS
261	1		*REAR SPARE TYRE RIM LH	Serviceable	150.00 FS	*- FS
262	1		*REAR TYRE RH	Serviceable	180.00 FS	*- FS
263	1		*REAR TYRE RIM RH	Serviceable	150.00 FS	*- FS
264	1		*HUB CUP RR RH	Not Necessary	70.00 FS	*- FS
265	1		*REAR TYRE LH	Serviceable	180.00 FS	*- FS
266	1		*REAR TYRE RIM LH (LOCAL PURCHASE)	Dented	150.00 FS	*50.00 FS
267	1		*HUB CUP RR LH	Not Necessary	70.00 FS	*- FS
268	1		*FRONT DOOR STICKER TRANS-CAB LH	Necessary	80.00 FS	*80.00 FS
269	1		*REAR DOOR STICKER 6555-3333 LH	Necessary	80.00 FS	*80.00 FS
270	1		*FRONT DOOR STICKER TRANS-CAB RH	Necessary	80.00 FS	*80.00 FS
271	1		*REAR DOOR STICKER 6555-3333 RH	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	121,277.26	23,135.77
- List Item Discount on L Items 25.00/25.00% (\$\$)	29,382.62	5,579.94
Total Parts (\$\$)	91,894.64	17,555.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	16,800.00	3,200.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED.	New	16,200.00	2,400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	220.00	180.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	120.00	40.00
5	TO RESEAL SEALANT ON GAP.	New	120.00	120.00
6	TOWING FEE.	New	120.00	120.00
7	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	170.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	80.00
9	TO TRANSFER OF TIRE, RIM AND WHEEL BALANCING.	New	170.00	40.00
10	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	0.00
11	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	0.00
12	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	120.00
13	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	160.00
14	TO CHECK ABS BREAK AFFICIENCY, FINAL CHECKING AND TESTING.	New	380.00	0.00
15	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	120.00
16	TO REMOVE AND REFIT REAR 1/4 GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	60.00
17	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
18	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	0.00
19	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	100.00
20	TO DROP CNG TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	440.00	0.00
21	TO RELEASE AND REFILL CNG GAS.	New	170.00	0.00
22	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
23	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENCHANCEMENT.	New	380.00	0.00
24	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
Gross Labour Cost (\$\$)			38,220.00	6,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >