

Your Ref: S9M0277K
Our Ref : CI/ASM19021204/D

02 December 2019

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(Motor Claims Department)

AUTOMOBILE INSPECTION REPORT OF INSURED VEHICLE SLH 6518A

1. I refer to your request dated 26 November 2019 to carry out an inspection of the insured vehicle SLH 6518A.
2. The objective of the inspection was to check whether the insured vehicle was fitted with any modification(s) and/or non-standard parts, and whether if fitted, the modification(s) and/or non-standard parts are LTA compliant; regardless of whether LTA compliant, the effects of the modification(s) and/or non-standard parts on the insured vehicle.
3. Following the request, I had physically inspected the insured vehicle on 27 November 2019 at the premises of M/s Avantage VAG, No. 48 Toh Guan Road East #05-155 Enterprise Hub, Singapore 608586. The paragraphs below set out my observations regarding the inspection.
4. The following general information of the insured vehicle was first recorded at the time of my inspection: -

Vehicle Registration No. : SLH 6518A
Make / Model : Volkswagen Golf R 2.0L 5DR
Chassis No : WVVZZZ1KZBW130168
Year of Registration : 2011 (January)
Mileage : 165,587km

5. The insured vehicle was observed to have sustained relatively moderate impact damage at its frontal portion. Without dismantling of any exterior body parts, I had observed damage to its front bumper, front grille, front left fender, front left headlamp, front bonnet, front support panel, aircon condenser, radiator and cooling fan amongst others. The rear portion and interior compartment were unaffected. See photo 1 – 4 below.