

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021213/BPA3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SJA3959R

Insured Vehicle No : GBG3097R

Date of Loss: 29/11/2019

Nature of Claim: TP

Claim No: 4351074862SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA3959R**

Make & Model: HONDA STREAM, 1.8 RSZ (A)

Engine No: R18A1744480

Reg. Date: 07/12/2007 (Man. Year: 2007)

Chassis No: RN61039440

Colour: Silver

Odometer: 283630 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Roadstone 7 mm

Rear Left Side:

Roadstone 7 mm

Front Right Side: Roadstone 7 mm

Rear Right Side:

Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,935.12	3,917.04	7,018.08	64.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	2,100.00	1,860.00	46.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,895.12	6,017.04	8,878.08	59.60
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	14,895.12	4,800.00	10,095.12	67.77
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,676.45		
Global Sum Settlement (S\$)		5,676.00		

INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,460.00 FL	*1,160.00 FL
2	1		*TAILGATE LOGO	Necessary	68.00 FL	*68.00 FL
3	1		*TAILGATE EMBLEM STREAM	Necessary	98.00 FL	*68.50 FL
4	1		*TAILGATE EMBLEM RSZ	Necessary	78.00 FL	*78.00 FL
5	1		*TAILGATE WEATHERSTRIP	Not Necessary	188.00 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Not Damaged	86.00 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Dislodged	187.00 FL	*187.00 FL
8	1		*REAR TAILLAMP RH	Broken	718.00 FL	*718.00 FL
9	1		*TAILLAMP LOWER BRACKET	No such part	68.00 FL	*- FL
10	1		*TAILLAMP BASE PANEL	Dented	318.00 FL	*145.90 FL
11	1		*REAR BUMPER ASSY	Dented	1,385.00 FL	*690.00 FL
12	2		*REAR BUMPER BRACKET	No such part	216.00 FL	*- FL
13	2		*REAR BUMPER RETAINER	Necessary	152.00 FL	*118.00 FL
14	1		*REAR FENDER	Dented	869.00 FL	*869.00 FL
15	1		*REAR FENDER INNER GARNISH	No such part	267.00 FL	*- FL
16	1		*REAR FENDER INNER SHIELD	Not Damaged	209.00 FL	*- FL
17	1		*REAR FENDER GLASS MOULDING	Necessary	134.00 FL	*68.20 FL
18	1		*REAR DOOR	Repair	1,163.00 FL	*- FL
19	1		*REAR DOOR TRIMBOARD	Not Damaged	860.90 FL	*- FL
20	1		*REAR DOOR WEATHERSTRIP	Not Damaged	164.50 FL	*- FL
21	1		*REAR DOOR BLACK TAPE	Necessary	81.30 FL	*37.70 FL
22	1		*REAR DOOR OUTER HANDLE	Not Damaged	134.90 FL	*- FL
23	1		*REAR DOOR INNER LOCK	Not Damaged	210.80 FL	*- FL
24	1		*REAR DOOR REGULATOR ASSY	Not Damaged	386.50 FL	*- FL
25	1		*REAR WHEEL BEARING RH	Dented	238.00 FL	*238.00 FL
26	1		*REAR EXHAUST ASSY	Not Damaged	865.40 FL	*- FL
27	1		*REAR EXHAUST MOUNTING	Not Damaged	68.90 FL	*- FL
28	1		*REAR EXHAUST MUFFLER TIP	Not Damaged	156.20 FL	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
30	1		*REAR FENDER INNER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*REAR FENDER GLASS INNER SEAL	Necessary	80.00 FS	*50.00 FS
33	1		*REAR FENDER GLASS SEALANT	Necessary	100.00 FS	*50.00 FS
34	1		*REAR DOOR TRIMBOARD CLIPS	Not Necessary	60.00 FS	*- FS
35	1		*TYRE	Not Damaged	350.00 FS	*- FS
36	1		*ALLOY RIM (LOCAL REPAIR)	Cut	850.00 FS	*200.00 FS
37	10		*REAR TAILLAMP CLIPS RH	Necessary	50.00 FS	*30.00 FS
38	4		*REAR BUMPER REVERSE SENSOR	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,101.40	4,806.30
- List Item Discount on L Items 20.00/20.00% (\$)	2,166.28	889.26
Total Parts (\$)	10,935.12	3,917.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,400.00	800.00
3	RUST PROOFING	New	100.00	60.00
4	CHECK WIRING	New	80.00	30.00
5	R&R TYRE ,PERFORM TYRE ROTATION AND BALANCING	New	120.00	60.00
6	WHEEL ALIGN	New	120.00	60.00
7	R&R DOOR COMPONENT	New	150.00	50.00
8	R&R UNDERCARRIAGE COMPONENT	New	150.00	80.00
9	R&R QUARTER GLASS	New	150.00	80.00
10	R&R TAILGATE COMPONENT	New	140.00	80.00
11	R&R EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,960.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >