

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021214/T1DS3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800016990

Claimant
Vehicle No : SJT7667G **Insured Vehicle No :** SLM1378T

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 3270290562SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT7667G	Engine No:	4A910126007
Make & Model:	MITSUBISHI LANCER, 1.3 (A)	Chassis No:	JMYSRCY2AAU000358
Reg. Date:	29/10/2009 (Man. Year: 2009)	Odometer:	193875 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/45 R12	Rear Tyre Size:	275/45 R12
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,459.12	3,195.61	6,263.51	66.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,540.00	1,230.00	44.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,229.12	4,735.61	7,493.51	61.28
Approved Total (Overridden) (\$\$)		3,750.00		
(\$\$)	12,229.12	3,750.00	8,479.12	69.34
+ GST 7.00/7.00% (\$\$)	856.04	262.50	593.54	69.34
Nett Amount (\$\$)	13,085.16	4,012.50	9,072.66	69.34
+ Car Rental (6.0 x \$S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		36.49		
Nett Liability (\$\$)		4,648.99		

INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At:

51 UBI AVE 1 #01-25
Repairer: Teamwork Garage Pte Ltd
(HQ)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	702.60 FL	*682.00 FL
2	1		*REAR BUMPER BEAM	Bent	114.00 FL	*114.00 FL
3	1		*REAR BUMPER TOW COVER	Missing	85.00 FL	*85.00 FL
4	1		*REAR BUMPER SIDE RETAINER	N/S Not Necessary /O/SDeformed	232.80 FL	*116.40 FL
5	1		*REAR BUMPER REFLECTOR	N/S Not Necessary / O/SCracked	207.00 FL	*103.50 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	270.00 FL	*270.00 FL
7	1		*REAR END PANEL	Bent	769.60 FL	*485.00 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	316.80 FL	*255.00 FL
9	2		*BOOTLID LAMP	Not Necessary	680.00 FL	*- FL
10	2		*BOOTLID HINGE	Repair	187.20 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Torn	186.00 FL	*186.00 FL
12	1		*BOOTLID LOCK	Bent	78.00 FL	*78.00 FL
13	1		*BOOTLID LOCK STRIKER	Repair	30.00 FL	*- FL
14	1		*BOOTLID INNER TRIM	Not Necessary	201.60 FL	*- FL
15	1		*REAR RH FENDER	Repair	939.60 FL	*- FL
16	1		*SPARE TYRE TOP BOARD	Not Necessary	512.60 FL	*- FL
17	1		*TAILLAMP	N/S Not Necessary / O/SCracked	1,164.00 FL	*548.00 FL
18	1		*BOOTLID (NPA)	Repair	0.00 FL	*- FL
19	1		*REAR NUMBER PLATE BASE }	Cracked	80.00 FS	*45.00 FS
20	1		*REAR NUMBER PLATE }	Cracked	80.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
22	1		*SET REAR REVERSE SENSOR	Not Working	600.00 FS	*200.00 FS
23	1		*REAR BUMPER LIP	N/S Not Necessary /O/SDeformed	500.00 FS	*250.00 FS
24	1		*BOOTLID (CARBON FIBRE)	Not Necessary	2,000.00 FS	*- FS
25	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,126.80	3,487.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	667.68	292.29
Total Parts (\$\$)	9,459.12	3,195.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	120.00	50.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	120.00	0.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	700.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	700.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			2,770.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >