



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1255Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	WINDSHIELD SPRAY NOZZLE @ \$48.00 (CONSISTENT)	DENTED	96.00	96.00
2	FRONT WIPER ARM @ \$165.00 (CONSISTENT)	N/S DENTED	330.00	165.00
1	FRONT WIPER ARM GARNISH (CONSISTENT)	BENT	360.00	360.00
1	FRONT LH SIDE MIRROR STAND WITH BUILT IN BOTH GLASS (CONSISTENT)	DENTED	450.00	450.00
1	FRONT LH SIDE MIRROR STAND MOTOR (CONSISTENT)	JAMMED	750.00	750.00
	LESS 20% DISCOUNT		-397.20	-
	LESS 25% DISCOUNT		-	-455.25
			1,588.80	1,365.75
	<u>LABOUR</u>			
	REMOVE AND REFIT WINDSHIELD SPRAY NOZZLER, FRONT WIPER ARM, FRONT WIPER ARM GARNISH, FRONT LH SIDE MIRROR STAND WITH BUILT IN BOTH GLASS, FRONT LH SIDE MIRROR STAND MOTOR. HEAT / WELD / BEATING / PULL / STRAIGHTEN / ALIGN FRONT CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.		500.00	200.00
	TUFF KOTE FRONT DAMAGED PORTION.		150.00	30.00
	PUTTY / PRIMER APPLICATION, SPRAY PAINTING ON FRONT WIPER ARM GARNISH.		250.00	200.00
			900.00	430.00
GRAND TOTAL			2,488.80	1,795.75

RECOMMENDED COST OF REPAIRS			1,795.75
------------------------------------	--	--	-----------------

Report Ref No. CC4/ASM19021217/Kps3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.