

ASS. REC. BY:

REF: CS/FCI/9021231/K4f3n2

Special Instructions:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Jason Tan che Kat of FCI Date/Time: 2.12.19 4.01p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 53605 Insured: SHC 8539A

at Workshop n/s Trans-cab Tel: 62876666

of M2 Ann Street 63

Policy No: Claim No: D19007535MPS4

Sum Insured: Excess:

Make of Veh: D.O.A. 26.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 2.12.19 4.05p.m. Person Contacted: Zhe Wei H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time Action/Instruction (✓) Estimate

SHC 53605 - CS / FCI 130037801 K4f3n2 D.O.A. 26/04/2018

SHC 8539A - CS / FCI 19016530 / 04f3 D.O.A. 12/07/2019

4/12-5:34pm- Revert via email.

Lump Sum \$12000 (Red: 28696.39; 95%)

ASS. REC. BY:

REF: P021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

RECEIVED 23 DEC 2019

Date/Time, File Pass to?

1) 23/12 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final Report

Report Format :

Lump Sum / I.B.I. (\$) 1200/-

TP

Days Of Repair: 2Resurvey No. of Trip: —

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Fees

Others

TOTAL

350

Veh No:

S/H C 53605

Yr Regn:

10.14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude cc 1995

Colour

M. White / Blue

A/C: Insured / Std / NI / NA

Sp. Reading

614272

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC.279599Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: All / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Sailun

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007335MFSH

Date: 4/12/2019

Our Ref: CS/FC119021231/Ktf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5360S

Please be informed that we had conducted the inspection of the abovementioned vehicle 2/12/2019 at the premises of M/s Trans-cab have the following to report: -

Workshop Estimate Amount	: S\$ 29,896.39
Revised Estimate Amount	: S\$ 1,621.24
"Check" Items Amount	: S\$ 493.02
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comment/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-11-2019	Our Ref No. D19007535MFSH
Accident Date	26-11-2019	Claim Type. Third Party
Insured Vehicle	SHC8539A	Third Party Vehicle. SHC5360S
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 4 December 2019 5:34 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Jason Tea'
Subject: RE: SURVEY ASSESSMENT - D19007535MFSH/1
Attachments: PRELI ADVISED OF SHC 5360SL.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 5360S
Number of days (estimated) : 2 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 2 December 2019 4:04 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007535MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignment@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 2 December, 2019 4:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007535MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 23 December 2019 11:24 AM
To: Denise Tay (LKKAUTO)
Subject: FW: SHC 5360S / TP / FIRST CAPITAL / DOA:26/11/2019 -- AAD1911-208
Attachments: SHC 5360S.pdf

Hi Denise

Amount confirmed \$ 1,200 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 23 December, 2019 9:02 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: SHC 5360S / TP / FIRST CAPITAL / DOA:26/11/2019 -- AAD1911-208

Dear Wai Yin,

Lump sum \$1200/-, 2 days

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 23 December 2019 8:40 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: FW: SHC 5360S / TP / FIRST CAPITAL / DOA:26/11/2019 -- AAD1911-208

Morning Denise

Can check Kenneth's recommended how much?

Thank You
Best Regards,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	B78K
Vehicle Details	
Vehicle No.:	SHC53605
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001716
Chassis No.:	VF1ABL15AUC279599
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Oct 2014
First Registration Date:	14 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$18,333.00
Total Rebate Amount:	\$27,081.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Nov 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5360S**AAD1911-208***Not Authored
C/Py B*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

02 DEC 2019

SHC 5360S

VF1ABL15AUC279599

RENAULT

LATITUDE

26.11.19

FCIL

14/10/2014

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH
28	1	BOOT HINGE LH

LIST

\$	<i>Bu/As</i>	561.70	✓
\$	<i>ml/ks</i>	411.90	✓
\$	<i>sh</i>	98.10	}
\$	<i>sh</i>	82.10	
\$	<i>sh</i>	59.80	
\$	<i>sh</i>	16.60	
\$	<i>sh</i>	80.80	
\$	<i>sh</i>	54.20	}
\$	<i>sh</i>	16.60	
\$	<i>su</i>	547.80	
\$	<i>sh</i>	114.50	}
\$	<i>sh</i>	100.90	
\$	<i>sh</i>	745.80	
\$	<i>sh</i>	404.56	
\$	<i>sh</i>	313.10	
\$	<i>sh</i>	401.40	
\$	<i>sh</i>	401.40	
\$	<i>sh</i>	401.40	
\$	<i>sh</i>	1,677.20	
\$	<i>sh</i>	344.70	
\$	<i>sh</i>	178.20	}
\$	<i>sh</i>	277.70	
\$	<i>sh</i>	277.70	
\$	<i>sh</i>	82.40	
\$	<i>sh</i>	95.80	
\$	<i>sh</i>	145.10	}
\$	<i>sh</i>	145.10	
\$	<i>sh</i>	254.20	X

Trans-cab Auto Services Pte Ltd

AAD1911-208

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5360S

29	1	BOOT HINGE RH	\$	253.80	}	X
30	2	BOOT RUBBER PLUG	\$	139.90		
31	2	BOOT BUFFER	\$	26.80		
32	1	BOOT LOCK LINKAGE	\$	20.60		
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50		
34	1	BOOT INNER TRIM BOARD	\$	611.00		
35	1	BOOT SWITCH	\$	113.00		
36	1	BOOT LOCK	\$	246.60		
37	1	BOOT LOCK CATCH	\$	41.70		
38	1	EXHAUST REAR	\$	5,263.60		
39	1	EXHAUST CAP REAR	\$	125.40		
TOTAL			\$	15,232.66		
10%			\$	1,523.27		
			\$	13,709.39		

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	80.00	
13	1	WINDSCREEN MOULDING	\$	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
15	1	BOOT INNER TRIM CLIP	\$	45.00	
16	1SET	BOOT FINISHER CLIP	\$	24.20	
17	1	TAILLAMP CLIP LH	\$	5.00	
18	1	TAILLAMP CLIP RH	\$	5.00	
19	1	Rear Bumper Protector	\$	100.00	

Trans-cab Auto Services Pte Ltd**AAD1911-208**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHC 5360S

20	1	EXHAUST MOUNTING REAR	\$	<i>Ph</i>	16.00	X
21	1	EXHAUST BRACKET REAR	\$	<i>Ph</i>	24.80	X
TOTAL			\$		1,507.00	
TOTAL PARTS			\$		15,216.39	

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>10/</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>60/</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>200/</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>~</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>~</i>	220.00	X
To repair and realign rear exhaust pipe.	\$	<i>~</i>	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>~</i>	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-208**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5360SLabour charge to mount and dismount vehicle on jig
bench, to facilitate repair.\$ *~* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 6,000.00 *2201*To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.\$ *~* 170.00 *X***TOTAL** \$ **14,680.00****Over All Total** \$ **29,896.39****LUMP SUM (REPAIR DAY)**~~20 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To receive letter after spray coating
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification allowed
- Supplementary works must be acknowledged and
in subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19021231/Ktf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-12-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8539A	Veh. Inspected	SHC 5360S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007535MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	02/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279599	Colour	METALLIC WHITE / RED	
Odometer	614272	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	7 mm	
L/H Front Tyre	215/60 R16	SAILUN	7 mm	
R/H Rear Tyre	215/60 R16	SAILUN	7 mm	
L/H Rear Tyre	215/60 R16	SAILUN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2019	Inspection Date	02/12/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5360S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED / DENTED	561.70	561.70
1	BUMPER LOWER REAR	DENTED / CUT	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	SERVICEABLE	547.80	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	82.40	-
1	BOOT BADGE	NOT NECESSARY	95.80	-
1	BOOT STRUT LH	SERVICEABLE	145.10	-

Report Ref No. CS/FCI19021231/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT RH	SERVICEABLE	145.10	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
2	BOOT RUBBER PLUG	SERVICEABLE	139.90	-
2	BOOT BUFFER	SERVICEABLE	26.80	-
1	BOOT LOCK LINKAGE	SERVICEABLE	20.60	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	99.50	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	41.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	5,263.60	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	125.40	-
	LESS 10% DISCOUNT		-1,523.27	-97.36
			13,709.39	876.24
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/FCI19021231/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	16.00	-
1	EXHAUST BRACKET REAR (SN)	SERVICEABLE	24.80	-
			1,507.00	165.00
	LABOUR			
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, EXHAUST REAR AND EXHAUST CAP REAR.		6,000.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI19021231/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
			14,680.00	490.00
	GRAND TOTAL		29,896.39	1,531.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI19021231/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.