

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021253/GKA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800006187

Claimant
Vehicle No : SH9635S **Insured Vehicle No :** SJC3960A

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 4959734387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9635S		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU111381
Reg. Date:	18/10/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU114785
Colour:	Blue	Odometer:	150029 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	815.84	690.96	124.88	15.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	740.00	490.00	39.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,045.84	1,430.96	614.88	30.06
+ GST 7.00/7.00% (\$\$)	143.21	100.17	43.04	30.05
Nett Amount (\$\$)	2,189.05	1,531.13	657.92	30.06
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (\$\$)		625.95		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		2,414.57		
Global Sum Settlement (\$\$)		2,300.00		

INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 03/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (RH)	Buckled	490.70 FL	*490.70 FL
2	1		*FRONT FENDER SHIELD (RH)	Not Necessary	114.70 FL	*- FL
3	1		*FRONT FENDER RETAINER	Not Necessary	41.40 FL	*- FL
4	1		*EMBLEM -BLUE DRIVE (RH)	Necessary	26.60 FL	*26.60 FL
5	1		*FRONT WHEEL HUB CAP (RH)	Scratched	346.40 FL	*346.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,019.80	863.70
- List Item Discount on L Items 20.00/20.00% (\$)	203.96	172.74
Total Parts (\$)	815.84	690.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	560.00	320.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	TUFF KOTE	New	50.00	20.00
4	FRT WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			1,230.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >