



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2003634
INV Date 04/05/2020
Reference CC4/EQI19021265/Upa3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SLF 1634R
Insured Veh. SJQ 4764U
Claim No. DM19HO03145
Policy No. DMPPHQ19-003306
Accident Date 27/11/2019
Inspection Date 02/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ119021265/Upa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 04-05-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJQ 4764U	Veh. Inspected	SLF 1634R
Policy No.	DMPPHQ19-003306	Coverage (\$)	0.00
Claim No.	DM19HO03145	Excess (\$)	0.00
Assign From	JAIME	Assign Date	29/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMGK5850HX200333	Colour	WHITE
Odometer	46865	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50Z R16	NEUTON	7 mm
L/H Front Tyre	205/50Z R16	NEUTON	7 mm
R/H Rear Tyre	205/50Z R16	NEUTON	7 mm
L/H Rear Tyre	205/50Z R16	NEUTON	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/11/2019	Inspection Date	02/12/2019
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 1634R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP -R/H	CRACKED	933.80	755.20
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	65.20	-
1	FRONT GRILLE	NOT NECESSARY	267.50	-
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	188.30	-
1	FRONT GRILLE LOGO	NOT NECESSARY	85.40	-
1	FRONT GRILLE OUTER GARNISH	NOT NECESSARY	117.30	-
1	FRONT BUMPER	DEFORMED / CUT	660.90	594.70
1	SET FRONT BUMPER CLIP	NECESSARY	50.00	35.00
1	FRONT BUMPER FOG LAMP	CRACKED	155.80	155.80
1	FRONT BUMPER FOG LAMP COVER	SCRATCHED	96.00	84.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	250.80	-
2	FRONT BUMPER SIDE RETAINER	O/S BENT	131.20	25.20
1	FRONT FENDER -R/H	TO REPAIR SEE LABOUR	571.50	-
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	121.60	-
1	FRONT WHEEL HUB	NOT NECESSARY	195.50	-
1	FRONT WHEEL BEARING	NOT NECESSARY	145.00	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	380.50	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	385.00	-
1	FRONT KNUCKLE ARM BEARING	NOT NECESSARY	135.00	-
1	FRONT LOWER ARM	NOT NECESSARY	346.50	-
1	FRONT TIE ROD	NOT NECESSARY	125.00	-
	LESS 20% DISCOUNT		-1,081.56	-330.02
			4,326.24	1,320.08
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER LOWER SPOILER (SN)	TO REPAIR SEE LABOUR	650.00	-
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	50.00	-
1	FRONT TYRE (SN)	SERVICEABLE	350.00	-
1	FRONT SPORT RIM (SN)	DENTED	800.00	400.00
			1,850.00	400.00

Report Ref No. CC4/EQ119021265/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	100.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER -R/H AND FRONT BUMPER LOWER SPOILER .		1,400.00	350.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,200.00	600.00
			3,280.00	1,030.00
	GRAND TOTAL		9,456.24	2,750.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00

Report Ref No. CC4/EQ119021265/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 1634R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 1634R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 1634R

RE-INSPECTION

