

ASS. REC. BY:

REF:

09/FCI/1902/288/T/9d3n2

Special Instruction:

Survey:

Taufik

ASSIGNMENT (Office)

From (Person):

Rachel Wu H mei

of

FCI

Date/Time:

9.18am 3/12/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBH 5886L

Insured:

SHC 1888M

at Workshop m/s

Kanz Work Solutions

Tel:

6844 2475

of

53 Ubi Ave 1# 01-24

Policy No:

Claim No:

D19007568MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/11/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:38am 3/12/19

Person Contacted:

Damen

Vehicle IN/OUT

Date/Time

Action/Instruction

Johny! ✓

FBH 5886L - NA / INC 19021014 / 24

DOA: 26/11/2019

SHC 1888M - NA / INC 19021014 / 24

DOA: 26/11/2019

04/12/19 @ 1.31pm revised to Rachel Wu by email.

24/12/19 @ 10.22am confirmed with Darren LS \$3400, 5 days.

Cost \$5975.50, 64%

Tanph

REF: FCI

ASSIGNMENT

From: _____ Date: 31/12/19
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBH 5886 L
at Workshop m/s: Karz WONGZ
of 53 Ubi Avenue L#0 -24
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 44800
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS up
Date: _____ Person Contacted: Daren
Vehicle: IN / OUT

Veh No: FBH 5886 L Yr Regn: 2013 July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha FZ16 c.c 153
Colour: Blue A/C: Insured / Std / NI / NA
Sp Reading: - T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ME1210661229 3258
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 120 / 70 R17
R: 140 / 70 R17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Metzeler
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. mm L/Bal. mm
D.O.A. D.O.I. 03/12/14 01240
Survey held at Karz Wongz
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Battery weak
	Repair limit 44000
	Tanfikh,
	PLS check parts prices.
	RECEIVED 24 DEC 2019
	4/12

Date/Time, File Pass to? ☐ : Preli. Report
1) 24/12 1919 ☐ : Final Report
Date/Time, File Return to?
3)
Report Format: TP
Lump Sum / TP: 3400
Days Of Repair: 5
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)
Survey Fee: 170
Transportation: 50
S + RS: 50
Photos: 121
TOTAL: 391



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007568MFSH

Date: 04 December 2019

Our Ref: CS/FCI19021288/T1qd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBH 5886L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/12/2019 at the premises of M/s KARZ WORK SOLUTIONS. and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 9,375.50</u> .
Revised Estimate Amount	: <u>S\$ 4,502.00</u> .
"Check" Items Amount	: <u>S\$ 900.00</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the front portion, o/s & n/s body.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-11-2019	Our Ref No. D19007568MFSH
Accident Date	26-11-2019	Claim Type. Third Party
Insured Vehicle	SHC1888M	Third Party Vehicle. FBH5886L
Survey Location	53 UBI AVENUE 1 #02-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	SHU SHAN	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KARZ WORK SOLUTIONS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	RACHELWU LIMEI	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Darren <karzworks.sg@gmail.com>
Sent: Tuesday, 24 December 2019 10:22 AM
To: Shiau Chan (LKKAUTO); Taufikh (LKKAUTO)
Subject: RE: FBH5886L YAMAHA FZ16

Hi Shiau Chan,

We confirm COR @ \$3400 and DOR @ 5 Days

Darren
Karz Works Pte Ltd
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 18 December 2019 4:08 PM
To: Darren; Taufikh (LKKAUTO)
Subject: RE: FBH5886L YAMAHA FZ16

Dear Darren,

As your requested.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren <karzworks.sg@gmail.com>
Sent: Wednesday, 18 December 2019 11:51 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: FBH5886L YAMAHA FZ16

Hi Shiau Chan,

Can I have the marked estimate for reference.

Darren
Karz Works Pte Ltd
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

Shiau Chan (LKKAUTO)

From: Darren <karzworks.sg@gmail.com>
Sent: Thursday, 12 December 2019 3:41 PM
To: Taufikh (LKKAUTO)
Subject: FBH5886L YAMAHA FZ16
Attachments: 37e743cf-0d85-4462-ab1e-068282fb0081.jpg; 80e3208d-18dc-46be-8db8-d973cac17b9f.jpg; 05590f34-2b53-4f69-882b-51c04c7e6ece.jpg; 9161de4e-581c-4032-98fd-fc1940bcee3b.jpg; a522bce5-15bd-4c38-b0a6-87e5e08ff83a.jpg; c917ae2d-b03a-4448-8fb0-487854b880f5.jpg

Hi Taufikh,

FYNA

Based on estimate calculation:

COR @ \$4000 (REPAIR LIMIT AS AGREED)
DOR @ 5 Days

Kindly revise and get back to us so that we can close the case asap.

Darren
Karz Works Pte Ltd
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 December 2019 1:31 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Rachel Wu'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007568MFSH/1
Attachments: CSFCI19021288T1qd3.pdf

Dear Rachel,

Enclosed herewith preliminary advice of FBH 5886L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 3 December 2019 11:53 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Rachel Wu' <RachelWu@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007568MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 December 2019 9:18 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Rachel Wu <RachelWu@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007568MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 792B

Vehicle Details

Vehicle No.: FBH5886L

Vehicle to be Exported: No

Intended Deregistration
Date: 04 Dec 2019

Vehicle Make: YAMAHA

Vehicle Model: FZ 16

Primary Colour: Blue

Manufacturing Year: 2013

Engine No.: 21CG013042

Chassis No.: ME121C0G6D2013258

Maximum Power
Output: -

Open Market Value: \$2,274.00

Original Registration
Date: 30 Jul 2013

First Registration Date: 30 Jul 2013

Transfer Count: 7

Actual ARF Paid: \$342.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Jul 2023

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,712.00

COE Rebate Amount: \$624.00

Total Rebate Amount: \$624.00

The information contained herein is correct as at 04 Dec 2019

OK

REPAIR PERFORMA INVOICE

FIRST CAPITAL INSURANCE

Vehicle number	FBH5886L
Make / Model	YAMAHA FZ16
Chassis number	ME121C0G6D2013258
Accident date	26.11.19
Reference	KK1911-37

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS	
1	IU UNIT
1 SET	WING MIRROR
1	CLUTCH LEVER
1	HANDLE BAR
1	FRONT HEADLAMP
1	FRONT LH SIGNAL LAMP
1	FRONT RH SIGNAL LAMP
1 SET	FRONT FORK
1	FRONT FENDER
1	BODY PANEL LH
1	BODY PANEL RH
1	TANK COVER
1	CLTUCH PADEL
1	BRAKE LEVER
2	EXHAUST COVER
1	SEAT
1	TAIL FAIRING LH
1	TAIL FAIRING RH
1	REAR SIGNAL LH
1	REAR SIGNAL RH
1	KICK STARTER
1 SET	FRONT FOOT REST
1 SET	PILLION FOOT REST
	6445.00
	Less 10%
	Subtotal
	Balance C/F
PARTS REPLACEMENT - SPECIAL NETT ITEMS	
	Balance B/F
1	BRAKE LEVER (AFTER MARKET)
1	GEAR SHIT SHAFT OIL SEAL
1	FORK OIL SEAL
1	FORK OIL
1	REAR CARPLATE
1	FRONT CARPLATE
1	RIM
1	TYRE
	Subtotal
	Balance C/F
LABOUR AND MISCELLANEOUS CHARGES	
	Balance B/F
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM
2	TO REMOVE/REFIT, REPLACE FRONT FORK
3	SPRAY PAINTING
4	REMOVE AND RESTICK STICKER
	Subtotal
	Grand total

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

[Signature]
4/12/19

Tanpin 97495749
NP
3/12/19 @ 1240
Lucy 54m
Rising after repair
05 days
sur @ lkkauto.com

9375.50

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

REPAIR PERFORMA INVOICE

FIRST CAPITAL INSURANCE

Vehicle number	FBH5886L
Make / Model	YAMAHA FZ16
Chassis number	ME121COG6D2013258
Accident date	26.11.19
Reference	KK1911-37

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	IU UNIT	170 310.00 cut ✓
1 SET	WING MIRROR	220.00 cut ✓
1	CLUTCH LEVER	120.00 bt ✓
1	HANDLE BAR	300 450.00 bt ✓
1	FRONT HEADLAMP	240 350.00 ? cut ✓
1	FRONT LH SIGNAL LAMP	180.00 x nn ✓
1	FRONT RH SIGNAL LAMP	180.00 cut ✓
1 SET	FRONT FORK	550.00 ? bt ✓
1	FRONT FENDER	70 250.00 cut ✓
1	BODY PANEL LH	700.00 x nn ✓
1	BODY PANEL RH	220 700.00 cut ✓
1	TANK COVER	90.00 R ✓
1	CLTUCH PADEL	150.00 bt ✓
1	BRAKE LEVER	120.00 id ✓
2	EXHAUST COVER	185.00 cut ✓
1	SEAT	400.00 x nn ✓
1	TAIL FAIRING LH	250.00 x nn ✓
1	TAIL FAIRING RH	250.00 cut ✓
1	REAR SIGNAL LH	180.00 x nn ✓
1	REAR SIGNAL RH	180.00 al ✓
1	KICK STARTER	200.00 x nn ✓
1 SET	FRONT FOOT REST	215.00 cut ✓
1 SET	PILLION FOOT REST	215.00 x nn ✓
		6445.00
	Less 10%	644.50 10%
	Subtotal	5800.50
	Balance C/F	5800.50
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	5800.50
1	BRAKE LEVER (AFTER MARKET)	150 350.00 cut ✓
1	GEAR SHIT SHAFT OIL SEAL	35.00 R ✓
1	FORK OIL SEAL	55.00 T ✓
1	FORK OIL	35.00 ? R ✓
1	REAR CARPLATE	60.00 x nn ✓
1	FRONT CARPLATE	60.00 20 bt ✓
1	RIM	350.00 200 dd ✓
1	TYRE	450.00 x nn ✓
	Subtotal	1045.00
	Balance C/F	1045.00
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	6845.50
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	600.00 250 ✓
2	TO REMOVE/REFIT, REPLACE FRONT FORK	380.00 100 ✓
3	SPRAY PAINTING	700.00 450 ✓
4	REMOVE AND RESTICK STICKER	500.00 100 ✓
	Subtotal	2180.00
	Grand total	9025.50

3170
2853

Removal of the
4/12.

495

Tan Kah 97495749
WP

3/12/19 @ 1240

Lumpsum

Removal after repair

900 - 05 days

sure/khant.com

4248
453400 * 05 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19021288/T1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-12-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1888M	Veh. Inspected	FBH 5886L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007568MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU LI MEI	Assign Date	03/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA FZ 16	c.c	153	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	ME121C0G6D2013258	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	METZELER	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	METZELER	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION,O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2019	Inspection Date	03/12/2019	
Survey held at	KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 5886L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	IU UNIT	CUT	310.00	170.00
1	SET WING MIRROR	CUT	220.00	220.00
1	CLUTCH LEVER	BENT	120.00	120.00
1	HANDLE BAR	BENT	450.00	300.00
1	FRONT HEADLAMP	CUT	350.00	240.00
1	FRONT LH SIGNAL LAMP	NOT NECESSARY	180.00	-
1	FRONT RH SIGNAL LAMP	CUT	180.00	180.00
1	SET FRONT FORK	BENT	550.00	550.00
1	FRONT FENDER	CUT	250.00	70.00
1	BODY PANEL LH	NOT NECESSARY	700.00	-
1	BODY PANEL RH	CUT	700.00	220.00
1	TANK COVER	TO REPAIR SEE LABOUR	90.00	-
1	CLUTCH PADEL	BENT	150.00	150.00
1	BRAKE LEVER	DENTED	120.00	120.00
2	EXHAUST COVER	CUT	185.00	185.00
1	SEAT	NOT NECESSARY	400.00	-
1	TAIL FAIRING LH	NOT NECESSARY	250.00	-
1	TAIL FAIRING RH	CUT	250.00	250.00
1	REAR SIGNAL LH	NOT NECESSARY	180.00	-
1	REAR SIGNAL RH	CUT	180.00	180.00
1	KICK STARTER	NOT NECESSARY	200.00	-
1	SET FRONT FOOT REST	CRACKED	215.00	215.00
1	SET PILLION FOOT REST	NOT NECESSARY	215.00	-
	LESS 10% DISCOUNT		-644.50	-317.00
			5,800.50	2,853.00
SPECIAL NETT ITEMS				
1	BRAKE LEVER (AFTER MARKET)(SN)	CUT	350.00	150.00
1	GEAR SHIT SHAFT OIL SEAL (SN)	NECESSARY	35.00	35.00
1	FORK OIL SEAL (SN)	NECESSARY	55.00	55.00
1	FORK OIL (SN)	NECESSARY	35.00	35.00

Report Ref No. CS/FCI19021288/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CARPLATE (SN)	NOT NECESSARY	60.00	-
1	FRONT CARPLATE (SN)	BENT	60.00	20.00
1	RIM (SN)	DENTED	350.00	200.00
1	TYRE (SN)	NOT NECESSARY	450.00	-
			1,395.00	495.00
	LABOUR			
	REPLACE,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM.INCLUSIVE OF THE REPAIR OF TANK COVER.		600.00	250.00
	TO REMOVE/REFIT,REPLACE FRONT FORK.		380.00	100.00
	SPRAY PAINTING.		700.00	450.00
	REMOVE AND RESTICK STICKER.		500.00	100.00
			2,180.00	900.00
GRAND TOTAL			9,375.50	4,248.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/FCI19021288/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.