

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021305/KPA3Q2

**Date:** 07/05/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800079079
<b>Claimant</b>		
<b>Vehicle No :</b> SMN3599S	<b>Insured Vehicle No :</b>	SBV9933J
Date of Loss: 01/12/2019	Nature of Claim: TP	Claim No: 8136576916SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3599S	Engine No:	L13B14101448
Make & Model:	HONDA JAZZ, 1.3 CVT (A)	Chassis No:	JHMGK3850KS217852
Reg. Date:	01/08/2019 (Man. Year: 2019)	Odometer:	6647 km
Colour:	Metallic Grey		
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,426.88	1,593.04	1,833.84	53.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,850.00	580.00	23.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,856.88</b>	<b>3,443.04</b>	<b>2,413.84</b>	<b>41.21</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	409.98	241.01	168.97	41.21
<b>Nett Amount (\$\$)</b>	<b>6,266.86</b>	<b>3,684.05</b>	<b>2,582.81</b>	<b>41.21</b>
<b>+ Loss of Use (5.0 x S\$120.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,286.05</b>		

### INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 03/12/2019 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)  
160 Sin Ming Drive #02-20, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Cracked	492.70 FL	*492.70 FL
2	1		*O/S REAR BUMPER SIDE RETAINER	Cracked	15.00 FL	*15.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
4	1		*REAR BUMPER LOWER GARNISH -CENTRE	Distorted	68.30 FL	*68.30 FL
5	1		*O/S REAR BUMPER LOWER SIDE GARNISH	Cracked	48.70 FL	*48.70 FL
6	1		*O/S REAR BUMPER INNER SHIELD	Torn	33.10 FL	*33.10 FL
7	1		*O/S TAILLAMP	Mtg Cracked	223.90 FL	*223.90 FL
8	1		*O/S TAILLAMP PANEL	Bent	75.30 FL	*75.30 FL
9	1		*O/S REAR FENDER	Buckled	559.30 FL	*559.30 FL
10	1		*O/S REAR FENDER LOWER INNER GRILLE	Cracked	26.00 FL	*26.00 FL
11	1		*REAR END PANEL	Bent	314.00 FL	*314.00 FL
12	1		*O/S REAR RIM	Serviceable	418.40 FL	*- FL
13	1		*O/S REAR SHOCK ABSORBER	Serviceable	212.90 FL	*- FL
14	1		*O/S REAR WHEEL BEARING	Not Necessary	287.50 FL	*- FL
15	1		*REAR AXLE	Serviceable	911.00 FL	*- FL
16	1		*REAR BUMPER L PLATE	Serviceable	80.00 FS	*- FS
17	1		*REAR BUMPER L PLATE BRACKET	Distorted	30.00 FS	*30.00 FS
18	1		*O/S REAR FENDER TOP GLASS SEALANT	Necessary	40.00 FS	*30.00 FS
19	1		*O/S REAR FENDER TOP GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
20	1		*O/S REAR TYRE	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,171.10</b>	<b>1,971.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	744.22	378.26
<b>Total Parts (\$\$)</b>	<b>3,426.88</b>	<b>1,593.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS	New	900.00	800.00
2	TO FOCUS TAILLAMPS ,TO CHECK REAR WIRING AND LIGHTING OPERATION	New	50.00	20.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
4	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS ,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	100.00
5	TO DISMANTLE AND CHECK REAR UNDERCARRIAGE .TO REPACE AFFECTED PORTIONS	New	240.00	0.00
6	TO CONDUCT REAR WHEEL ALIGNMENT TEST	New	100.00	60.00
7	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	900.00	750.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,430.00</b>	<b>1,850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >