

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021309/NKB3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419081

Claimant
Vehicle No : SHB8735E **Insured Vehicle No :** SKT8179E

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 1914697986SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8735E	Engine No:	D4FDDH308788
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414ME5452510
Reg. Date:	12/12/2013 (Man. Year: 2013)	Odometer:	420218 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,659.30	1,924.90	734.40	27.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	800.00	1,320.00	62.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,779.30	2,724.90	2,054.40	42.99
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	4,779.30	2,150.00	2,629.30	55.01
+ GST 7.00/7.00% (S\$)	334.55	150.50	184.05	55.01
Nett Amount (S\$)	5,113.85	2,300.50	2,813.35	55.01
+ Loss of Use (4.0 x S\$40.00/day) (S\$)		160.00		
+ Car Rental (4.0 x S\$96.96/day) (S\$)		387.84		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,850.34		
Global Sum Settlement (S\$)		2,850.00		

INSPECTION

Date of Assignment: 29/11/2019

Date Inspected: 29/11/2019 Inspected At:

Premier Automotive Services Pte Ltd
(HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*END PANEL INNER GARNISH	Serviceable	74.00 FL	*- FL
2	1		*BOOT LID LOCK	Serviceable	99.00 FL	*- FL
3	1		*END PANEL	Serviceable	250.00 FL	*- FL
4	1		*BOOTLID STRIKER	Serviceable	21.00 FL	*- FL
5	1		*BOOTLID EMBLEM	Necessary	27.00 FL	*27.00 FL
6	1		*BOOTLID CRDI	Necessary	29.00 FL	*29.00 FL
7	1		*BOOT LID RUBBER WEATHERSTRIP	Torn	96.00 FL	*96.00 FL
8	1		*REAR BUMPER	Cracked	696.00 FL	*696.00 FL
9	1		*REAR BUMPER LOWER COVER	Deformed	206.00 FL	*206.00 FL
10	1		*REAR BUMPER INNER SPONGE	Cracked	114.00 FL	*114.00 FL
11	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Bent	58.00 FL	*58.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Deformed	607.00 FL	*607.00 FL
13	2		*REAR BUMPER STAY O/S & N/S	Bent	108.00 FL	*108.00 FL
14	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Serviceable	36.00 FL	*- FL
15	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Serviceable	36.00 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	28.00 FS	*28.00 FS
17	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
18	1		*SET BOOTLID LOWER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
19	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*SET BOOTLID STICKERS	Necessary	30.00 FS	*30.00 FS
21	1		*REAR BUMPER TOP PROTECTOR	Necessary	80.00 FS	*80.00 FS
22	1		*REAR NO PLATE WITH CASING	Dented	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,905.00	2,119.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	245.70	194.10
Total Parts (\$\$)	2,659.30	1,924.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT/WELD ,CUT-OFF THE THE END PANEL FLOORBOARD PANEL,REAR O/S FENDER ,N/S & O/S TAILLAMP PANEL INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ETC	New	1,000.00	360.00
2	TO PUTTY AND SPRAY PAINTING ON BOOTLID ,BOOTLID LOWER GARNISH ,REAR BUMPER ,FLOORBOARD ,COMPARTMENT END PANEL	New	1,000.00	400.00
3	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	40.00
Gross Labour Cost (\$\$)			2,120.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >