

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021311/AEA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100441786

Claimant
Vehicle No : SLT3449Y **Insured Vehicle No :** SKC2282T

Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 3689421787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3449Y	Engine No:	G4FGHU687293
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU560999
Reg. Date:	26/10/2017 (Man. Year: 2017)	Odometer:	36706 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,790.32	4,591.20	3,199.12	41.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,130.00	1,970.00	48.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,890.32	6,721.20	5,169.12	43.47
Approved Total (Overridden) (\$\$)		5,300.00		
Nett Amount (\$\$)	11,890.32	5,300.00	6,590.32	55.43
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		5,667.49		

INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At:

Hua Meng Spray Painting Workshop
(HQ)
No 1 Kaki Bukit Avenue 6, #01-61
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,977.80 FL	*1,620.00 FL
2	2		*REAR BOOTLID HINGES	Not Necessary	207.40 FL	*- FL
3	1		*REAR BOOTLID UPPER LOCK	Damaged	139.30 FL	*139.30 FL
4	1		*REAR BOOTLID LOWER LOCK	Not Necessary	138.80 FL	*- FL
5	1		*REAR BOOTLID CABLE	Not Necessary	75.70 FL	*- FL
6	1		*REAR BOOTLID WEATHERSTRIP	Cut	101.80 FL	*101.80 FL
7	1		*REAR BOOTLID INSULATION	Not Necessary	161.50 FL	*- FL
8	2		*REAR BOOTLID REFLECTOR	Not Necessary	682.00 FL	*- FL
9	1		*REAR BOOTLID CENTRE EMBLEM	Necessary	52.80 FL	*52.80 FL
10	1		*REAR BOOTLID S EMBLEM	Necessary	22.00 FL	*22.00 FL
11	1		*REAR BOOTLID ELANTRA EMBLEM	Necessary	63.80 FL	*63.80 FL
12	2		*REAR LAMP	Cracked	862.40 FL	*862.40 FL
13	1		*REAR END PANEL	Dented	499.40 FL	*499.40 FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	76.80 FL	*76.80 FL
15	1		*REAR BUMPER	Distorted	505.80 FL	*505.80 FL
16	2		*REAR BUMPER SIDE HOLDER	Necessary	61.60 FL	*61.60 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	324.30 FL	*324.30 FL
18	2		*REAR BUMPER BRACKET	Not Necessary	121.80 FL	*- FL
19	4		*REAR BUMPER LOWER BRACKET	Damaged	66.00 FL	*66.00 FL
20	1		*REAR BUMPER LOWER LIP	Cracked	308.00 FL	*308.00 FL
21	2		*REAR BUMPER REFLECTOR	Cracked	127.60 FL	*127.60 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	66.00 FL	*30.00 FL
23	1		*REAR EXHAUST PIPE	Not Necessary	647.20 FL	*- FL
24	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	33.00 FL	*- FL
25	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	240.90 FL	*- FL
26	1		*REAR BOOTLID CENTRE LOCK SENSOR	Cracked	115.50 FL	*115.50 FL
27	1		*REAR END PANEL LOWER LH SIDE COVER	Deformed	54.50 FL	*54.50 FL
28	2		*REAR FENDER INNER GARNISH	Torn	457.40 FL	*457.40 FL
29	2		*REAR NUMBER PLATE LAMP	Not Necessary	71.80 FL	*- FL
30	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
31	1		*REAR CAMERA	Not Necessary	800.00 FS	*- FS
					Sub Total (\$\$)	9,442.90 5,689.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,652.58 1,097.80
					Total Parts (\$\$)	7,790.32 4,591.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
2	REMOVE & REINSTALL EXHAUST PIPE	New	200.00	0.00
3	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	50.00
4	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	60.00
5	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	900.00
6	RESPRAY PAINTING	New	1,400.00	1,000.00
7	TUFF KOTE	New	100.00	60.00
Gross Labour Cost (\$)			4,100.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >